GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/FH/SZ/2018 / 207

Dated: 7/2/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Farm House No. F-20 located at Pushpanjali, Dwarka Link Road New Delhi-110037 comprised of Basement, Ground & 1st floor with open farm house has already been issued FSC by this department vide letter No. F6/DFS/MS/2014/SZ/1379 dated 11/11/2014. The Farm House was re-inspected by the officer concerned of this department on 29/01/2018 in the presence of Ms. Geeta Luthra & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010and that the building is fit for occupancy Class D "Assembly Building Farm House" with effect -----7-12018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) **Chief Fire Officer** Ph:-011-23412235

Copy to:-

010) ± 1. The Executive Engineer (Bldg.), SDMC, .Nazafgarh Zone, Main Zonal Building, Dhansa Stand, Nazafgarh, New Delhi-110043

2. Sh. Mukesh Chaudhary, M/s Farm House No. F-20, Pushpanjali, Dwarka Link Road New Delhi-110037

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first form is available 2010. The of Delhi Fire Service Rules schedule http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1. Name & address of the building: M/s Farm House No.F-20, Pushpanjali, Dwarka Link Road New

Delhi-110037

2. Type of Occupancy : Assembly Building Group "D" (Farm House)

3. Type of Case : Renewal

4. Details of Previous NOC : F6/DFS/MS/2014/SZ/1379 dated 11/11/2014

5. Fire Safety directives letter No : F6/DFS/MS/2009/2218 dated 23/07/2009

6. Date of inspection. : 29/01/2018 7. Name of Inspecting Officer : A.K. Malik

8. Name and designation of officers

From the building side : Ms. Geeta Luthra

S.	Applicant's letter No. : Form "J", o Minimum Standards on fire prevention	outdoor diary no. 1647 Old NOC	Provided at site	Remarks			
No.	and fire safety U/R 33	Requirement		MR/NMR			
1.	Access to building						
	 Road width 	Required	25m	MR			
	Gate width	5m	Provided	MR			
	Width of internal road	-NA-	-NA-	-NA-			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases			7.57			
	Upper Floors	Required	3 Nos	MR			
	Basements	Required	2 Nos	MR			
	b. Width of staircases						
	 Upper Floor 	Required	2 x 0.8m & 0.9m	MR			
	 Basements 	Required	2 x 0.9m	MR			
	c. Protection of exits		L				
	Fire check door	-NA-	-NA-	-NA-			
	 Pressurization 	-NA-	-NA-	-NA-			
	d. No. of continuous staircases to terracee. Width of Corridorf. Door Size	One	Provided	MR			
		-NA-	-NA-	-NA-			
		-NA-	-NA-	-NA-			
3.	Compartmentation	117	1111	I VI X			
٥.		NIA	NIA	-NA-			
	• Fire check door	-NA- -NA-	-NA- -NA-	-NA-			
	• Sealing of electrical shafts	-NA-	-NA-	-NA-			
	Fire Rating of shaft doorWater Curtain	-NA-	-NA-	-NA-			
	Fire Dampers	-NA-	-NA-	-NA-			
4.	Smoke Management System	1111	1111	1111			
		-NA-	-NA-	-NA-			
	Basements						
	• Upper floors	-NA-	-NA-	-NA-			
5.	Fire Extinguishers	0 N	12 \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	MD			
	• Total numbers	8 Nos ABC/W.Co ₂ /Co ₂	12 No's	MR			
	TypesIS marking	ISI Marked	4/4/4 Nos Yes	MR MR			
6	First-Aid Hose Reels		1 68	IVIK			
6.	Total numbers on each side	1 Nos	Provided	MR			
	Length of hose reel hose	30m	Provided	MR			
	Nozzle diameter	5mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	• Type of detectors	-NA-	-NA-	-NA-			
	Location of Main Panel	-NA-	-NA-	-NA-			
	Location of Repeater Panel						
	Alternate source of power	-NA-	-NA-	-NA-			
	Hooters' Location	-NA-	-NA-	-NA-			
0	MOLEA	-NA-	-NA-	-NA-			
8.	MOEFA Public Address System	Required	Provided	MR			
9. 10.	Public Address System Automatic Sprinkler System	Required	Provided	MR			
10.	Automatic Sprinkier System	NT A	NTA.	T DIA			

14	M/s Farm House No.F-20, P	usnpanjali, Dwarka Link Roa	d New Delhi-110037	
11.	7			
	Size of riser/down-comer	-NA-	-NA-	-NA-
	Number of hydrants per floor Hose Box	-NA-	-NA-	-NA-
12.	Hose Box Yard Hydrants	-NA-	-NA-	-NA-
12.				
	Total number of hydrants	Required	3 Nos	MR
13.	Hose Box	Required	3 Nos	MR
13.	Pumping Arrangements • Ground Level			
	Discharge of main Pump	-NA-	-NA-	-NA-
	Head of Main pump	-NA-	-NA-	-NA-
	Number of main pumps	-NA-	-NA-	-NA-
	Jockey Pump out put	-NA- -NA-	-NA-	-NA-
	Jockey pump head	-NA-	-NA-	-NA-
	Standby Pump out put	-NA-	-NA-	-NA-
	Standby Pump Head	-NA-	-NA- -NA-	-NA-
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-
	Pump House Access	1 1/ 1	-1N/A-	-NA-
	• Terrace level			
	Discharge of pump	180 & 900 LPM	Provided	MR
	Head of the pumpPower Supply	40m (each)	Provided	MR
	Auto Starting of pump	Required	Provided	MR
	7 Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fighting	5.00		
	Underground tank capacity	-NA-	-NA-	-NA-
	Draw-off connection	-NA-	-NA-	-NA-
	Fire service inlet	-NA-	-NA-	
	Access to tank	-NA-	-NA-	-NA-
	 Overhead Tank capacity 	10,000 Ltr.	Provided	-NA-
15.	Exit Signage.	Required	Provided	MR MR
16.	Provision of Lifts.	5. ⁴ a.	Trovided	IVIIX
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	Pressurization of Lift lobby	-NA-	-NA-	
	Communication In lift Car	-NA-	-NA-	-NA-
	Fireman's Grounding Switch	-NA-	-NA-	
	Lift Signage			-NA-
17.	Standby navyas	-NA-	-NA-	-NA-
18.	Standby power supply	Required	Provided	MR
10.	Refuge Area. > Total Area	NT.4		
	Location	-NA-	-NA-	-NA-
19.	Fire Control Room	-NA-	-NA-	-NA-
	Detector System Panel	-NA-	NIA	N.T.A.
	• Flow Switch Panel		-NA-	-NA-
100	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the above substantial compliance of the minimum standards of fire

M/s Farm House No.F-20, Pushpanjali, Dwarka Link Road New Dethi-110037

Accordingly form "H" in shape of DFA is put up for approval.

Signature of Inspecting Officer

Name: A. K. Malik

Designation: Divisional Officer

DY. CFO(SZ)