GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2018/SZ/ 280

Dated: 23/2/18

FIRE SAFETY CERTIFICATE

Certified that **G.D. Goenka Public School** located at J-Block, Sarita Vihar, New Delhi-110076 comprised of **Basement, Stilt, Ground and three upper floors** was issued Fire Safety Certificate by this department vide letter No. F.6/MS/DFS/School/2015/SZ/128 Dated 27/01/2015. The school building was re-inspected by officer concerned of this department on 09/02/2018 in presence of Mr. Vipul Garg (Chairman) and found that the said School building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "**Educational**" Group-B (School) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23/2/18 at New Delhi by

(Vipin Kental) Chief Fire Officer

ale

Copy to: -

1. The Chairman, GD Goenka Public School, J-Block, Sarita Vihar, New Delhi-110076

2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept unlocked and free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any,
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT					
1	Name & Address of the Building					
1	Tvalle & Address of the Building	G.D. GOENKA PUNLIC SCHOOL, J-BLOCK, SARITA VIHAR, NEW DELHI-110076 Educational Building "Group-B"				
2	Type of Occupancy					
3	Building Comprised of	Basement, Stilt, Ground plus three upper floors.				
4	Type of Case	Renewal				
5	Details of Previous NOC	F.6/DFS/MS/School/2015/SZ/128 Dt. 27-01-2015				
6	Fire Safety Directives Letter No	F.6/DFS/MS/SC0001/2013/102 Dated 30-05-2013				
7	Date of Inspection	09-02-2018				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of	Sh. Vipul Garg (Chairman)				
	Officers from the building side	April Omb (Camillani)				
10	Year of construction	2014		Į.		
11	Applicant letter No.	GDGPS/SV/2017-18/447 Dated 08-01-2018				
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirement		MR/NMR		
1	Access to Building.		The state of the s			
	Road width	Required	6 mtr	MR		
	Gate width	Required	6.15m, 6.15m, 8m	MR		
	Width of internal road	Required	6 mtr			
		Required	o mur	MR		
2	Number, width, type & arrangement of exits	-				
	a) Number of Staircase		00.31	1 16		
	> Upper floors	Required	02 Nos	MR		
	Basement floor	Required	02 Nos	MR		
	b) Width of Staircase					
3	➤ Upper floors	2.0 mtr each	Provided	MR		
	➢ Basement floor	2.0 mtr each	Provided	MR		
	c) Protection of exits		·			
	> Fire check door	Required	Provided	MR		
	> Pressurization	N/A	N/A	N/A		
	d) No. of continuous staircase to terrace	Required	02 Nos	MR		
	e) Width of corridor	1.5m	Provided	MR		
	f) Door size (Exits in Auditorium)	1m x 2 Nos	Provided	MR		
3	Compartmentation.			-		
	Fire check door.	Required	Provided	MR		
7	Sealing of electrical shafts.	Required	Provided	MR		
	Fire rating of shaft door.	Required	Provided	MR		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.			_		
NO.	Basement	30 ACPH	Provided	MR		
	Upper floors	12 ACPH	Provided	MR		
5.	Fire Extinguishers.					
	Total numbers	Required	24 No's	MR		
	Types	CO2 / ABC	ABC-16, Co2-08	MR		
	ISI Marking	ISI marked	Provided	MR		
		151 markeu	riovided	IVIK		
6.	First Aid Hose Reels.		A 3.1	1.00		
-	Total numbers on each floor.		2 Nos	MR		
ESTREMENT OF THE PROPERTY OF T	 Length of hose-reel hose. 	Hose-reels*	30 m	MR		
1	Nozzle Diameter		5 mm	MR		

G.D. Goenka Public School, J-Block, Sarita Vihar, NEW Delhii-110076

7 Automatic fire detection & alarming system	8	· · · · · · · · · · · · · · · · · · ·	
Type of detectors	N/A	Smoke type	N/A
Location of Main Panel	N/A	Ground floor	N/A
Location of Repeater Panel	N/A	N/A	N/A
Alternate source of power	N/A	Provided	N/A
Hooter's location	N/A	Each floor	N/A
8. MOEFA / MCP's	Required	Provided	MR
9. Public Address System	N/A	N/A	N/A
0. Automatic Sprinkler System		1	· · · · · · · · · · · · · · · · · · ·
Basement	Required	Provided	MR
Upper floors / stilt floor	Required	Provided	MR
Sprinkler above false ceiling	N/A	N/A	N/A
11. Internal Hydrants.		*	
Size of Riser/Down-comer	Required	100 mm	MR
Number of Hydrant per floor	Required	2 Nos	MR
Hose box.	Required	2 Nos	MR
2. Yard Hydrants.		· ·	
Total number of hydrants.	N/A	2 Nos	N/A
Hose box.	N/A	2 Nos	N/A
		·	
13. Pumping arrangements. • Ground Level			
Discharge of main pump.	N/A	N/A	N/A
Head of main pump.	N/A	N/A	N/A
Number of main pumps.	N/A	N/A	N/A
> Jockey Pump output.	N/A	N/A	N/A
> Jockey Pump head.	N/A	N/A	N/A
Standby Pump output.	N/A	N/A	N/A
Standby pump head.	N/A	N/A	N/A
➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
Terrace Level	14/12		
Discharge of pump.	1620 LPM	1620 LPM	MR
> Head of pump.	40m	40m	MR
Power supply.	Required	Provided	MR
> Auto starting of pump.	Required	Provided	MR
14. Captive water storage for Fire Fighting.	110001100		
Underground tank capacity.	N/A	N/A	N/A
Draw-off connection.	N/A	N/A	N/A
Fire Service Inlet.	N/A	Provided	N/A
Access to tank.	N/A	N/A	N/A
Overhead tank capacity.	25,500 Ltr	Provided	MR
15. Exit Signage.	Required	Provided	MR
16. Provisions of Lifts.			
Pressurization of lift shaft.	Required	Provided	MR
Pressurization of lift lobby.	Required	Provided	MR
Communication in lift car.	Required	Provided	MR
• Fireman's switch.	Required	Provided	MR
Lift signage.	Required	Provided	MR
17 Standby Power Supply	Required	Provided	MR
17 Standby Fower Supply 18. Refuge Area	1. Addition		
Total area	N/A	N/A	N/A
U .		N/A	N/A
Location G.D. Goenka Public School, J-Block	N/A		N/A

19.	Fire Control Room.			
	Detector System Panel.	Required	Provided	MR
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	Required	Provided	MR
20.	Special Fire Protection System for the	Required	ABC type fire extinguisher	MR
	Protection of special Risk, if any.		provided near elect. panel	

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2015/SZ/128 Dated 27-01-2015, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

R.N. Singh Name: Designation: ADO (BCP)

G.D. Goenka Public School, J-Block, Sarita Vihar, NEW Delhii-110076

DO (SE

1614/Clos2

FT10),

MSTZ

Just up for signfol. Rung

14/2 PJ leffer is CPO/S/2