

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE**  
**NEW DELHI- 110001**

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/EH/2018/SZ/ 281

Dated: 23/2/18

**FIRE SAFETY CERTIFICATE**

Certified that the **Taco Bell Restaurant** (A Unit of Burman Hospitality Pvt. Limited) located at Space-8 (T-316A), 3<sup>rd</sup> Floor, Ambience Mall, Vasant Kunj, New Delhi-110070, comprised of **03 Basements, Ground + three upper floors**. The restaurant running at 3<sup>rd</sup> floor was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/EH/2015/SZ/861 dated 28/05/2015. The restaurant premise was re-inspected by the officer concerned of this department on 01-02-2018 in presence of Mr. Avneesh (Manager) and found that the restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Assembly**" **Group-D** (Restaurant) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 23/2/18 at New Delhi by

  
(Vipin Kental)  
Chief Fire Officer

Copy to: -

1. The DHO, SDMC, Public Health Deptt., South Zone, Green Park, New Delhi-110016
2. M/s Taco Bell Restt, Space-8 (T-316A), 3<sup>rd</sup> floor, Ambience Mall, Vasant Kunj, ND-70

**Conditions for the validity of Fire Safety Certificate**

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT				
1	Name & Address of the Building	TACO BELL (Restt), Space-8 (T-316A), 3 <sup>rd</sup> floor, Ambience Mall, Vasant Kunj, New Delhi-110070 (A Unit of Burman Hospitality Pvt. Ltd)		
2	Type of Occupancy	Assembly "Group-D" (Restaurant)		
3	Building Comprised of	Three Tier basement, Ground + 03 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2015/SZ/861 Dated 28/05/2015		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	01-02-2018		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Avneesh (Manager)		
10	Year of construction	2010   Restt running at 3 <sup>rd</sup> floor of the building		
11	Applicant letter No.	Nil dated Nil, ODD No. 541 dated 11/01/2018		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR
1	<b>Access to Building.</b>	F.6/DFS/MS/Mall/SZ/2017/33 dated 09/01/2017		
	• Road width	Restt within Amb. Mall	As above	MR
	• Gate width		As above	N/A
	• Width of internal road		As above	N/A
2	<b>Number, width, type &amp; arrangement of exits</b>	Provided & Maintained by Ambience Mall		
	<b>a. Number of Staircase</b>	Required	Two near restaurant	MR
	• Upper floors	N/A	N/A	N/A
	• Basement floor	N/A	N/A	N/A
	<b>b. Width of Staircase</b>	Provided & Maintained by Ambience Mall		
	• Upper floors	Required	As above	MR
	• Basement floor	N/A	As above	N/A
	<b>c. Protection of exits</b>	Provided & Maintained by Ambience Mall		
	• Fire check door	Required	As above	MR
	• Pressurization	Required	As above	MR
	<b>d. No. of continuous staircase to terrace</b>	Required	As above	MR
	<b>e. Width of corridor</b>	N/A	N/A	N/A
	<b>f. Door size</b>	2.0 m	Open from all side	MR
3	<b>Compartmentation.</b>	Provided & Maintained by Ambience Mall		
	• Fire check door.	Required	As above	MR
	• Sealing of electrical shafts.	Required	As above	MR
	• Fire rating of shaft door.	N/A	As above	N/A
	• Water curtain	N/A	As above	N/A
	• Fire dampers.	N/A	As above	N/A
4.	<b>Smoke Management system.</b>	Provided & Maintained by Ambience Mall		
	• Basement	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	Exhaust fans provided	MR
5.	<b>Fire Extinguishers.</b>	Provided & Maintained by Ambience Mall		
	• Total numbers		05 No's	MR
	• Types	ISI marked	ABC-03, Co2-02	MR
	• ISI Marking		Provided	MR
6.	<b>First Aid Hose Reels.</b>	Provided & Maintained by Ambience Mall		
	• Total numbers on each floor.		As above	MR
	• Length of hose-reel hose.	Hose-reels	As above	MR
	• Nozzle Diameter		As above	MR

M/s Taco Bell Restt, Space-8 (T-316A), 3<sup>rd</sup> floor, Ambience Mall, Vasant Kunj, New Delhi

7	<b>Automatic fire detection &amp; alarming system</b>	Provided & Maintained by Ambience Mall		
	• Type of detectors	Required	As above	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	Required	As above	MR
	• Alternate source of power	Required	As above	MR
	• Hooter's location	Required	As above	MR
8.	<b>MOEFA</b>	Required	Provided	MR
9.	<b>Public Address System</b>	Required	Provided	MR
10.	<b>Automatic Sprinkler System</b>	Provided & Maintained by Ambience Mall		
	• Basement	N/A	As above	N/A
	• Upper floors	Required	As above	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	<b>Internal Hydrants.</b>	Provided & Maintained by Ambience Mall		
	• Size of Riser/Down-comer	Required	As above	MR
	• Number of Hydrant per floor	Required	As above	MR
	• Hose box.	Required	As above	MR
12.	<b>Yard Hydrants.</b>	Provided & Maintained by Ambience Mall		
	• Total number of hydrants.	N/A	As above	N/A
	• Hose box.	N/A	As above	N/A
13.	<b>Pumping arrangements.</b>	Provided & Maintained by Ambience Mall		
	• <b>Ground Level</b>	Provided & Maintained by Ambience Mall		
	➤ Discharge of main pump.	N/A	4500 LPM	N/A
	➤ Head of main pump.	N/A	70m	N/A
	➤ Number of main pumps.	N/A	2 Nos	N/A
	➤ Jockey Pump output.	N/A	180 LPM	N/A
	➤ Jockey Pump head.	N/A	70m	N/A
	➤ Standby Pump output.	N/A	4500 LPM	N/A
	➤ Standby Pump head.	N/A	70m	N/A
	➤ Auto Starting/Manual Stopping.	N/A	Provided	N/A
	➤ Access to pump house	N/A	Provided	N/A
	• <b>Terrace Level</b>	Provided & Maintained by Ambience Mall		
	➤ Discharge of pump.	N/A	As above	N/A
	➤ Head of pump.	N/A	As above	N/A
	➤ Power supply.	N/A	As above	N/A
	➤ Auto starting of pump.	N/A	As above	N/A
14.	<b>Captive water storage for Fire Fighting.</b>	Provided & Maintained by Ambience Mall		
	• Underground tank capacity.	500 KL	As above	MR
	➤ Draw-off connection.	Required	As above	MR
	➤ Fire Service Inlet.	Required	As above	MR
	➤ Access to tank.	Required	As above	MR
	• Overhead tank capacity.	10,000 Ltr	30,000 Ltr	MR
15.	<b>Exit Signage.</b>	Required	Provided	MR
16.	<b>Provision of Lifts.</b>	Provided & Maintained by Ambience Mall		
	• Pressurization of lift shaft.	N/A	As above	N/A
	• Pressurization of lift lobby.	N/A	As above	N/A
	• Communication in lift car.	N/A	As above	N/A
	• Fireman's switch.	N/A	As above	N/A
	• Lift signage.	N/A	As above	N/A
17	<b>Standby Power Supply</b>	Required	Provided (DG Set)	MR
18.	<b>Refuge Area</b>			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A


M/s Taco Bell Restt, Space-8 (T-316A), 3<sup>rd</sup> floor, Ambience Mall, Vasant Kunj, New Delhi

19.	Fire Control Room.	Provided & Maintained by Ambience Mall		
		<ul style="list-style-type: none"> <li>• Detector System Panel.</li> <li>• Flow Switch Panel.</li> <li>• PA system Panel.</li> <li>• Battery backup</li> <li>• Building floor plan</li> </ul>	N/A	As above
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
		N/A	As above	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	As above	N/A

The Fire protection systems provided in the building were checked / operated and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2015/SZ/861 Dated 28/05/2015, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.


  
 Signature of the Inspecting Officer  
 Name : R.N. Singh  
 Designation: ADO (BCP)

M/s Taco Bell Restt, Space-8 (T-316A), 3<sup>rd</sup> floor, Ambience Mall, Vasant Kunj, New Delhi

DO (SD)

  
12/2/18

  
12/2/18

  
12/2



CFO (ST)

M. S. Cell

FTM


12/3/2

FT letter is sent up for signature

CFO/ST

M. S. Cell

12/2

  
12/2