GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2018/ School/w2/359

Dated: (/3/2018

FIRE SAFETY CERTIFICATE

Certified that the Rajdhani Public School located at Kureni Road, Narela, Delhi-110040 comprised of ground and 02 upper floors owned/ occupied by Rajdhani Public School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of fire service on 19.02.2018 in the presence of Sh. Abbas Ali, Manager and that the building/ premise is fit for occupancy class B Educational with effect from 6/3/18 for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working
- 2. Loss of life or property due to non functional fire safety measure shall be at the
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned
- 5. This certificate cannot be treated in any case for regularizations of unauthorized
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Chief Fire Officer Ph:-011-23414250

Copy to: -

- py to :
 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 54.
- 2. The Principal, Rajdhani Public School, Kureni Road, Narela, Delhi-110040.

INSPECTION REPORT Name & address of the building : Rajdhani Public School, Kureni Road, Narela, Delhi-110040. 2 Type of Occupancy :Educational 3 Type of Case :New Case (G+02floorss) Details of previous NOC :Nil Fire Safety directives letter No : NBC Part 4. Date of inspection : 19.02.2018 Name of the Inspecting Officers : ADO (RN) Name and designation of officers from the building side : Mr. Abbas Ali (Manager) 9. Year of Construction : 1995 10. Applicant's letter No. : RPS/722/17 Dated: 23.01.2018 Plot Area-. 1150 yards Covered Area:900 yards class rooms -30 nos, students---590 nos Minimum Standards on fire prevention and NBC Provided at site Remarks fire safety U/R 33 Requirement MR/NMR 1 Access to building Road width 6m 06m MR Gate width Directly Directly accessible MR Accessible Width of internal road NA NA NA 2 Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 03 MR NA NA NA Basements b. Width of staircases 1.50m 1.10 m, 75 cm MR(old case) Upper Floors 1.20m (iron staircase) Basements NA NA NA c. Protection of exits

NA

NA

01

NA

1 m

NA

NA

NA

NA

02

NA

1 m

NA

NA

NA

NA

MR

NA

MR

NA

NA

Fire check door

Pressurization

Fire check door

e. Width of Corridor

Compartmentation.

f. Door Size

3

d. No. of continuous staircases to terrace

Sealing of electrical shafts

	Fire Rating of shaft door	27.1					
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.	NA	NA	NA			
	Basements	30 a/c per hour	Exhaust Fan	MR			
	• Upper floors	12 a/c per hour	Natural Ventilated	MR			
5	Fire Extinguishers						
	Total numbers	05 nos	06 nos	MR			
	• Types	ABC/CO2	ABC—06	MR			
	ISI marking	ISI Marked	Yes	MR			
6	First-Aid Hose Reels.						
	Total numbers on each floor	01	02	MR			
	Length of hose reel hose	30m	30m	MR			
	Nozzle diameter	5mm	5mm	MR			
7	Automatic fire detection and alarming syst	em.		IVIIX			
	Type of detectors	NA	NA	NA			
	 Location of Main Panel 	NA	NA	NA			
	 Location of Repeater Panel 	NA	NA	NA			
	Alternate source of power	NA	NA	NA			
	Hooters' Location	NA	NA	NA			
3	MOEFA	NA	NA	1			
)	Public Address System.	NA	NA NA	NA			
0	Automatic Sprinkler System. NA NA NA NA						
	Basement	NIA	N				
	· ·	NA NA	NA NA	NA			
	Cpper 1 1001	NA	NA NA	NA			
1	Sprinkler above false ceiling Internal Hydrogets	1171	IVA	NA			
1	Internal Hydrants						
	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floorHose Box	NA	NA	NA			
2		NA	NA	NA			
2	Yard Hydrants.						
	Total number of hydrants	NA	NA	NA			
	Hose Box						

	Detector System Panel	N/A	N/A	N/A
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 2057 dated 21.08.2013.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2016/NBC Part-4, it is recommended to issue Fire Safety Certificate.

Signature of the Inspecting Officer

Name :- Rajesh Kumar Designation:- ADO/RN

A STORY OF THE

As approved, f.f. letter er prump for your signature

1/14/2