GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

F.6/DFS/MS/EH/2018/SZ/ 367 No.

DELHI 110001 Dated: 06/03/2018

FIRE SAFETY CERTIFICATE

Certified that the Eating House located at India Islamic Cultural Centre, 87-88, Lodhi Estate, New Delhi-110003, comprised of lower ground floor, upper ground floor and First floor (Eating House at upper ground floor only) was granted FSC by this department vide letter No F6/DFS/MS/EH/2015/SZ/513 dated 10/04/15. The premise was re-inspected by the officer concerned of this department on 23/10/17 in presence of Sh. Mohd. Nausherawan (Jr. Manager Administration) and found that the said eating house premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" (Restaurant) with effect from . $\triangle 6 03.118.$ for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 06 03 18 at New Delhi by

(Vipin Kental) Chief Fire Officer Delhi Fire Service Ph: 011-23412225

Copy to: -

A

- 1. The Addl. Commissioner of Police (Lic.), 1st floor, PS Defence Colony, New Delhi-49
- 2. M/s India Islamic Cultural Centre, 87-88, Lodhi Estate, New Delhi-110003

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. The means of escape shall be kept unobstructed / unlocked & remain available for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, unauthorized use of land, if any.
- 7. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules. 2010. The form is www.dfs.delhigovt.nic.in.
- 8. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INSPE	CTION REPOR	Т	-			
	Name & address of the building:-	M/S India Islami	c Cultural Centre,87	-88,			
1.	Name & address of the building.	dhi Estate New D	Delhi-110003.				
2.	2. Building is Comprised of lower ground floor, ground floor, 1st floor (Restaurant at ground floor only) [Life control of the						
	T f a couponov:	ing. (Restaurant)	anilash				
3.	Type of occupancy:-						
4. Type of case.							
5.	Details of previous 1 3C.	10/04/15.					
5	Fire safety directives No	N/A 23/10/17. (lower ground floor, ground floor,					
J. 7	Date of inspection:-						
/.	Bute of mape and	1 st floor) Resta	aurant at ground floc	or only			
8.	Name of the inspecting officer:-	A.D.O. Mehm	nood.				
9.	Name & designation of officer						
	From the building side:-		isherawan (Jr. Mana	ager			
		Administration	1)				
	Year of construction:-	2006.	10/10 0/046 1 4 1	21/00/17			
11.	Applicant's letter No:-		18/D-9/246, dated				
S.No.	Minimum Standards on fire	Requirements	Provided at site	Remarks MR/NMR			
	Prevention and fire safety	as Circular No. F6/DFS/EH/20		IVIN/INIVIN			
	U/R 33	05/718, Dated-					
		04/04/05	1				
1.	Access to Building	04/01/03		1, 5			
1.	1) Road width	12 m.	18 m.	MR			
	2) Gate width	N/A	N/A	N/A			
	3) Width of internal road	N/A	N/A	N/A			
2	Nambar Width Type & Arr		cits				
2.	Number, Width Type & Arrangement of Exits A. Number of staircases						
		N/A	N/A	N/A			
	1. Upper floors (mezzanine)	N/A	N/A	N/A			
	2. Basements B. Width of staircase	14/14					
		N/A	N/A	N/A			
	1. Upper floors 2. Basements	N/A	N/A	N/A			
	C. Protection of exits	14/71					
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous	01 no.	02 nos.	MR			
	staircase to terrace	or no.					
	E. Width of corridor	2 m.	2 m.	MR			
	F. Door size	Required	4 nos.=1m, 1	MR(old case)			
	F. Door size	recoloris	no.=1.7m. & 1				
			no.=1.3m.				
3.	Compartmentation						
3.	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	N/A	N/A	N/A			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System		INTERNATION OF STREET				

T / A				
N/A				
/IR				
1R				
AR AR				
1R				
15				
1R				
1R				
1R				
5				
/IR				
1R				
I/A				
I/A				
1R				
1R				
I/A				
17.1				
I/A				
I/A				
I/A				
1R				
IR IR				
1R				
Yard Hydrants				
/A				
/A				
e building)				
1R				
1R				
1R				
I/A				
1R				
// // e 41 41 41 41 41 41 41				

	Special Fire Protection System Risk, if any:	n for Protection	n of special	N/A
20.	e) Building floor plan	N/A	N/A	N/A
	- January Suchap	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	a) Detector systempanelb) Flow switch panel	N/A	N/A	N/A
17.	a) Detector system	N/A	N/A	N/A
19.		N/A	N/A	N/A
	Total area location		N/A	N/A
18.	Refuge Area	N/A	Provided	MR
17.	Stand by Power Supply	Required	N/A	N/A
	e) Lift signage	N/A N/A	N/A	N/A
	c) Communication in lift car d) Fireman's switch	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	a) Pressurization of lift shaft	N/A	N/A	N/A
16.	Provision of Lifts.		Trovided	MR
15.	capacity Exit Signage.	Required	Provided	*
1	d) Over head tank	30,000 ltr.	30,000 ltr.	MR
* 1	c) Access to tank	N/A	N/A	N/A N/A
	b) Fire service inlet	Required .	Provided Provided	MR
1	capacity a) Draw-off connection		Eris.	MR
	Captive Water Storage for 1) Under ground tank	100000 Ltrs.	100000	
14.	Captive Water Storage for	p N/A	N/A	N/A
	c) Power supply d) Auto starting of pum	N/A	N/A	N/A
	b) Head of pump c) Power supply	N/A	N/A	N/A
-1	a) Discharge of pump	N/A	N/A	N/A

The fire protection system provided in the restaurant were tested, checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No.F6/ DFS/MS/EH/2015/SZ/513 dated 10/04/15, renewal under rule35 of the Delhi Fire Service rules 2010, is recommended.

Mehmood 710117

Assistant Divisional Officer(CS)

File called from DNS office on Sh18

Apolsce to impact an clarify about the