GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Assembly/SZ/2018/ 402

Dated: 13/3/18

FIRE SAFETY CERTIFICATE

Certified that Banquet Hall pertaining to M/s Saav Hospitality situated atPlot No.2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhicomprisedof three triple height banquet halls running at ground floor onlywas inspected by the officer concerned of this department on 09/03/2018in the presence of Mr. Sameer Aroraand found that the said premise havedeemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premise is fit for occupancy class "Assembly Building, Group-D" with effect from 2012 --2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Ph.: 011-23412225

Copy to:-

- 1. Sh. Sameer Arora, M/s Saav Hospitality, Plot No.2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhi.
- 2. The DHO, Central Zone, SDMC, Lajpat Nagar, New Delhi-110024 {Ref: Letter no. DHO/CNZ/1494/2018 dated 12/02/2018}
- 3. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration **every year** in **Form 'K'** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1. Name & address of the building: M/s Saav Hospitality, Plot No.2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhi

2. Type of Occupancy : Banquet Hall-Group D Assembly Building

3. Type of Case : New [Three Triple height banquet halls running at Ground Floor]

4. Details of Previous NOC : NA

5. Fire Safety directives letter No: F6/DFS/MS/BP/2018/951 dated 08/03/2018

6. Date of inspection : 09/03/2018 7. Name of Inspecting Officers : A.K. Malik

8. Name and designation of officers

From the building side : Mr. Sameer Arora

S.	Applicant's letter No. : Outdoor diary Minimum Standards on fire prevention	no. 3610 dated 08/03/2 UBBL/NBC	Provided at site	Remarks			
No.	and fire safety U/R 33	Requirement	1 Tovided at site	MR/NMR			
1.	Access to building						
	Road width	12m	Provided	MR			
	• Gate width	NA	NA	MR			
	 Width of internal road 	NA	NA	NA			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	 Upper Floors 	NA	NA	NA			
	 Basements 	NA	NA	NA			
	b. Width of staircases						
	 Upper Floor 	NA	NA	NA			
	 Basement 	NA	NA	NA			
	c. Protection of exits						
	 Fire check door 	NA	NA	NA			
	 Pressurization 	NA	, NA	NA			
	d. No. of continuous staircases to terrace	Required	1 No.	MR			
	e. Width of Corridor	2m	Provided	MR			
	f. Door Size	1 m & 2 m	Provided	MR			
3.	Compartmentation						
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door 	Required	Provided	MR			
		NA	NA	NA			
		NA	NA	NA			
	 Water Curtain 	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4.	Smoke Management System						
	Basements	NA	NA	NA			
	• Upper floors	12 ACPH	Exhaust Fans Provided	MR			
5.	Fire Extinguishers	12 ACI II		IVIIX			
J.	Total numbers	20 No's	22 No's	MR			
	• Types	ABC/W. CO ₂ /CO ₂	10/10/2	MR			
	• IS marking	ISI marked	Yes	MR			
6.	First-Aid Hose Reels		168	IVIIX			
0.	Total numbers on each floor	6 Nos	Provided	MR			
	• Length of hose reel hose	30 m	Provided	MR			
	Nozzle diameter	5 mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	Type of detectors NA NA NA						
	Location of Main Panel	NA NA	NA NA	NA			
	Location of Main Fanel Location of Repeater Panel	NA	1 2/	NA			
	Alternate source of power	NA	NA NA	NA			

- N/5-

	M/s Saav Hospitality, Plot No.2, Shambhu	Daval Marg. Near Okhla NSI	C Metro Station Non Della	
	• Basement	NA	NA	NA
	 Ground Floor 	NA	NA	NA
	 Sprinkler above false ceiling 	NA	NA	NA
11.	Internal Hydrants		1111	INA
	 Size of riser/down-comer 	100mm	Provided	MR
	 Number of hydrants per floor 	6 Nos	Provided	MR
*	Hose Box	6 Nos	Provided	MR
12.	Yard Hydrants	And the second s		1111
	 Total number of hydrants 	NA	NA	NA
	Hose Box	NA	NA	NA
13.	Pumping Arrangements			1111
	Ground Level			
	Discharge of main Pump	NA	NA	NA
	Head of Main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey Pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump Out put	NA	NA	NA
	Standby Pump HeadAuto Starting/Manual Stopping	NA	NA	NA
	Pump House Access	NA	NA	NA
	Terrace level	NA	NA	NA
	Discharge of pump			1171
	Head of the pump	900 LPM	Provided	MR
	Power Supply	40m	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14		Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	 Underground tank capacity 	NA	NA .	NA
	Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	Access to tank	NA	NA	NA
	Overhead Tank capacity	25,000 Lts	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		Trovided	IVIK
	Pressurization of Lift Shaft	NA	NA	NIA
	Pressurization of Lift lobby	NA	NA NA	NA
	Communication In lift Car	NA	NA	NA NA
	Fireman's Grounding Switch	NA	NA	NA NA
ž	Lift Signage	NA	NA	NA
17.	Standby power supply	Required	Provided	
18.	Refuge Area.	required	Tiovided	MR
	Total Area	NA .	NA	NIA
	> Location	NA NA	NA NA	NA NA
19.	Fire Control Room		11/1	INA
	Detector System Panel	NA	NA	NTA
	Flow Switch Panel	NA	NA NA	NA
	PA System Panel	NA	NA NA	NA
	Batter backup	NA	NA NA	NA NA
	Building Floor Plans	NA	NA	NA NA
20.	Special Fire Protection System for	NA	NA	
	Protection of special Risks, if any:	1 1/1 1	AVI	NA

M/s Saav Hospitality, Plot No.2, Shambhu Dayal Marg, Near Okhla NSIC Metro Station, New Delhi Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly form "H" in shape of DFA is put up for approval.

Signature of Inspecting Officer Name: - A.K. Malik Designation:-DO (SD)

Dy. CFO(SZ)

m.scell

Siz, f.T. is putup for Sig- plean.

DO (SM)

Miscey less.