GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ 418

Dated: 15/03/2018

FIRE SAFETY CERTIFICATE

Certified that the **Smt. Misri Devi Gyan Niketan**, Goyala Road, Shyam Vihar Ph-1, Najafgarh, New Delhi-110043 comprised ground plus one upper floor owned/occupied by Smt. Misri Devi Gyan Niketan was issued FSC by this department vide letter no. F.6/DFS/MS/School/2013/SZ/1318 dated 18.12.13. The school was re-inspected by the officer concerned of this department on 13.02.2018 in the presence of Sh. Rajesh (Supervisor) and found that an additional B-Block (under renovation as per form "J") comprised of ground plus two upper floors is constructed and will apply for FSC separately after completion of same. Smt. Misri Devi Gyan Niketan have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**A-Block only**) is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 1503 2018 at New Delhi.

13/3.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal, Smt. Misri Devi Gyan Niketan, Goyala Road, Shyam Vihar Ph-1, Najafgarh, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

School building is comprised of two blocks namely A-Block & B-Block. A-Block is having ground plus one upper floor and B-Block is comprised of ground plus two upper floors (Under renovation). INSPECTION REPORT Smt. Misri Devi Gyan Niketan, Goyala Road, Shyam Vihar Ph-1, 1. Name & address of the building: Najafgarh, New Delhi-110043. 2. Type of Occupancy Educational Renewal Type of Case F.6/DFS/MS/School/2013/SZ/1318 dated 18.12.13 (for A Block only) 4. Details of Previous NOC 5. Fire Safety directives letter No 6. Date of inspection 13.02.2018 A.D.O. Sandeep Duggal 7. Name of Inspecting Officer 8. Name and designation of officers Sh. Rajesh (Supervisor) From the building side 1997 & after 2013 9. Year of Construction Form "J" dated Nil 10. Applicant's letter No. Requirements as Provided at Remarks Minimum Standards on fire prevention and S. No. per FSC dt. MR/NMR site fire safety U/R 33 18.12.13 Access to building 1. Accessible 06 mtrs 09 mtrs M/R Road width Directly accessible 4.5 mtrs M/R Gate width from road N/A N/A Width of internal road N/A Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors 02 No. Provided M/R **Basements** N/A N/A N/A b. Width of staircases 150 cms/additional 115 to 122 (02 M/R Upper Floor staircase of 75 cms no.'s) cms in A **Basements** if less than 150 cms blk N/A N/A N/A c. Protection of exits N/A N/A Fire check door N/A Pressurization N/A N/A N/A d. No. of continuous staircases to N/A One N/A terrace 180 cms in A-blk M/R 150 cms. Width of Corridor 90 to 100 cms in M/R, being old case 100 cms Door Size A blk Compartmentation 3. N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A Smoke Management System 4. N/A N/A N/A Basements Natural ventilation M/R Required Upper floors provided Fire Extinguishers 5. M/R Provided 06 no's Total numbers ABC/CO₂ type Provided M/R **Types** ISI marked IS marking M/R Provided First-Aid Hose Reels 6. Total numbers on each floor in B blk N/A N/A N/A N/A N/A N/A Length of hose reel hose NI/A NT/A

	1			
7.	Automatic fire detection and alarming system		27/4	DI/A
	 Type of detectors 	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	, N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
.]	MOEFA	N/A	N/A	N/A
.]	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System	27/4	DI/A	N/A
	 Basement 	N/A	N/A N/A	N/A N/A
	Ground Floor	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants	N/A	N/A	N/A
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	IN/A	14/11	11/12
2.	Yard Hydrants	N/A	N/A	N/A
	Total number of hydrants	N/A N/A	N/A N/A	N/A
	Hose Box	IN/A	IN/A	14/17
3.	Pumping Arrangements			15.
	Ground Level			27/4
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out putJockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A N/A	N/A N/A
	Pump House Access	N/A	N/A	IN/A
	Terrace level in B blk	N. C.	27/4	21/4
	Discharge of pump	N/A	N/A	N/A
_	Head of the pump	N/A	N/A	N/A N/A
	> Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
4.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
*	 Overhead Tank capacity in B blk 	N/A	N/A	N/A
-	D '(C' : D L1).	N/A N/A	N/A N/A	N/A
5.	Exit Signage in B blk	17/11		
6.	Provision of Lifts.	27/4	No Li	ft N/A
	Pressurization of Lift Shaft	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
	Surgery Power supply			
18.	Refuge Area.			
10.	> Total Area	N/A	N/A	N/A
	> Location	NI/A	N/A	N/A

19.	Fire Control Room	e Control Room					
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	/ N/A			
	PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2013/SZ/1318 dated 18.12.13 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per Form "J" submitted by Smt. Pushpa Sharma (Principal) Block -B is under renovation, therefore renewal of FSC for Block-A is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

80 00 (Ca) 20 02 | 18 22/02/18

Divisional Officer (South West)

CFO (\$2\$) MSCELL FT/10.

FT/10.