GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F.6/DFS/MS/ 2018/943

Dated: 16/3 /2018

FIRE SAFETY CERTIFICATE

Certified that The Heritage School, Plot No - 8, Sector-23, Rohini, Delhi-110085 comprised of Basement + Ground + Three upper floor owned/occupied by The Heritage School was issued fire safety certificate vide letter no. F.6/DFS/MS/2015/School/WZ/86 dated 15/01/2015. The premises was re-inspected by the officer from this department on dated 05/03/2018 in the presence of Mrs. Neena Kaul and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition and there is no additional construction. The premises have therefore deemed complied with the requirements under Rule 33 of the Delhi Fire Service Rules, 2010 and building/premises is fit for occupancy under Education class with effect from $\frac{1}{6}$ / $\frac{2}{2018}$ for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The basement shall only be used as per BBL 1983.
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the schedule of Delhi Fire Service Rules 2010. The form is available WWW.dfs.Delhigovt.nic.in

at New Delhi by

(Atul Garg) Chief Fire Officer

Ph: 011-23414250

Copy to:

- 1. The Principal, The Heritage School, Plot no-8, Sector-23, Rohini, Delhi-110085
- 2. The Director of Education, Old Secretariat, Delhi

INSPECTION REPORT

1. Name & address of the building: The Heritage School, Plot no-8, Sector-23, Rohini, Delhi-85

2. Type of Occupancy

: Educational

(B+G+3)

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/2015/School/WZ/86 dated 15/01/2015

5. Fire Safety directives letter No : NBC Part-IV

6. Date of inspection

: 05/03/2018

7. Name of the Inspecting Officers: ADO (RN)

8. Name and designation of officers

from the building side

: Mrs. Neena Kaul

9. 9. Year of Construction

:2003

10. 10. Applicant's letter No.

: Nil dated 28/12/2017

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mtr	06 mtr	M/R		
	Gate width	4.5 mtr	4.5 mtr	M/R		
	 Width of internal road 	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of	of Exits				
	a. Number of staircases					
	Upper Floors	04	04	M/R		
	Basements	04	04	M/R		
	b. Width of staircases		100			
	Upper Floors	1.5 mtr	1.5 mtr each	M/R		
	Basements	1.5 mtr	1.5 mtr each	M/R		
	c. Protection of exits					
	Fire check door	Required	Provided in basement	M/R		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	02	02	M/R		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	1 mtr	1 mtr	M/R		

3	Compartmentation.					
	Fire check door	Required	Provided in basement	M/R		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	• Fire Rating of shaft door	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	• Fire Dampers	N/A	N/A	N/A		
	Smoke Management System.					
	• Basements	30 a/c per hour	Exhaust fan	M/R		
	 Upper floors 	12 a/c per hour	provided Provided	M/R		
	Fire Extinguishers					
	Total numbers	28	28	M/R		
	• Types		ABC	M/R		
	 IS marking 	ISI marked	yes	M/R		
	First-Aid Hose Reels.					
	Total numbers on each floor	Three @ each floor	03 at each floor	M/R		
	 Length of hose reel hose 	30 m	Provided	M/R		
	Nozzle diameter	5 mm	Provided	M/R		
,	Automatic fire detection and alarming			CLEINIU-RANU		
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
3	MOEFA	Required	Provided	M/R		
)	Public Address System.	Required	Provided	M/R		
0	Automatic Sprinkler System.					
	Basement	Required	Provided	M/R		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	4"	Provided	M/R		
	Number of hydrants per floor	03	Provided	M/R		
	Hose Box	03	Provided	M/R		

12	Yard Hydrants.				
	Total number of hydrants	Required	Provided	M/R	
	Hose Box	Required	Provided -	M/R	
13	Pumping Arrangements.	1000000			
	A unping 111 ungements	2			
	Ground Level				
	Discharge of main Pump	1620 LPM X 3	Provided	M/R	
	Head of Main pump	40 m	Provided	M/R	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	180 LPM	Provided	M/R	
	Jockey pump head	40 m	Provided	M/R	
	Standby Pump out put	1620 LPM	Provided	M/R	
	Standby Pump Head	40	Provided	M/R	
	Auto Starting/ Manual stopping	Required	Provided	M/R	
	Pump House Access	Required	Provided	M/R	
	Terrace level				
	Discharge of pump	450 LPM	Provided	M/R	
	Head of the pump	40 m	Provided	M/R	
	➤ Power Supply	Required	Provided	M/R	
	> Auto Starting of pump	Required	Provided	M/R	
4	Captive Water Storage for fire fighting.				
	Underground tank capacity	2,00,000 ltr	Provided	M/R	
	Draw-off connection	N/A	N/A	N/A	
	> Fire service inlet	N/A	N/A	N/A	
	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	25,000	Provided	M/R	
5	Exit Signage.	Required	Provided	M/R	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
7	Standby power supply	Not Required	Provided	M/R	

18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2015/School/WZ/86 dated 15/01/2015 Renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer

Name: Rajesh Kumar

Designation: Asstt. Divisional Officer

Dycholw 2/

8/3/18