GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/2018/ 50 4

Dated: 26/3/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Farzi Café (A Unit of Massive Restaurants Pvt. Ltd.) located at E-38, 39, First floor, Inner Circle, New Delhi comprises of Ground + 02 Upper floor owned/occupied by M/s Farzi Café (A Unit of Massive Restaurants Pvt. Ltd.) was granted FSC by this department vide letter No.F6/DFS/MS/EH/2015/NDZ/2240 dated 23/12/15. The premises was re-inspected by the officer concerned of this department on 20/03/18 in the presence of Mr. Govind (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D without addition of new seats with effect from 24/24/142-for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 26/2/18----at New Delhi by.

(Vipin Kental)
Chief Fire officer
Delhi Fire Service

Copy to:-

1. The Medical Officer of Health, Health Department, Palika Kendra, New Delhi.

2. The Manager,

M/s Farzi Café (A Unit of Massive Restaurants Pvt. Ltd.) at E-38, 39, First floor, Inner Circle, New Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

M/s Farzi Café (A Unit of Massive Restaurants Pvt. Ltd.) at E-38, 39, First floor, Inner Circle,

New Delhi.

2. Type of occupancy:-

Assembly Building Group-D

Gr. + 02 upper floors

3. Type of case:-

4. Details of previous FSC:-

Renewal F6/DFS/MS/EH/2015/NDZ/2240 dated

23/12/15 N/A

5. Fire safety directives No.-

6. Date of inspection:-

20/03/18 7. Name of the inspecting officer:-

Sh. G.S. Chauhan (DO/CD) &

Sh. Manoj Kumar Sharma (ADO/CC)

8. Name & designation of officer from the building side:-

9. Year of construction:-

10. Applicant's letter No:-

Mr. Govind (Manager) Old Heritage Bldg. Nil dated 12/03/2018

S.No.	Minimum Ct. 1 1 C				
5.110.	Prevention and fire safety	Requirement/ Existing fire safe arrangements	Provided at site	Remarks MR/NMI	
	U/R 33	arrangements		IVIIVINIVII	
1.	Access to Building				
	1) Road width	09 mtr	13 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & A	rrangement of F	vite	IN/A	
	A. Number of staircases	general of L	Arts		
	1. Upper floors	02 No.	02 No.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase		14/11	IN/A	
	1. Upper floors	1.25 mtr.	1.45 mtr. & 1.10 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits	N/A	N/A	N/A	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	21/4	
	F. Door size	2 mtr.	2 mtr.	N/A	
	Compartmentation	2 11111.	2 11101.	MR	
	1) Fire check door	N/A	N/A	NI/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A N/A	
	4) Water curtain	N/A	N/A	N/A N/A	
	5) Fire Dampers	N/A	N/A	N/A	
	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	12 ACPH		MR	
	Fire Extinguishers			1411/	
	1) Total numbers	04 Nos.	04 Nos.	MR	
	2) Types			MR	
	3) ISI marking			MR	

6.	First-Aid Hose Reel			
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	Alarming Sv	stem	IVIK
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
).	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		IVA	IVA
	1) Basement	N/A	N/A	NI/A
	2) Upper floors	N/A	Provided	N/A N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling		14/71	IN/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	100 mm	MR
	2) Number of hydrants per	01	01	MR
	floor			IVIIC
	3) Hose box	01	01	MR
2.	Yard Hydrants			TVIIC
	1) Total number of hydrants	N/A	N/A	N/A
11	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level			
	a) Discharge of main	N/A	N/A	N/A
	pump			
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pum	p N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	t N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	450 LPM	450 LPM	MR
	b) Head of pump	30 mtr.	30 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
4.	Captive Water Storage for I			
	1) Under ground tank	N/A	N/A	N/A
	capacity			
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	10,000 ltr.		

15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys Risk, if any: ABC & Co2	MR		

The fire protection systems provided in the building were randomly tested,

checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2015/NDZ/2240 dated 23/12/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name - G.S Chauhan Designation :- DO (CD) Name: - M.K. Sharma

Signature of the Inspecting Officer

Designation:- ADO (CC)

Aycro(NDZ)

Resturant has increased seeds

from 98 to 300 hundered. Ask for plans

to ascertain seeds numbers.

The Livensee had regnested too addition of