GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2018/ 456

Dated: $2 \approx 13/18$

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Metro View Inn located at 9/8, East Patel Nagar, New Delhi110008 comprised of basement, ground plus three upper floors, using basement as hall/storage, ground floor as reception, pantry & 04 guest rooms, first, second and third floor each having 05 guest rooms respectively (total 19 guest rooms) was granted FSC by this department vide letter No. F6/DFS/MS/GH/2014/SZ/1562 dated 12.12.2014. The premises was re-inspected by the officer concerned of this department on 07/03/2018 in presence of Sh. Kamal Kishore, proprietor, and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) with effect from 10/2/18 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ______ at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. The Manager, M/s. Hotel Metro View Inn, 9/8, East Patel Nagar, New Delhi- 110008.

2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

: M/s. Hotel Metro View Inn, 9/8, East Patel Nagar, New 1. Name & address of the building Delhi- 110008

: Lodging House 2. Type of Occupancy

: Renewal 3. Type of Case

: F.6/DFS/MS/GH/2014/SZ/1562 dated 12.12.2014 4. Details of previous NOC

5. Fire Safety directives letter No : Nil

: 07.03-2018 6. Date of inspection

: M.K. Chattopadhyay, DO(South West) 7. Name of the Inspecting Officers

8. Name and designation of officers

: Sh. Kamal Kishore, proprietor from the building side

: 2009 9. Year of Construction

: Form 'J' dated 03.01.2018 10. Applicant's letter No.

The said guest house is comprised of basement, stilt, ground plus three upper floors.

S. No.	3	inimum Standards on fire ention and fire safety U/R 33	Fire safety arrangements as per letter dt. 12.12.2014	Provided at site	Remarks MR/NMR
1	Access	to building			
1		Road width	06 mts	Provided	MR
		Gate width		Directly accessible	MR
		Width of internal road	N/A	N/A	N/A
2	Numb	er, Width, Type & Arrangement	t of Exits		
1	1	nber of staircases	-	-	-
	a. Ivul	Upper Floors	01	01	MR
		Basements	01	01	MR being old case
		dth of staircases	-	-	· -
		Upper Floors	Old Case	1.25 mts	MR being old case
	•	Basements	Old Case	1.16 - 1.40 mts	MR being old case
	Due		-	-	-
	c. Pro	c. Protection of exits • Fire check door	N/A	N/A	N/A
		Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to	01	01	MR	
	terrac	· ·	N/A	N/A	N/A
		dth of Corridor or Size	Old case	0.85 mts	MR being old case
3		partmentation.			,
	•	Fire check door	N/A	N/A	N/A
	•	Sealing of electrical shafts	Required	Sealed	MR
	•	Fire Rating of shaft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
		Fire Dampers	N/A	N/A	N/A
4	Smo	ke Management System.			

	• Basements	30 a/c per hour	provided	MR
	Upper floors	12 a/c per hour	Natural Ventilation	MR
5	Fire Extinguishers			
	 Total numbers 	20	Provided	MR
	 Types 	CO ₂ , ABC, WCO ₂	Provided	MR
	IS marking	ISI marked	Provided	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming	g system.		
	• Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	• Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	D.G. set 85 KVA	MR
	Hooters' Location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
~	Basement	N/A	Provided	MR (area is less than 200 sq. mtr)
	Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.		-	2 1/2 2
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A

1-V. -----

	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace level						
	Discharge of pump	450 LPM	450 LPM	MR			
	Head of the pump	30 mts	30 mts each	MR			
	Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for fire fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	Provided				
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	5,000 lts	5,000 lts	MR			
15	Exit Signage.	Required	Provided	MR			
6	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	Required	Provided	MR			
	Fireman's Grounding Switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
8	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Battery backup	Required	Provided	MR			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note: - All the shortcomings issued by this department vide letter no. F.6/DFS.MS/GH/SZ/2018/610 dated 13.02.2018 have been complied with by the guest house mangement.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/2014/SZ/1562 dated 12.12.2014, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY Div. Officer (South West)

F. T. letter is but up for Signi

2/2/00/30

M.SCEM 15/3