GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2018 / 556

Dated 2/4/18

FIRE SAFETY CERTIFICATE

Certified that the Half Way Home/ Long Stay Homes located at Block C, IFC Narela, Delhi-110040 comprised of basement, stilt, ground and four upper floors owned/occupied by Half Way Home/ Long Stay Homes have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 02.04.2018 in the presence of Mr. Charan Singh, E.E. and that the building/ premises is fit for occupancy "Institutional" only with effect from for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

Issued on ...2 4.4.8...... at New Delhi by

Chief Fire Officer Ph-011-23414250

Copy to:-

1. The Executive Engineer (ED-III)
DSIIDC, Technical Center Building
Wazirpur Industrial Area
Delhi-110052.

ole

4

2/12

INSPECTION REPORT

1. Name & address of the building: Half Way Home/ Long Stay Homes at Block C, IFC Narela

Delhi-110040.

2. Type of Occupancy : Institutional (Basement, stilt, ground plus 04 floors)

3. Type of Case :New4. Details of previous NOC : Nil

5. Fire Safety directives letter No : F6/DFS/MS/BP/2012/1687 dated 10.05.2012.

6. Date of inspection : 02.04.20187. Name of the Inspecting Officers : ADO (RN)

8. Name and designation of officers

from the building side : Sh Charan Singh/ E.E

9. Year of Construction : 2016-17

10. Applicant's letter No. : DSIIDC/EE (ED-III)/2016-17/301 dated 22.03.2018

S. No	Minimum Standards on fire prevention and fire safety U/R 33 Access to building	NBC Requirement	Provided at site	Remarks MR/NMI
	Access to building			•
	Road width	06m	20m	MR
	Gate width	4.5m	4.5 m	MR
Telephone in a contract of	Width of internal road	06m	06m	MR
2	Number, Width, Type & Arrangem	ent of Exits		
	c. Number of staircases			
	Upper Floors	02 nos	02 nos	MR
	• Basements	02nos	02 nos	MR
	d. Width of staircases			IVIIC
	Upper Floors	02m each	02m each	MR
The same of	• Basements	02m each	02m each	MR
	c. Protection of exits			1111
No.	• Fire check door	Required	Provided	MR
Annual Control of the	Pressurization	Required	Provided	MR
100	g. No. of continuous staircases to terrace	2nos	2nos	MR
- 1	h. Width of Corridor	NA	NA	NA
	i. Door Size	2.0m	2.0m	MR
	Compartmentation.			
	• Fire check door	Required	Provided	MR
The same of the sa	Sealing of electrical shafts	Required	Provided	MR

V	. []		
 Fire Rating of shaft door 	Required	Provided	MF
Water Curtain	Required	Provided	MF
• Fire Dampers	Required	Provided	MF
Smoke Management System.			
Basements	30ACPH	Provided	MR
Upper floors	12ACPH	Provided	MR
Fire Extinguishers			
Total numbers	18nos	21 nos	MR
• Types	ABC/CO2	ABC-21	MR
IS marking	Required	Provided	MR
First-Aid Hose Reels.	-	9	17110
Total numbers on each	01 nos each floor	01 nos each	MR
floor			
Length of hose reel hose	30m	Provided	MR
Nozzle diameter	5mm	Provided	MR
Automatic fire detection and alarming system.			
Type of detectors	Required	Provided	MR
 Location of Main Panel 	Required	Provided	MR
Location of Repeater Panel	Required	Provided	MR
Alternate source of power	Required .	Provided	MR
Hooters' Location	Required	Provided	MR
MOEFA	Required	Provided	MR
Public Address System.	Required	provided	MR
Automatic Sprinkler System.			
Basement	Required	Provided	MR
Upper Floor	Required	Provided	MR
Sprinkler above false ceiling	Required	Provided	MR
Internal Hydrants			
Size of riser/down-comer	01	Provided	MR
 Number of hydrants per floor 	01 nos	01 nos	MR
Hose Box	01nos	01 nos	MR
Yard Hydrants.	•		
Total number of hydrants	03Nos.	03 nos	MR
		03 1103	IVIIC

0)114

		,		
	Hose Box	03	03 nos	MF
13	Pumping Arrangements.			
	➤ Ground Level			
	Discharge of main Pump	2280 Lpm	2280 LPM	MF
	Head of Main pump	70 mtr	70m	MF
	Number of main pumps	1nos	1nos	MR
	Jockey Pump out put	180 LPM	180 LPM	MR
	Jockey pump head	70 mtr	70m	M/F
	Standby Pump out put	2280LPM	2280 LPM	MR
	Standby Pump Head	70 mtr	70m	MR
	Auto Starting/ Manual	Required	Provided	MR
	stopping	Required	Provided	
	➤ Pump House Access		Tiovided	MR
	Terrace level	NA	NIA	1 274
	Discharge of pump	NA	NA	NA
	Head of the pump		NA	NA
	Power Supply	NA	NA	NA
	➤ Auto Starting of pump	NA	NA	NA
	Captive Water Storage for fire fighting.			
	Underground tank capacity	1,00,000ltrs	1,00,000 ltr.	MR
	➤ Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	
	Overhead Tank capacity	20,000 ltrs	20,000 ltr.	MR
	Enil Ci	*	20,000 111.	MR
	Exit Signage.	Required	Provided	MR
	Provision of Lifts.	1	9	
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	Required	Provided	MR
	Communication In lift Car	Required	Provided	MR
A CENTRAL PROPERTY OF THE PERSON NAMED IN COLUMN 1	Fireman's Grounding	Required	Provided	MR
Service and an artist of	Switch	•	11011404	IVIK
	• Lift Signage	Required	Provided	MR
6	Standby power supply	Required	Provided DG Set	MR
+			0 000	

18	Refuge Area.			~	
	> Total Area	NA	NA	NA	
	> Location	NA	NA	NA	
19	Fire Control Room				
	Detector System Panel	Required	Provided	MR	
	Flow Switch Panel	Required	Provided	MR	
>	PA System Panel	Required	Provided	MR	
	Batter backup	Required	Provided	MR	
	Building Floor Plans	Required	Provided	MR	
20	Special Fire Protection Systems	Required	Provided in Electrical Panel	MR	
	for Protection of special Risks, if		Room		
	any:				

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The observations/ shortcomings issued and communicated vide this department letter of even no. 1079 dated 14.03.2018 have been compiled by the management.

Keeping in view of satisfactory compliance of the minimum standards on fire prevention and fire safety required under the rules and fire safety guidelines issued vide letter of even no. 1687 dated 10.05.2012, it is recommended to issue Fire Safety Certificate under rule 2010.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation:- ADO/RN

letter is put up far ongriphens.