

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

Fax No. 011-23412593 , Ph. 011-23412225


No F 6/OFS/MS/school/2018/S2/576

Dated 4/4/18

FIRE SAFETY CERTIFICATE

Certified that the New Shanti Memorial School located at F-347, Lado Sarai, New Delhi, comprised of Ground plus one upper floor owned/occupied by Smart Welfare Society (Regd.,) was inspected by the officer concerned of this department on 05.03.2018 in presence of Mr. Anup Sejwal (Supervisor) of the school and found that said premises have complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education Govt. of NCT of Delhi and that the school building is fit for occupancy class "Educational Building" Group – B, as above with effect from the date of issue of this certificate for a period of Three years on the conditions mentioned below.

Issued on .....4/4/18..... at New Delhi by.

  
(Vipin Kantal)  
Chief Fire Officer

- Copy to- 1. The Principal, New Shanti Memorial School, F-347, Lado Sarai, New Delhi – 110030.  
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.


Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All fire safety arrangement provided there-in shall be maintained in good working conditions at all times as seen during inspection. Any Loss of life or property due to non functional fire safety measures shall be at risk and responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.Delhigovt.nic.in](http://www.dfs.Delhigovt.nic.in).
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 if UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

INSPECTION REPORT				
1	Name & Address of the Building	NEW SHANTI MEMORIAL SCHOOL, F-347, LADO SARAI, NEW DELHI-110030,		
2	Type of Occupancy	Educational Building "Group-B" (School)		
3	Building Comprised of	Ground plus one upper floor.		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	F.16//Estate/CC/Fire Safety/2011/3298 - 3398 Dated. 01.03.2011		
7	Date of Inspection	05.03.2018		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Anup Sejwal (Supervisor)		
10	Year of construction	1999		
11	Applicant letter No.	Nil dated 16/02/2018		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	DOE circular requirements	Provided at Site	Remarks MR/NMR
1	<b>Access to Building.</b>			
	• Road width	Accessible	6 mtr	MR
	• Gate width	NA	4.5m & 1.70m	NA
	• Width of internal road	NA	NA	NA
2	<b>Number, width, type &amp; arrangement of exits.</b>			
	<b>a. Number of Staircase</b>			
	➤ Upper floors.	One	Two	MR
	➤ Basement floor.	NA	NA	NA
	<b>b. Width of Staircase</b>			
	➤ Upper floors	1.5m / 0.75m	0.86m & 1.05m	MR
	➤ Basement floor	NA	NA	NA
	<b>c. Protection of exits</b>			
	➤ Fire check door	NA	NA	NA
	➤ Pressurization	NA	NA	NA
	<b>d. No. of continuous staircase to terrace</b>	One	One	MR
	<b>e. Width of corridor</b>	NA	NA	NA
	<b>f. Door size</b>	1 mtr	Provided	MR
3	<b>Compartmentation.</b>			
	• Fire check door.	NA	NA	NA
	• Sealing of electrical shafts.	NA	NA	NA
	• Fire rating of shaft door.	NA	NA	NA
	• Water curtain	NA	NA	NA
	• Fire dampers.	NA	NA	NA
4.	<b>Smoke Management system.</b>			
	• Basement	NA	NA	NA
	• Upper floors	NA	NA	NA
5.	<b>Fire Extinguishers.</b>			
	• Total numbers	04 Nos.	Provided	MR
	• Types	ABC / Co2	ABC type	MR
	• ISI Marking	ISI Marking	Provided	MR
6.	<b>First Aid Hose Reels.</b>			
	• Total numbers on each floor.	NA	NA	NA
	• Length of hose-reel hose.	NA	NA	NA
	• Nozzle Diameter	NA	NA	NA


New Shanti Memorial School at F-347, Lado Sarai, New Delhi

7	<b>Automatic fire detection &amp; alarming system.</b>			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooter's location	NA	NA	NA
8.	<b>MOEFA</b>	NA	NA	NA
9.	<b>Public Address System</b>	NA	NA	NA
10.	<b>Automatic Sprinkler System</b>			
	• Basement	NA	NA	NA
	• Upper floors	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA
11.	<b>Internal Hydrants.</b>			
	• Size of Riser/Down-comer	NA	NA	NA
	• Number of Hydrant per floor	NA	NA	NA
	• Hose box.	NA	NA	NA
12.	<b>Yard Hydrants.</b>			
	• Total number of hydrants.	NA	NA	NA
	• Hose box.	NA	NA	NA
13.	<b>Pumping arrangements.</b>			
	• <b>Ground Level</b>			
	➤ Discharge of main pump.	NA	NA	NA
	➤ Head of main pump.	NA	NA	NA
	➤ Number of main pumps.	NA	NA	NA
	➤ Jockey Pump output.	NA	NA	NA
	➤ Jockey Pump head.	NA	NA	NA
	➤ Standby Pump output.	NA	NA	NA
	➤ Standby Pump head.	NA	NA	NA
	➤ Auto Starting/Manual Stopping.	NA	NA	NA
	➤ Pump house access.	NA	NA	NA
	• <b>Terrace Level</b>			
	➤ Discharge of pump.	NA	NA	NA
	➤ Head of pump.	NA	NA	NA
	➤ Power supply.	NA	NA	NA
	➤ Auto starting of pump.	NA	NA	NA
14.	<b>Captive water storage for Fire Fighting.</b>			
	• Underground tank capacity.	NA	NA	NA
	➤ Draw-off connection.	NA	NA	NA
	➤ Fire Service Inlet.	NA	NA	NA
	➤ Access to tank.	NA	NA	NA
	• Overhead tank capacity.	NA	NA	NA
15.	<b>Exit Signage.</b>	NA	NA	NA
16.	<b>Provision of Lifts.</b>			
	• Pressurization of lift shaft.	NA	NA	NA
	• Pressurization of lift lobby.	NA	NA	NA
	• Communication in lift car.	NA	NA	NA
	• Fireman's switch.	NA	NA	NA
	• Lift signage.	NA	NA	NA
17.	<b>Standby Power Supply</b>	NA	NA	NA
18.	<b>Refuge Area</b>			
	• Total area	NA	NA	NA
	• Location	NA	NA	NA


19.	<b>Fire Control Room.</b>	NA	NA	NA
	• Detector system panel.	NA	NA	NA
	• Flow switch panel.	NA	NA	NA
	• PA system panel.	NA	NA	NA
	• Battery backup.	NA	NA	NA
	• Building floor plan.	NA	NA	NA
20.	<b>Special Fire Protection System for the Protection of special Risk, if any.</b>	NA	NA	NA
<p>The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.</p> <p>Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010</p> <p>Accordingly DFA is put up for approval and signature please.</p> <p style="text-align: right;">               Signature of the Inspecting Officer              Name : R.N. Singh              Designation: ADO (BCP)         </p>				

New Shanti Memorial School at F-347, Lado Sarai, New Delhi

~~DO (SD)~~

  
14/3/18

  
CFO (SZ)

  
15/3




CFO (SZ) Pl speak

  
16/3

BCFO/SZ

~~DO (SD)~~

  
17/3

The FSC to be prepared as per DOE