## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/School/2018/SZ/ 565

Dated: .3.4.1.8.

## FIRE SAFETY CERTIFICATE

Certified that **The Ardee School** located at Maharishi Ramana Marg, Sujan Singh Park, New Delhi-110003, comprised of Ground and one upper floor (1<sup>st</sup> floor Pota cabin) was issued FSC by this department vide letter No. F.6/DFS/MS/SZ/School/2014/SZ1248 dated 07/10/2014. The premises was re-inspected by officer concern of this department on 21-03-2018 in presence of Mr. BK Thakur (Admin)) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class "**Educational**" (School), with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 2/4/8 at New Delhi by

(Vipin Kental) Chief Fire Officer

Copy to: -

- 1. Principal, The Ardee School, Maharishi Ramana Marg, Sujan Singh Park, N. Delhi-110003
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTI	ON REPORT			
1	Name & Address of the Building	THE ARDEE SCHOOL, MAHARISHI RAMANA MARG, SUJAN SINGH PARK, NEW DELHI- <b>2</b> 3			
2	Type of Occupancy	ip-B" (School)	EETH 65		
3	Building Comprised of		r floor. (First floor Pota	(Cabins)	
4	Type of Case	Renewal	1 11001. (1 1131 11001 1 011	e Cuomby	
5	Details of Previous NOC		ol/2014/SZ/1248 Dated	107-10-2014	
6	Fire Safety Directives Letter No		Safety/2011/3298 to 3398 da		
7	Date of Inspection	21-03-2018			
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)			
9	Name & Designation of	Mr. BK Thakur (Admin)			
10	Officers from the building side	2003			
10	Year of construction	Nil dated 20.02.20	110		
11	Applicant letter No.	Old NOC	Provided at Site	Remarks	
S. No	Minimum standards on Fire Prevention	requirement	Provided at Site	MR/NMI	
1	and Fire Safety U/R 33 Access to Building.	requirement		IVAROTATA	
1	Road width	Required	6 mtr	MR	
	Gate width	N/A	4.5 mtr	N/A	
	Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits	14/24	A 17 A A		
hat	a) Number of Staircase				
	Upper floors	Required	02 Nos	MR	
	Basement floor	N/A	N/A	N/A	
	b) Width of Staircase				
	Upper floors	1.50 / 0.75m	0.90m & 0.92m	MR	
		N/A	N/A	N/A	
	Basement floor	IN/A	IV/A	IN/A	
	c) Protection of exits	DI/A	NI/A	NI/A	
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	N/A	1.5 mtr	N/A	
	f) Door size	1m	Provided	MR	
3	Compartmentation.				
	Fire check door.	N/A	N/A	N/A	
	<ul> <li>Sealing of electrical shafts.</li> </ul>	N/A	N/A	N/A	
	Fire rating of shaft door.	N/A	N/A	N/A	
	Water curtain	N/A	N/A	N/A	
	Fire dampers.	NA	NA	NA	
4.	Smoke Management system.	40 1 0077	27/4	27/4	
	Basement	30 ACPH	N/A	N/A	
	Upper floors	12 ACPH	N/A	N/A	
5.	Fire Extinguishers.				
	Total numbers	04 Nos	08 Nos	MR	
	Types	ABC / CO2	ABC type	MR	
	ISI Marking	Required	Provided	MR	
6.	First Aid Hose Reels.				
	Total numbers on each floor.	N/A	N/A	N/A	
	<ul> <li>Length of hose-reel hose.</li> </ul>	N/A	N/A	N/A	
	Nozzle Diameter	N/A	N/A	N/A	
	The Ardee School at Maharishi Ramana				

The Ardee School at Maharishi Ramana Marg, Sujan Singh Park, New Delhi-110023

7 A	utomatic fire detection & alarming system			-
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
-	<ul> <li>Hooter's location</li> </ul>	N/A	N/A	N/A
3. M	10EFA	N/A	N/A	N/A
). P	ublic Address System	N/A	N/A	N/A
0. A	utomatic Sprinkler System			27/1
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1. II	nternal Hydrants.			27/4
	Size of Riser/Down-comer	N/A	N/A	N/A
	<ul> <li>Number of Hydrant per floor</li> </ul>	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
2. Y	ard Hydrants.		**************************************	3.774
	<ul> <li>Total number of hydrants.</li> </ul>	N/A	N/A	N/A
1	Hose box.	N/A	N/A	N/A
3. P	rumping arrangements.			
	Ground Level			
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A	N/A	N/A
-	> Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	<ul><li>Standby pump head.</li><li>Auto Starting/Manual Stopping.</li></ul>	N/A	N/A	N/A
		N/A	N/A	N/A
	Terrace Level	DT/A	NT/A	N/A
and the same of th	Discharge of pump.	N/A	N/A N/A	N/A
*AAA	> Head of pump.	N/A	N/A N/A	N/A
Section 2	Power supply.	N/A	N/A N/A	N/A
	> Auto starting of pump.	N/A	IN/A	IN/A
4.	Captive water storage for Fire Fighting.	N/A	N/A	N/A
od significance	<ul> <li>Underground tank capacity.</li> <li>Draw-off connection.</li> </ul>	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	<ul> <li>Overhead tank capacity.</li> </ul>	N/A	N/A	N/A
5. I	Exit Signage.	N/A	N/A	N/A
	Provisions of Lifts.			
I	Pressurization of lift shaft.	N/A	N/A	N/A
	<ul> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
ertweenenddo		N/A	N/A	N/A
	• Fireman's switch.			
	• Lift signage.	N/A	N/A	· N/A
17 5	Standby Power Supply	N/A	N/A	N/A
	Refuge Area			
	Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A

The Ardee School at Maharishi Ramana Marg, Sujan Singh Park, New Delhi-110023

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the	N/A	N/A	N/A
	Protection of special Risk, if any.			

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under DOE circular, FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/1248 dated 07/10/2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name:

R.N. Singh Designation: ADO (BCP)

The Ardee School at Maharishi Ramana Marg, Sujan Singh Park, New Delhi-110023

exology MSCUL WY 3/4.