

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2018/SZ/ 618

Dated: 6/4/18

FIRE SAFETY CERTIFICATE

Certified that the **Modern School** located at Poorvi Marg, Vasant Vihar, New Delhi-110057 comprised of Ground plus three upper floors (01 block), Ground plus two upper floors (01 block) and Ground floor only (One auditorium), all blocks are interconnected, was issued Fire Safety Certificate by this department vide letter No. F.6/MS/DFS/School/2014/SZ/1633 Dated 23/12/2014. The school premises was re-inspected by officer concerned of this department on 15/03/2018 in presence of Sh. Ram Prakash (Admn) and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Educational**" Group-B, with effect from 6/4/2018 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 6/4/18 at New Delhi by


(Vipin Kental)
Chief Fire Officer

B.
o/c

Copy to: -

1. The Principal, Modern School, Poorvi Marg, Vasant Vihar, New Delhi-110057
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."


INSPECTION REPORT				
1	Name & Address of the Building	MODERN SCHOOL, POORVI MARG, VASANT VIHAR, NEW DELHI-110057		
2	Type of Occupancy	Educational Building "Group-B"		
3	Building Comprised of	G+3 & G+2 (interconnected) + Auditorium (GF only)		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/School/2014/SZ/1633 Dt. 23/12/2014		
6	Fire Safety Directives Letter No	F.6/DFS/MS/BP/93/435 Dated 12/03/1993 F.6/DFS/MS/BP/97/546 Dated 13/05/1997		
7	Date of Inspection	15-03-2018		
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)		
9	Name & Designation of Officers from the building side	Sh. Ram Prakash (Admin)		
10	Year of construction	1975, 2000		
11	Applicant letter No.	MSVV/17-18/341 Dated 28-02-2018		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Required	9 mtr	MR
	• Gate width	Required	3.7 mtr	MR
	• Width of internal road	N/A	N/A	N/A
2	Number, width, type & arrangement of exits			
	a) Number of Staircase			
	➤ Upper floors	Required	4 Nos + 1 ramp	MR
	➤ Basement floor	N/A	N/A	N/A
	b) Width of Staircase			
	➤ Upper floors	Old case	1.8, 1.25, 1.25, 1.06m + 1.35m ramp Audi- 1.70m & 1.80m	MR
	➤ Basement floor	N/A	N/A	N/A
	c) Protection of exits			
	➤ Fire check door	N/A	N/A	N/A
	➤ Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	Required	One	MR
	e) Width of corridor	1.25m	Provided	MR
	f) Door size (Exits in Auditorium)	Required	1.7m x 4 + 0.90 x 2 + 1.4 x 2	MR
3	Compartmentation.			
	• Fire check door.	N/A	N/A	N/A
	• Sealing of electrical shafts.	N/A	N/A	N/A
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4.	Smoke Management system.			
	• Basement	30 ACPH	N/A	N/A
	• Upper floors	12 ACPH	N/A	N/A
5.	Fire Extinguishers.			
	• Total numbers	Required	50 Nos	MR
	• Types	CO2 / ABC	ABC Type	MR
	• ISI Marking	ISI marked	Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor.	4+2 Nos in Audi	4+2 Nos in Audi	MR
	• Length of hose-reel hose.	30 m	Provided	MR
	• Nozzle Diameter	5 mm	Provided	MR

19.	Fire Control Room.			
	• Detector System Panel.	N/A	N/A	N/A
	• Flow Switch Panel.	N/A	N/A	N/A
	• PA system Panel.	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. The shortcomings communicated by this department vide letter dated 21/02/2018 found complied.


Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, the FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/1633 dated 23/12/2014, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.


 Signature of the Inspecting Officer
 Name: R.N. Singh
 Designation: ADO (BCP)


Modern School, Poorvi Marg, Vasant Vihar, New Delhi-110057

DO (SD)


19/3/18

~~DO (SD)~~
Dy. CPO/SZ

1150/cfo/sz
28/3-16/4.


19/3



Cfo sz

m.scell

F.T/07

U 28/3

F.T letter is put up for sign-off
02/4

cfo/sz

m.scell

U 5/4