GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2018/727

Dated: 18/04/20/8

FIRE SAFETY CERTIFICATE

Issued on 18 /04/2018 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. Shri Ranjit Samanta (Owner), Hotel Sun View International, 24B/9, WEA, Deshbandhu Gupta Road, Karol Bagh, New Delhi- 110005.

2. The Addl. C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.

3. The trained firefighting staffs should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of UBBL-16.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT Name & address of the building: M/s Hotel Sun View International, Plot No 24B/9, WEA, Karol Bagh, D.B.Gupta Road, New Delhi 2. Type of Occupancy : Lodging House 3. Type of Case : New case 4. Details of previous NOC : N/A 5. Fire Safety directives letter No : N/A 6. Date of inspection : 05.04.2018 7. Name of the Inspecting Officers: M.K. Chattopadhyay, Divisional Officer (South West) 8. Name and designation of officers from the building side : Sh. Ranjit Samanta, Owner/occupier 9. Year of Construction : 2016-17 10. Applicant's letter No. : nil dated 09.03.2018 The said guest house is comprised of basement, stilt, ground plus three upper floors. Minimum Standards on fire Requirement as S.No Remarks prevention and fire safety U/R 33 per UBBL/NBC Provided at site MR/NMR 1 Access to building Provided Road width 06 mts MR Gate width 4.5 mts Directly accessible MR Width of internal road N/A N/A N/A 2 Number, Width, Type & Arrangement of Exits a. Number of staircases 02-upto terrace level Upper Floors MR 02 01- upto first floors Basements 02 Provided(03) MR b. Width of staircases 1.50 mts, 1.0 mts - upto terrace 1.35 mts Upper Floors 1.50 mts -upto first floor MR 1.35 mts 1.55, 1.50, 1.20 mts Basements MR c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A e. No. of continuous staircases to 02 02 MR terrace 1.25 mts 1.44 mts MR g. Width of Corridor 1.35 mts h. Door Size Provided MR 3 Compartmentation. Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. Basements 30 a/c per hour Provided MR Natural ventilation Upper floors 12 a/c per hour MR 5 Fire Extinguishers

	Total numbers	12	Provided	MR	
	• Types	ABC type	Provided	MR	
	IS marking	ISI marked	Provided	MR	
6	First-Aid Hose Reels.	*			
	Total numbers on each floor	01	Provided	MR	
	 Length of hose reel hose 	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	• Type of detectors	N/A	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.	,	18		
	Basement	Required	Provided	MR	
	Upper Floor	Not Required	Provided	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants				
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.			1.0	
327	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House AccessTerrace level	N/A	N/A	N/A	
	• Terrace level > Discharge of pump			1	
THE REAL PROPERTY.	Discharge of pullip	900 I PM	Described) (D	

	> Head of the pump	30 mts	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	10,000 lts	Provided	MR		
.5	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

All the shortcomings issued by this department vide letter No. F.6/DFS/MS/GH/SZ/2018/161 dated 12.01.2018 have been complied with by the management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-

DFA is put up for approval & signature please

