

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEADQUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

NO F 6/DFS/MS/EH/2018/ 797

Dated: 23/09/18

FIRE SAFETY CERTIFICATE

Certified that the M/S Surahi (The Veg Kitchen & Bar) 30-31, Ground floor, Unity One Mall, CBD Ground Shahdara Delhi -110032 comprised of Ground + 01 upper floor, Eating House/restaurant at ground floor owned/occupied by Surahi (The Veg Kitchen & Bar) 30-31, Ground floor, Unity One Mall, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of Delhi Fire Service on 10/09/2016 in the presence is Mr. Krishna (Manger) and found that the said premises is fit for occupancy class **Assembly /Business** with effect from 23/09/18 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire service rule 2010,,printed below.

Issued 23/09/18 at New Delhi by.

Yours faithfully


(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

copy to:-

(1) Medical Officer of Health,
New Delhi Municipal Council,
Palika Kendra New Delhi.

(2) Sh. Nirmal Jain , M/S Surahi (The Veg Kitchen & Bar) 30 -31, Ground Floor,
Unity One Mall, CBD Geound Shahdara Delhi - 110032,

Condition:-

1. All the fire safety arrangement provided therein shall be maintained in good working conditions at all times.. All the means of escape shall be kept unobstructed /unlocked & remain available for speedy evacuation of occupants in case of an emergency.
 - 3.Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 4. The trained fire fighting staff should be available round the clock.
 5. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
 6. The fire safety certificate may not be treated in any case for regularization of unauthorized construction if any.
 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi fire service 2010. The form is available on www.dfs.delhigovt.nic.in.
 8. The owner / occupier shall apply for renewal of this fire safety certificated to the director in Form 'J' [sub rule (1) of rule 37] alongwith a copy of this certificate, six months prior to it expiry.
- issued on ----- at New Delhi by

INSPECTION REPORT

1. Name & address of the building : M/S Surahi (The Veg Kitchen & Bar) 30-31, Ground Floor, Unity One Mall, CBD Ground Shahdara Delhi - 110032.
2. Type of occupancy : Assembly.
3. Type of Case : New Case
4. Details of Previous NOC : N/A
5. Fire Safety directives No : N/A
6. Date of Inspection : 13.04.2018
7. Name of the Inspecting Officers: : Sh. Sunil Chawdhary Dy.CFO (NDZ)/ F. Brown (D.O East)
8. Name of the designation of Officer
from the building side : Mr. Krishna.
9. Year of Construction : 2005 - 2006.
10. Applicant's letter No : DHO/Shd.(S)/2018/476 Dated 05-04-2018.

S.No	Minimum Standards on fire prevention and fire safety U/R33	Requirement as Per NBC	Provided at Site	Remarks MR/NMR
1	Access to building	Mall		
	Road width	6 mtr.	6mtr.	MR
	Gate width	6 mtr.	6mtr.	MR
	Width of internal road	6 mtr.	6mtr.	MR
2	Number, Width, Type and Arrangement of Exits	Mall		
	a. Number of Staircases			
	Upper Floor(Gr & 01 floor)	01 No.	01 No.	MR
	Basement	N/A	N/A	N/A
	B. Width of Staircases	N/A	N/A	N/A
	Upper Floor	01 no.	01 no.	01 no.
	Basement	N/A	N/A	N/A
	c. Protection of exits	Required	Provided	MR
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	01	01	MR
	g. Width of Corridor	N/A	N/A	N/A
h. Door Size	Restaurant	1.5 mtr , 2 mtr	2mtr, 1.5 mtr	MR
3	Compartmentation.	Mall		
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire rating of shaft door	2 hrs.	2 hrs.	M/R
	Water curtain	N/A	N/A	N/A
	Fire Dampers	Required	Provided	MR
4	Smoke Management System.	Mall		
	Basement	N/A	N/A	N/A
	Upper floor	12 a/c per	Provided	MR

5. Fire Extinguisher		Restaurant		
Total numbers types IS marking		10 Nos.	12 Nos.	MR
		CO ₂ & ABC	CO ₂ & ABC	MR
		ISI marked	Provided	MR
6 First-aid-Hose Reels.		Restaurant		
Total numbers of each floor Length of hose reel hose Nozzle diameter		01 no.	Provided	MR
		30 m	30 m	MR
		5 mm	5 mm	MR
7 Automatic fire detection and alarming system.		Restaurant		
Type of detectors Location of main panel Location of repeater panel Alternate source of power Hooters's location		Heat/Smoke	Provided	MR
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public address System.	N/A	N/A	N/A
10 Automatic Sprinkler System.		Mall		
basement upper floor sprinkler above false ceiling		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
11 Internal Hydrants		Restaurant		
size of riser/down-comer Number of hydrants per floor Hose Box		150 mm	provided	MR
		01	Provided	MR
		01	Provided	MR
		01	Provided	M/R
12 Yard Hydrants.		Mall		
Total number of hydrants Hose Box		N/A	N/A	N/A
		N/A	N/A	N/A
13 Pumping Arrangements.		Mall		
1) Ground Level a) Discharge of main Pump b) Head of Main Pump c) Number of main pumps d) Jockey pump out put e) Jockey pump head f) Standby pump out put g) Standby pump Head h) Auto Starting /Manual stopping 2) Terrace Level a) Discharge of pump b) Head of the Pump c) Power supply d) Auto Starting of pump		Required	Provided	MR
		2280 LPM	2280 LPM	M/R
		60 Mtrs.	60 Mtrs.	M/R
		01 nos.	01 nos.	M/R
		450 LPM	450 LPM	M/R
		60 Mtrs.	60 Mtrs.	M/R
		2280 LPM	2280 LPM	M/R
		60 Mtrs.	60 Mtrs.	M/R
		Auto	Provided	M/R
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

14	Captive Water Storage for Fire Fighting.	Mall		
	1) Underground tank capacity	20,000ltr	20,000ltr	M/R
	a) Draw-off connection	Required	Provided	MR
	b) Fire service inlet	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	d) Overhead Tank capacity Restaurant	20,000 Liters	25,000 Liter	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Mall		
	a) Pressurization of Lift Shaft	Required	Provided	MR
	b) Pressurization of Lift lobby	Required	Provided	MR
	c) Communication in lift car	Required	Provided	MR
	d) Firemen's grounding switch	Required	Provided	MR
	e) Lift Signage	Required	Provided	MR
17	Standby power supply	Required	1000 KVA	MR
18	Refuge Area.	Mall		
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	Mall		
	Detector system panel	Required	Provided	MR
	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Batter backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. Keeping In view of the Substantial compliance of the compliance of the minimum standards on fire prevention and fire safety required under the Rules, grant of fire safety Certificate under rule 35 of the Delhi Fire Service Rule 2010/ Restaurant is at ground and Mezzanine floor recommended for FSC please.

Signature of the Inspecting Office
 Name Sunil Chawdhary
 Designation DY. CFO(NDZ)

Signature of the Inspecting Officer
 Name F. Brown
 Designation Div Officer

CFO/NDZ

F.T.M.

m. seel

20/4/18

F.T. letter is put up for