GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/School/2018/SZ/ Sog

Dated: 24/4/18

FIRE SAFETY CERTIFICATE

Certified that **Arpan Public School** located at J–11, Jaitpur Extn., Badarpur, New Delhi-110044, comprised of ground and one upper floor was issued FSC by this department vide letter No. F.6/DFS/MS/School/2014/SZ/188 dated 06/02/2014. The school premises was re-inspected by officer concern of this department on 06/04/2018 in the presence of Ms. Anu Lata (Principal) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. 262–362 dated 17-01-2005 issued by Director of Education, Govt. of NCT of Delhi and that the premises is fit for occupancy class '**Educational**' Group–B, (School) as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of the conditions mentioned below.

Issued on 94/4/18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

OIC

Copy to: -

1. The Manager, Arpan Public School, J-11, Jaitpur Extn, Badarpur, New Delhi-110044

2. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSPECTION REPORT					
1 1	Jame & Address of the Building	ARPAN PUBLIC SCHOOL, J-11, JAITPUR EXTN,				
	taine or rudiess of the Building		W DELHI-110044			
2 T	ype of Occupancy	Educational "Group-B" (School)				
	Building Comprised of	Ground + 01 uppe				
4 Type of Case	Renewal					
	Details of Previous NOC		ool/2014/SZ/188 Dated	106-02-2014		
	ire Safety Directives Letter No		. 262-362 dated 17-01			
	Date of Inspection	06-04-2018				
	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
	Name & Designation of	Ms. Anu Lata (Principal)				
	Officers from the building side					
	ear of construction	2010				
11 A	Applicant letter No.	Nil dated 16.03.20	018			
	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
8	nd Fire Safety U/R 33	requirement		MR/NMF		
1 A	access to Building,					
	 Road width 	6 mtr	Provided	MR		
	 Gate width 	N/A	N/A	N/A		
Carrie	 Width of internal road 	N/A	N/A	N/A		
2 N	lumber, width, type & arrangement of exits					
8				7		
	 Upper floors 	Required	02 Nos	MR		
	 Basement floor 	N/A	N/A	N/A		
b) Width of Staircase					
	Upper floors	1.5m / 0.75	0.91m & 0.90m	MR		
- Complete C	Basement floor	N/A	N/A	N/A		
e						
	Fire check door	N/A	N/A	N/A		
and the same of th		N/A	N/A	N/A		
	Pressurization					
d		Required	One	MR		
e		N/A	N/A	N/A		
1		N/A	N/A	N/A		
3 (Compartmentation.	DY/A I	27/4	DT/A		
	Fire check door.	N/A	N/A	N/A N/A		
	Sealing of electrical shafts.	N/A	N/A N/A	N/A N/A		
	Fire rating of shaft door.	N/A N/A	N/A N/A	N/A		
	Water curtain					
	• Fire dampers.	NA	NA	NA		
4. S	Smoke Management system.	20 A CPUI	NI/A:	N/A		
all and a second	Basement	30 ACPH	N/A			
	Upper floors	12 ACPH	N/A	N/A		
5. F	Fire Extinguishers.					
epad-maniferance	 Total numbers 	Required	04 Nos	MR		
Bagillonna-Adapte	• Types	ABC / CO2	ABC type	MR		
panyonana	ISI Marking	Required	Provided	MR		
6. F	irst Aid Hose Reels.	, ,				
U. E	Total numbers on each floor.	N/A	One	N/A		
pp-daymatak		N/A	30m	N/A		
	• Length of hose-reel hose.					
	Nozzle Diameter Amor Public School I 11 Icitarus F	N/A	5mm	N/A		

Arpan Public School, J-11, Jaitpur Extension, Badarpur, New Delhi-110044

7 A	utomatic fire detection & alarming system	27/4	NI/A	N/A
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A N/A
	Location of Repeater Panel	N/A	N/A	N/A N/A
	Alternate source of power	N/A	N/A	
No.	Hooter's location	N/A	N/A	N/A
8. N	MOEFA	N/A	N/A	N/A
9. F	Public Address System	N/A	N/A	N/A
10. A	Automatic Sprinkler System	77//	DT/A	N/A
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	INIA
11. I	nternal Hydrants.	37/4	NT/A	N/A
The state of the s	Size of Riser/Down-comer	N/A	N/A	N/A
Adjustini	Number of Hydrant per floor	N/A	N/A	N/A
- delication of the second	Hose box.	N/A	N/A	IN/A
12.	Yard Hydrants.	3714	DT/A	N/A
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.			
	Ground Level	25/4	27/4	N/A
	Discharge of main pump.	N/A	N/A	N/A
-	Head of main pump.	N/A	N/A	N/A N/A
Booksteen	Number of main pumps.	N/A	N/A	N/A
La production of the Control of the	> Jockey Pump output.	N/A	N/A N/A	N/A
	> Jockey Pump head.	N/A	N/A	N/A
	> Standby Pump output.	N/A	N/A	N/A
	Standby pump head.Auto Starting/Manual Stopping.	N/A	N/A	N/A
		N/A	IN/A	1 IN/A
	Terrace Level	N/A	N/A	N/A
es established a	Discharge of pump.	N/A N/A	N/A	N/A
	> Head of pump.	N/A N/A	N/A	N/A
	Power supply.Auto starting of pump.	N/A	N/A	N/A
		IN/A	14/28	1 27/22
14.	Captive water storage for Fire Fighting.	N/A	N/A	N/A
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
The state of the s	> Fire Service Inlet.	N/A	N/A	N/A
	> Access to tank.	N/A	N/A	N/A
And a	Overhead tank capacity.	N/A	1,000 ltrs	N/A
15.	Exit Signage.	N/A	Provided	N/A
	Provisions of Lifts.		*	
10.	Pressurization of lift shaft.	N/A	N/A	N/A
	n : .: CliQ1-1-1-	N/A	N/A	N/A
		N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	 Fireman's switch. 			
	Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	N/A	N/A	N/A
18.	Refuge Area			
	Total area	N/A	N/A	N/A
		N/A	N/A	N/A

Arpan Public School, J-11, Jaitpur Extension, Badarpur, New Delhi-110044

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any.	Required	ABC type fire extinguisher provided near elect, panel	MR

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under DOE circular, FSC issued vide letter No. F.6/DFS/MS/School/2014/SZ/188 dated 06/02/2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name:

R.N. Singh Designation: ADO (BCP)

Arpan Public School, J-11, Jaitpur Extension, Badarpur, New Delhi-110044

DO (8D)

M:SCEU FT/M.

ET leffer is Intul for sign. bla. fung

CRO/Sof

M:SCEU WEJY.