GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6/DFS/MS/Petrol/2018/SZ/ 869

Dated: 27/4/18

FIRE SAFETY CERTIFICATE

Certified that M/s Bansiwal Service Station (Retail outlet of H.P.C.L. Petroleum's class A, B) located at San Martin Marg, Chanakya Puri, New Delhi-110022, comprised of Ground plus mezzanine floor was issued FSC by this department vide letter No. F.6/DFS/MS/Petl/2015/SZ/70 dated 14/01/2015. The premises was re-inspected by the officer concerned of this department on 06/03/2018 in presence of Sh. Inder Mohan Bansiwal (owner) and observed installed CNG dispensing units and that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Mixed" (Petrol Pump, CNG and Service Station) as above with effect from date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 2 74/18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

1. The Medical Officer (Health), N.D.M.C, Palika Kendra, New Delhi- 110001

2. The Proprietor, M/s Bansiwal Service Station, San Martin Marg, Chanakya Puri, N.D-21

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

| | INSPECTIO | N REPORT | - | | | |
|--------|---|---|--------------------------|-----------|--|--|
| 1 | Name & Address of the Building M/s BANSIWAL SERVICE STATION (Retail outlet | | | | | |
| | | | oleum's Class A, B & C | | | |
| 1 | | Martin Marg, Chanakya Puri, New Delhi- 110021 | | | | |
| 2 | Type of Occupancy | | cy (Petrol Pump, CNG & | | | |
| 3 | Building Comprised of | Ground plus mezzanine floor. | | | | |
| 4 | Type of Case | Renewal | | | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/Pe | trol/2015/SZ/70 dated 1 | 4-01-2015 | | |
| 6 | Fire Safety Directives Letter No | F5 (3A)/DFS/B | P/99/375 Dated 24-08-9 | 9 | | |
| 7 | Date of Inspection | 06-03-2018 | | | | |
| 8 | Name of the Inspecting Officers | R.N. Singh, ADO (BCP) | | | | |
| 9 | Name & Designation of | Sh. Mohan Bansiwal (owner) | | | | |
| | Officers from the building side | | | | | |
| 10 | Year of construction | 1999 | | | | |
| 11 | Applicant letter No. | No. Nil dated 0 | No. Nil dated 08-02-2018 | | | |
| S. No. | Minimum standards on Fire Prevention | Old NOC | Provided at Site | Remarks | | |
| | and Fire Safety U/R 33 | requirement | | MR/NMR | | |
| 1 | Access to Building. | | | в. | | |
| | Road width | 6 mtr | 12 mtr | MR | | |
| | Gate width | N/A | N/A | N/A | | |
| | Width of internal road | N/A | N/A | N/A | | |
| 2 | Number, width, type & arrangement of exits. | | | | | |
| | a. Number of Staircase | | | | | |
| 1 | > Upper floors. | One | One | MR | | |
| | Basement. | N/A | N/A | N/A | | |
| | b. Width of Staircase | | | | | |
| 78 | > Upper floors | 1.2m | 1.2m | MR | | |
| | > Basement | N/A | N/A | N/A | | |
| | c. Protection of exits | | | | | |
| | > Fire check door | N/A | N/A | N/A | | |
| - 1 | > Pressurization | N/A | N/A | N/A | | |
| | d. No. of continuous staircase to terrace | N/A | N/A | N/A | | |
| | e. Width of corridor | N/A | N/A | N/A | | |
| | f. Door size | 1m | 1m | MR | | |
| 3 | Compartmentation. | | | | | |
| | Fire check door. | N/A | N/A | N/A | | |
| | Sealing of electrical shafts. | N/A | N/A | N/A | | |
| | • Fire rating of shaft door. | N/A | N/A | N/A | | |
| | Water curtain | N/A | N/A | N/A | | |
| | • Fire dampers. | N/A | N/A | N/A | | |
| 4. | Smoke Management system. | | | | | |
| 7. | Basement | N/A | N/A | N/A | | |
| | Upper floors | N/A | N/A | N/A | | |
| 5. | Fire Extinguishers. | | | | | |
| ٥. | Total numbers | 16 No's | 22 No's | MR | | |
| | to to the second second second | | DCP (75kg), DCP(10kg), | | | |
| | • Types | CO2, DCP, ABC | CO2 & ABC | MR | | |
| | ISI Marking | ISI Marked | Provided | MR | | |
| 6. | First Aid Hose Reels. | | | | | |
| | Total numbers on each floor. | N/A | N/A | N/A | | |
| | Length of hose-reel hose. | N/A | N/A | N/A | | |
| | Nozzle Diameter | N/A | N/A | N/A | | |

M/s Bansiwal Service Station, San Martin Marg, Chanakya Puri, New Delhi

| 7 | Automatic fire detection & alarming system. | | | |
|------------|---|-------------|-----------------------------|----------|
| | Type of detectors | Gas & flame | Provided in compressor | MR |
| | Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooter's location | Required | Control room | MR |
| 8. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | 14/71 | 14/11 | 11/// |
| | Basement | N/A | N/A | N/A |
| | Upper floors | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | | 1771 | 14/11 |
| | Size of Riser/Down-comer | N/A | N/A | N/A |
| | Number of Hydrant per floor | N/A | N/A | N/A |
| | Hose box. | N/A | N/A | N/A |
| 12. | Yard Hydrants. | 14/21 | IVA | IN/A |
| 1. Int o | Total number of hydrants. | N/A | N/A | NI/A |
| | Hose box. | N/A N/A | N/A N/A | N/A |
| 13. | | IN/A | N/A | N/A |
| 13. | Pumping arrangements. • Ground Level | | | |
| | | NI/A | 77/4 | 27/ |
| | Discharge of main pump. | N/A | N/A | N/A |
| | Head of main pump. | N/A | N/A | N/A |
| | Number of main pumps.Jockey Pump output. | N/A | N/A | N/A |
| | Jockey Pump bad. | N/A | N/A | N/A |
| | Standby Pump output. | N/A | N/A | N/A |
| | Standby Pump head. | N/A | N/A | N/A |
| | Auto Starting / Manual Stopping. | N/A | N/A | N/A |
| | Pump house access. | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | Terrace Level | | | |
| | Discharge of pump. | N/A | N/A | N/A |
| | > Head of pump. | N/A | N/A | N/A |
| | Power supply. | N/A | N/A | N/A |
| | > Auto starting of pump. | N/A | N/A | N/A |
| 14. | Captive water storage for Fire Fighting. | | - | |
| | Underground tank capacity. Draw-off connection | N/A | N/A | N/A |
| | Draw-off connection.Fire Service Inlet. | N/A | N/A | N/A |
| | Access to tank. | N/A | N/A | N/A |
| | Overhead tank capacity. | N/A | N/A | N/A |
| 15. | | N/A | N/A | N/A |
| 16. | Exit Signage/ No Smoking Signage Provision of Lifts. | Required | Provided in Hindi & English | MR |
| 10. | Pressurization of lift shaft. | NI/A | | 27/4 |
| | Pressurization of lift shaft. Pressurization of lift lobby. | N/A | N/A | N/A |
| | Communication in lift car. | N/A | N/A | N/A |
| | • Fireman's switch. | N/A | N/A | N/A |
| | Lift signage. | N/A | N/A | N/A |
| 17 | | N/A | N/A | N/A |
| 17. 18. | Standby Power Supply | Required | Provided (DG Set) | MR |
| 10. | Refuge Area | 21/4 | , | N 7 / 1: |
| | Total area | N/A | N/A | N/A |
| | Location | N/A | N/A | N/A |

M/s Bansiwal Service Station, San Martin Marg, Chanakya Puri, New Delhi

| 19. | Fire Control Room. | | | |
|-----|--|-----|-----|-----|
| | Detector system panel. | N/A | N/A | N/A |
| | Flow switch panel. | N/A | N/A | N/A |
| | PA system panel. | N/A | N/A | N/A |
| | Battery backup. | N/A | N/A | N/A |
| | Building floor plan. | N/A | N/A | N/A |
| 20. | Special Fire Protection System for the | N/A | N/A | N/A |
| | Protection of special Risk, if any. | No. | | |

The fire protection system such as fire extinguishers of different type and capacity, fire buckets filled with loose dry sand & water provided at suitable places in the retail outlet area were checked and found functional at the time of inspection. "No Smoking" sign boards were found displayed both in Hindi & English at conspicuous places. No loose electrical wiring was seen in the premises.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/Petl./2015/SZ/70 dated 14.01.2015, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: R.N. Singh Designation: ADO (BCP)

M/s Bansiwal Service Station, San Martin Marg, Chanakya Puri, New Delhi

DO (SD)

20/3/18

gel spepen the correction in craftancy carried out by ADOJBCP.

dy exceptatabant Pup Polso

22 3-78 B

Was for

R May