

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2018/SZ/ 766

Dated: 20/4/18

FIRE SAFETY CERTIFICATE

Certified that New Sangam Convent School located at G-1312, Veer Bazar Road, Sangam Vihar, New Delhi-110080 comprised of Ground floor was issued NOC by this department vide letter No. F.6/DFS/MS/2006/2027 dated 10/08/2006. The premises was re-inspected by officer concerned of this department on 07/04/2018 in the presence of Mr. Anil Rastogi (Manager) of the school and observed that one upper floor have been added in the exiting building. The school building is now comprised of ground plus one upper floor. The school building have complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education, Govt. of NCT of Delhi and that the school building is fit for occupancy class 'Educational' Group-B (School), as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of the conditions mentioned below.

Issued on 20/4/18 at New Delhi by

VK
20/4
(Vipin Kental)
Chief Fire Officer

Rojc

Copy to: -

1. The Manager, New Sangam Convent School, G-1312, Sangam Vihar, New Delhi-110080.
2. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.


Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

| INSPECTION REPORT | | | | |
|-------------------|---|--|------------------|----------------|
| 1 | Name & Address of the Building | NEW SANGAM CONVENT SCHOOL, G-1312, Veer Bazar Road, Sangam Vihar, New Delhi-110080 | | |
| 2 | Type of Occupancy | Educational 'Group-B' (School) | | |
| 3 | Building Comprised of | Ground + 01 upper floor. | | |
| 4 | Type of Case | Renewal & addition of first floor | | |
| 5 | Details of Previous NOC | F.6/DFS/MS/2006/2027 dated 10-08-2006 (GF only) | | |
| 6 | Fire Safety Directives Letter No | F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 | | |
| 7 | Date of Inspection | 07-04-2018 | | |
| 8 | Name of the Inspecting Officers | R.N. Singh, ADO (BCP) | | |
| 9 | Name & Designation of Officers from the building side | Mr. Anil Rastogi (Manager) | | |
| 10 | Year of construction | 2004 & 2010 | | |
| 11 | Applicant letter No. | Nil Dated Nil, ODD No. 3116 Dated 28.02.2018 | | |
| S. No | Minimum standards on Fire Prevention and Fire Safety U/R 33 | DOE Circular requirement | Provided at Site | Remarks MR/NMR |
| 1 | Access to Building. | | | |
| | • Road width | Accessible | 6 mtr | MR |
| | • Gate width | N/A | N/A | N/A |
| | • Width of internal road | N/A | N/A | N/A |
| 2 | Number, width, type & arrangement of exits | | | |
| | a) Number of Staircase | | | |
| | ➤ Upper floors | One | 2 Nos | MR |
| | ➤ Basement floor | N/A | N/A | N/A |
| | b) Width of Staircase | | | |
| | ➤ Upper floors | 1.5m / 0.75m | 1.5m & 1.45m | MR |
| | ➤ Basement floor | N/A | N/A | N/A |
| | c) Protection of exits | | | |
| | ➤ Fire check door | N/A | N/A | N/A |
| | ➤ Pressurization | N/A | N/A | N/A |
| | d) No. of continuous staircase to terrace | N/A | N/A | N/A |
| | a) Width of corridor | N/A | N/A | N/A |
| | f. Door size | N/A | N/A | N/A |
| 3 | Compartmentation. | | | |
| | • Fire check door. | N/A | N/A | N/A |
| | • Sealing of electrical shafts. | N/A | N/A | N/A |
| | • Fire rating of shaft door. | N/A | N/A | N/A |
| | • Water curtain | N/A | N/A | N/A |
| | • Fire dampers. | N/A | N/A | N/A |
| 4. | Smoke Management system. | | | |
| | • Basement | N/A | N/A | N/A |
| | • Upper floors | N/A | N/A | N/A |
| 5. | Fire Extinguishers. | | | |
| | • Total numbers | 4 No's | 5 No's | MR |
| | • Types | ABC / Co2 | ABC-5 | MR |
| | • ISI Marking | ISI Marked | Provided | MR |
| 6. | First aid Hose-reels. | | | |
| | • Total numbers on each floor. | N/A | N/A | N/A |
| | • Length of hose-reel hose. | N/A | N/A | N/A |
| | • Nozzle Diameter | N/A | N/A | N/A |

New Sangam Convent School, G-1312, Veer Bazar Road, Sangam Vihar, New Delhi

| | | | | |
|------------|--|-----|-----|-----|
| 7 | Automatic fire detection & alarming system. | | | |
| | • Type of detectors | N/A | N/A | N/A |
| | • Location of Main Panel | N/A | N/A | N/A |
| | • Location of Repeater Panel | N/A | N/A | N/A |
| | • Alternate source of power | N/A | N/A | N/A |
| | • Hooter's location | N/A | N/A | N/A |
| 8. | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | | | |
| | • Basement. | N/A | N/A | N/A |
| | • Upper floors | N/A | N/A | N/A |
| | • Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants. | | | |
| | • Size of Riser/Down-comer | N/A | N/A | N/A |
| | • Number of Hydrant per floor | N/A | N/A | N/A |
| | • Hose box. | N/A | N/A | N/A |
| 12. | Yard Hydrants. | | | |
| | • Total number of hydrants. | N/A | N/A | N/A |
| | • Hose box. | N/A | N/A | N/A |
| 13. | Pumping arrangements. | | | |
| | • Ground Level | | | |
| | ➤ Discharge of main pump. | N/A | N/A | N/A |
| | ➤ Head of main pump. | N/A | N/A | N/A |
| | ➤ Number of main pumps. | N/A | N/A | N/A |
| | ➤ Jockey Pump output. | N/A | N/A | N/A |
| | ➤ Jockey Pump head. | N/A | N/A | N/A |
| | ➤ Standby Pump output. | N/A | N/A | N/A |
| | ➤ Standby Pump head. | N/A | N/A | N/A |
| | ➤ Auto Starting / Manual Stopping. | N/A | N/A | N/A |
| | ➤ Pump house access. | N/A | N/A | N/A |
| | • Terrace Level | | | |
| | ➤ Discharge of pump. | N/A | N/A | N/A |
| | ➤ Head of pump. | N/A | N/A | N/A |
| | ➤ Power supply. | N/A | N/A | N/A |
| | ➤ Auto starting of pump. | N/A | N/A | N/A |
| 14. | Captive water storage for Fire Fighting. | | | |
| | • Underground tank capacity. | N/A | N/A | N/A |
| | ➤ Draw-off connection. | N/A | N/A | N/A |
| | ➤ Fire Service Inlet. | N/A | N/A | N/A |
| | ➤ Access to tank. | N/A | N/A | N/A |
| | • Overhead tank capacity. | N/A | N/A | N/A |
| 15. | Exit Signage. | N/A | N/A | N/A |
| 16. | Provision of Lifts. | | | |
| | • Pressurization of lift shaft. | N/A | N/A | N/A |
| | • Pressurization of lift lobby. | N/A | N/A | N/A |
| | • Communication in lift car. | N/A | N/A | N/A |
| | • Fireman's switch. | N/A | N/A | N/A |
| | • Lift signage. | N/A | N/A | N/A |
| 17 | Standby Power Supply | N/A | N/A | N/A |
| 18. | Refuge Area | | | |
| | • Total area | N/A | N/A | N/A |
| | • Location | N/A | N/A | N/A |

| | | | | |
|--|---|-----|-----|-----|
| 19. | Fire Control Room. | N/A | N/A | N/A |
| | • Detector System Panel. | N/A | N/A | N/A |
| | • Flow Switch Panel. | N/A | N/A | N/A |
| | • PA system Panel. | N/A | N/A | N/A |
| | • Battery backup | N/A | N/A | N/A |
| | • Building floor plan | N/A | N/A | N/A |
| 20. | Special Fire Protection System for the Protection of special Risk, if any. | N/A | N/A | N/A |
| <p>The school building was comprised of ground floor only when the last NOC was issued. The school management has added one more floor in the existing building. Thus, building comprises ground plus one upper floor. The school management has submitted a certificate regarding construction/addition of first floor and no of class rooms placed at C-9.</p> <p>The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.</p> <p>Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, NOC issued vide letter No. F.6/DFS/MS/2006/2027 dated 10/08/2006, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.</p> <p>Accordingly, DFA is put up for approval and signature please.</p> <div style="text-align: right;">  Signature of the Inspecting Officer Name: R.N. Singh Designation: ADO (BCP) </div> | | | | |

New Sangam Convent School, G-1312, Veer Bazar Road, Sangam Vihar, New Delhi

DO (SD)

Anilash
12/4/18

dy. CFO (S2)

1237/CAO S2
18/4/2014.

deaf
13/4 FTB.

CFO (S2)
M. S. Cell 18/4

FT letter is put up for signature
19/4

CFO (S2)
M. S. Cell 20/4.

