## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/EH/2018/SZ/ 939

1

Dated: 7/5/18

## FIRE SAFETY CERTIFICATE

Certified that the M/s Shri Durga Enterprises, J-2/3, GF, FF, SF & TF, Rajouri Garden, New Delhi-110027 comprised of basement, ground floor plus two upper floors but the restaurant is running at ground floor plus two upper floors only, was issued FSC by this department vide letter no. F.6/DFS/MS/EH/2014/SZ/1196 dated 05.09.2014 owned/occupied by M/s Shri Durga Enterprises was re-inspected by the officers concerned of this department on 09.04.2018 in the presence of Sh. Ajay Makhija (Owner) and found that Management of M/s Shri Durga Enterprises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Ground Floor plus two upper floors Only) is fit for occupancy class Group-D "Assembly Building" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on. 7/5/2 of 3 at New Delhi.

Copy to:-

The Manager,
 M/s Shri Durga Enterprises, J-2/3,
 GF, FF, SF & TF, Rajouri Garden, New Delhi-110027

2. The Dy. Health Officer, S.D.M.C, Public Health Department, West Zone, Vishal Enclave, Rajouri Garden, New Delhi-110027 (VIPIN KENTAL) CHIEF FIRE OFFICER

ON C Son 19

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

		INSPECTION						
	1. N	Name & address of the building: M/s Shri Du New Delh	irga Enterprises, J-2/	3, GF, FF, SF & 7	ΓF, Rajouri Garden,			
	2. T	The second secon	Assembly Building)					
	3. T	ype of Case : Renewal						
			MS/EH/2014/SZ/119	6 dated 05.09.201	4			
		ire Safety directives letter No : N/A Pate of inspection : 09.04.2013	Q					
		The state of the s	. Chattopadhyay & A	A.D.O. Sandeep D	uggal			
	8. Name and designation of officers							
			Makhija (Owner)					
		Tear of Construction : Before 20 pplicant's letter No. : Nil dated						
S.		pplicant's letter No. : Nil dated um Standards on fire prevention and fire	Requirement as	Provided at	Remarks			
No.		U/R 33	per FSC dt. 05.09.2014	site	MR/NMR			
1.	Access	to building						
	•	Road width	Accessible (09 mtrs)	12 mtrs	MR			
	•	Gate width	4.5 mtrs N/A	Directly accessible from road	MR			
	•	Width of internal road	IN/A	N/A	N/A			
2.	Number, Width, Type & Arrangement of Exits							
i a	a. Nur	nber of staircases	20.25	20.37				
	•	Upper Floors Basements	02 No.'s	02 No.'s	MR			
	•	Dasellients	02 No.'s	02 No.'s	MR			
	b. Wid	th of staircases	105 . 0.01	107.0.100	) (D 1 ' - 11			
	• •	Upper Floor	1.25 mtrs & 01 mtrs	125 & 102 cms	MR, being old case			
	•	Basements	1.25 mtrs & 01 mtrs	125 & 102 cms	MR, being old case			
	c. Prot	ection of exits		×				
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization	N/A	N/A	N/A			
	d. No	of continuous staircases to						
	20000-004	race	Required	One	MR			
	e. Wi	dth of Corridor	1.5 mtrs	Opening in hall	MR			
	f. Do	or Size	02 Exits	Provided	MR			
3.	Comp	artmentation		s s				
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System							
	•	Basements	N/A	N/A	N/A			
	•	Upper floors	Required	Provided	MR			
5.	Fire Extinguishers							
	•	Total numbers	02 No.'s/floor	Provided	MR			
		Types	ABC/ CO <sub>2</sub>	Provided	MR			
	•	IS marking	ISI marked	ISI marked	MR			
6.	First-	Aid Hose Reels	151 marked					
	•	Total numbers on ground floor	One	Provided	MR			
		Length of hose reel hose	30 mtrs	Provided	MR			
		Nozzle diameter	5 mm	Provided	MR			

1.	Type of detectors	Smoke & Heat	Provided	MR
	Location of Main Panel	Required	Ground floor	MR
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A
	<ul> <li>Alternate source of power</li> </ul>	Required	Provided	MR
	<ul> <li>Hooters' Location</li> </ul>	Required	Near exit	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			100
	Basement	Required	Provided	MR
	<ul> <li>Ground Floor &amp; Upper floor</li> </ul>	Required	Provided	MR
-	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants	100	D '1 1	MD
	Size of riser/down-comer	100 mm	Provided Provided	MR MR
	<ul> <li>Number of hydrants</li> </ul>	One	Provided	MR
	Hose Box	One	Provided	IVIIX
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements		14	
	Ground Level			
	<ul><li>Discharge of main Pump</li></ul>	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	100		N/A
	> Standby Pump out put	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A
	> Auto Starting/Manual Stopping	N/A	N/A	N/A
	Titto Starting Manager 200 pp. 11-6	N/A	N/A	N/A
	➤ Pump House Access	N/A	N/A	N/A
	Terrace level		1	
	> Discharge of pump	450 LPM	Provided	MR
	> Head of the pump	& 180 LPM	7 11 1	) (D
	> Power Supply	40 mtrs	Provided	MR
	Auto Starting of pump	Required	Provided	MR
		Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	5000 ltrs	10,000 ltrs provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			C CONTROL OF THE CONT
100	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	Required	Provided	MR
=	Fireman's Grounding Switch	Required	Provided	MR
	Lift Signage	Required	Provided	MR
			Provided	MR
17.	Standby power supply	Required	Provided	IVIIX
18.	Refuge Area.		37/4	DI/A
	> Total Area	N/A	N/A	N/A

19.	Fire C	ontrol Room			
	•	Detector System Panel Flow Switch Panel	N/A	N/A	N/A
	•	PA System Panel	N/A	N/A	N/A
	•	Battery backup	N/A	N/A	N/A
	•	Building Floor Plans	N/A	N/A	N/A
			N/A	N/A	N/A
20.	Special special	Fire Protection System for Protection of Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings pointed out by this department vide letter no. F.6/DFS/MS/EH/2018/SZ/1219 dated 23.03.2018 has been complied.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/EH/2014/SZ/1196 dated 05.09.2014 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per the undertaking given by the Proprietor the restaurant is running at ground floor, first floor and second floor only. Basement is closed by gypsum board and lift is not operating in the basement and third floor is being used as office. Earlier FSC was issued in & style of Maya Tandoori Restaurant F.6/DFS/MS/EH/2014/SZ/1196 dated 05.09.2014.

Signature of Inspecting Officer Name: - M.K. Chattopadhyay

Designation:- Divisional Officer

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

75/DOCSW)

Dy. C.F.O.(South Zone)

F.T letter is put up for signature please.