GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax No. 011-23412593, Ph. 011-23412225

No. F.6 DFS/MS/School/2018/SZ/ 928

Dated:/05/18

FIRE SAFETY CERTIFICATE

Certified that **Sarvodaya Co-Ed. Vidyalaya**, Masjid Moth, South Ex-II, New Delhi-110049 comprised of Ground + three upper floors owned/occupied by Directorate of Education was issued FSC by this department vide letter No. F.6/DFS/MS/2015/SZ/61 dated 26/05/2015. The school premises was re-inspected by officer concerned of this department on 04/04/2018 in presence of Dr. Santhosh Kumar N (HOS) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "**Educational**" Group-B, as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of the conditions mentioned below.

Issued on 64/05/18 at New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to: -

0

- 1. The Principal, Sarvodaya Co-Ed. Vidyalaya, Masjid Moth, South Ex-II, New Delhi-110049
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept unlocked and free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECTION	ON REPORT				
1	Name & Address of the Building	SAVODAYA CO-ED. VIDYALAYA, MASJID MOTH,				
		SOUTH EX-II, NEW DELHI-110049 (ID- 1925246)				
2	Type of Occupancy	Educational 'Group-B' (School)				
3	Building Comprised of	Ground + 03 uppe	er floors.			
4	Type of Case	Renewal				
5	Details of Previous NOC	F.6/DFS/MS/2015	5/SZ/61 dated 12-01-20)15		
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	04-04-2018				
8	Name of the Inspecting Officers	R.N. Singh, ADO (BCP)				
9	Name & Designation of	Dr. Santosh Kumar N (HOS)				
	Officers from the building side	1.000				
10	Year of construction	1985				
11	Applicant letter No.	523 dated 13.03.2		-		
S. No	Minimum standards on Fire Prevention	Old NOC	Provided at Site	Remarks		
	and Fire Safety U/R 33	requirement		MR/NMF		
1	Access to Building.	C4	Duncidad	MR		
	Road width	6 mtr N/A	Provided N/A	N/A		
	Gate width			N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, width, type & arrangement of exits					
	a) Number of Staircase	Demind	02 Nos	MR		
	> Upper floors	Required				
	> Basement floor	N/A	N/A	N/A		
	b) Width of Staircase					
	Upper floors	1.5m	1.40 mtr each	MR		
	Basement floor	N/A	N/A	N/A		
	c) Protection of exits					
	> Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	N/A		
	d) No. of continuous staircase to terrace	One	Provided	MR		
	e) Width of corridor	1.5m	Provided	MR		
	1) Door size	1m	Provided	MR		
3	Compartmentation.		the second secon	10		
	Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	N/A	N/A	N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.					
	Basement	30 ACPH	N/A	N/A		
	Upper floors	12 ACPH	N/A	N/A		
5.	Fire Extinguishers.					
W4	Total numbers	16 Nos	17 Nos	MR		
		CO2 / ABC	ABC & CO2 type	MR		
	- 7 P - 5		Provided Provided	MR		
	ISI Marking	Required	riovided	IVIK		
6.	First Aid Hose Reels.	900 N	D *1 1	1.00		
	Total numbers on each floor.	02 Nos	Provided	MR		
	 Length of hose-reel hose. 	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		

Sarvodaya Co-Ed. Vidyalaya, Masjid Moth, South Ex-II, New Delhi-110049

7 Aut	omatic fire detection & alarming system			
and the same of th	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8. MO	DEFA	N/A	N/A	N/A
9. Put	olic Address System	N/A	N/A	N/A
lo. Aut	tomatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11. Inte	ernal Hydrants.			
	Size of Riser/Down-comer	N/A	100mm	N/A
	Number of Hydrant per floor	N/A	02 Nos	N/A
and the same	Hose box.	N/A	02 Nos	N/A
12. Yai	rd Hydrants.	AND THE RESIDENCE OF A STREET OF THE PARTY O		
	Total number of hydrants.	N/A	N/A	N/A
Business control	Hose box.	N/A	N/A	N/A
12 P		1 1/1 1		
13. Pui	mping arrangements.			
-	Ground Level Discharge of main nump	N/A	N/A	N/A
	Discharge of main pump.	N/A	N/A	N/A
	Head of main pump.Number of main pumps.	N/A	N/A	N/A
	Number of main pumps.Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby rump bead.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
-		IN/A	INIA	14/74
		450 LPM	450 LPM (two)	MR
a de la companya de l	Discharge of pump.	430 LFM	40m each	MR
	Head of pump.Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14 0		Required	FIOAIGG	IVIIV
14. Ca	ptive water storage for Fire Fighting.	N/A	N/A	N/A
Total Control of the	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A	N/A	N/A
lagiospilitoria	> Access to tank.	N/A	N/A	N/A
ingle-reproduction of	Overhead tank capacity.	10,000 Ltr	Provided	MR
15. Ex		Required	Provided	MR
	it Signage. ovisions of Lifts.	required	11011000	1 17114
10. FM	Pressurization of lift shaft.	N/A	N/A	N/A
- Parameter - Para	 Pressurization of lift shart. Pressurization of lift lobby. 	N/A	N/A	N/A
Officerological	Communication in lift car.	N/A	N/A	N/A
Approximates	Fireman's switch.	N/A	N/A	N/A
The state of the s		N/A	N/A	N/A
18 0	Lift signage.	31/4	N/A	N/A
THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME	andby Power Supply	N/A 🤫	IN/A	17/7
18. Re	fuge Area	N/A	N/A	N/A
	Total area			
	Location Sarvodaya Co-Ed, Vidyalaya, Masiid	N/A	N/A	N/A

Sarvodaya Co-Ed. Vidyalaya, Masjid Moth, South Ex-II, New Delhi-110049

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/2015/SZ/61 dated 12/01/2015, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

R.N. Singh Name: Designation: ADO (BCP)

Sarvodaya Co-Ed. Vidyalaya, Masjid Moth, South Ex-II, New Delhi-110049

DO (8D

1272/CAS2

0

CFO 874 MSQUU 23/4.

FF. le flow is hut up for Sign. Pole. Jung.

CFO 874 MSQUU VE Jy.