

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110001

No. F6/DFS/MS/EH/NDZ/2018/964

Dated: 9/5/18

FIRE SAFETY CERTIFICATE

Certified that the M/S MC Donald Family Restaurant at Shop No. 7,8,9, Aggarwal Fun City Mall, Plot No.29 & 31 ,East CBD Shahdara, Delhi-32, building comprised of Basement ground plus two upper floors. The restaurant running on ground floor only owned / occupied by MC Donald India Connaught Plaza Restaurant Pvt Ltd, was granted FSC by this department vide letter No. F6/DFS/MS/EH/2015/639 dated 29/04/2015. The building was re-inspected by the officer concerned of this department on 20/04/2018 in the presence of Sh. Samrat Gaur (Manager) of the premise and found that the Assembly building have deemed complied with the Fire prevention and Fire safety requirements in accordance with the rules . The Fire Safety Certificate under rule 35 unless renewed under rule 36 or sooner cancelled under Rule 40 and that the building is fit for occupancy Group "D" "Assembly Building" with effect from ...9/5/18.....for a period of three years, subject to conditions printed overleaf.

Issued on.....9/5/18.....at New Delhi by


(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Health officer ,
EDMC (PHD), Shahdara South Zone
Delhi-110092.
2. MC Donald Family Restaurant Shop No. 7,8,9,
Aggarwal Fun City Mall, Plot No.29 & 31 ,
East CBD, Shahdhra, Delhi-32.



CONDITIONS:

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. All comments/ directions of the Licensing Department shall always be permitted and followed.
7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : MC Donald Family Restaurant at Shop No. 7,8,9, Aggarwal Fun City Mall, Plot No.29 & 31 ,East CBD, Shahdhra, Delhi-32.
2. Building is comprised of : **ground floors** ~~2+1~~ (BS+G+II)
3. Type of Occupancy : Assembly (Restaurant)
4. Type of Case : **Renewal**
5. Details of Previous FSC : F6/DFS/MS/EH/NDZ/2015/639 dated 29/04/2015
6. Fire Safety direction letter No : Delhi Fire safety Act,2007 and Rules 2010.
7. Date of Inspection : 20/04/18.
8. Name of the Inspecting Officers: : Francis Brown (DO)
9. Name of the designation of Officer :
from the building side : Sh. Samrat Gaur (Manager)
10. Year of Construction : 2008
11. Applicant's letter No : Nil Dated 09.4.18.

	Minimum Standards on fire prevention and fire safety U/R 33	Requirement NBC	Provided at Site	Remarks MR/NMR
1	Access to building	12 m	30 m wide	MR
	Road width	4.5m	06	MR
	Gate width	N/A	N/A	N/A
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type and Arrangement of Exits.			
	a. Number of Staircases	N/A	07no.	MR
	Upper Floor	N/A	07no.	MR
	Basement			
	B. Width of Staircases			
	Upper Floor	N/A	1.5m	MR
	Basement	N/A	1.5m	MR
	c. Protection of exits			
	Fire check door	N/A	Provided	MR
	Pressurization	N/A	N/A	N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
	g. Width of Corridor	2.5m	2.5m	MR
	h. Door Size	02m.	02m & 1.5m.	MR
	i. No. of doors	02no	02no	MR
3	Compartmentation.			
	Fire check door	N/A	Provided	MR
	Sealing of electrical shafts	Required	Sealed	MR
	Fire rating of shaft door	2 hrs.	2 hrs.	MR
	Water curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.			
	Basement	30A/Cper hrs.	N/A	N/A
	Upper floor	12a/c per hrs.	N/A	N/A
5.	Fire Extinguisher			
	Total numbers	02 Nos.	03 Nos.	MR
	types	ABC type & Co2	ABC type & Co2	MR
	IS marking	ISI marked	ISI marked	MR


6	First-aid-Hose Reels.			
	Total numbers of 2 nd floors	01 nos.	01 nos.	MR
	Length of hose reel hose	30 m	30 m	MR
	Nozzle diameter	5 mm	5 mm	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	Heat or Smoke	smoke	MR
	Location of main panel	Required	Provided	MR
	Location of repeater panel	NA	Provided	MR
	Alternate source of power	Battery & DG Set	Provided	MR
	Hooters	NA	Out side	MR
8	MOEFA	NA	Provided	MR
9	Public address System.	NA	Provided	MR
10	Automatic Sprinkler System.			
	Basement	N/A	Provided	MR
	Upper floor	N/A	Provided	MR
	sprinkler above false ceiling	N/A	Provided	MR
11	Internal Hydrants			
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants each floor	01 nos.	01 nos.	MR
	Hose box each floor	01 nos.	01 nos.	MR
12	Yard Hydrants.			
	Total number of hydrants	N/A	03 no	MR
	Hose Box	N/A	03 no	MR
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> • Ground Level ➤ Discharge of main Pump ➤ Head of Main Pump ➤ Number of main pumps ➤ Jockey pump out put ➤ Jockey pump head ➤ Standby pump out put ➤ Standby pump Head ➤ Auto Starting /Manual stopping ➤ Pump House Access • Terrace Level ➤ Discharge of pump ➤ Head of the Pump ➤ Power supply ➤ Auto Starting of pump 			
		2280 lpm	2280 lpm	MR
		60 m	60 m	MR
		01 no	01 no	MR
		450 lpm	450 lpm	MR
		60 m	60 m	MR
		2280 lpm	2280 lpm	MR
		60 m	60 m	MR
		Required	Provided	MR
		Required	Provided	MR
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	2,00,000 liters	2,00,000 liters	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	25,000 Ltrs.	25,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	Firemen's grounding switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	Provided	MR
18	Refuge Area.			
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	Provided in Basment		
	Detector system panel	N/A	Provided	MR
	Flow switch panel	N/A	Provided	MR
	PA system panel	N/A	Provided	MR
	Batter backup	N/A	Provided	MR
	Building Floor Plans	N/A	Provided	MR

The Fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping In view compliance of the minimum standards of Fire prevention and Fire Safety measured as required under the rules. The Fire Safety Certificate issued vide latter no. F6/DFS/MS/EH/2015/639 Dated 29/04/15.

The Fire safety certificate renewed under rule 37, of the Delhi Fire Service Rules 2010 is recommended.



Signature of the Inspecting Officer
Name : Francis Brown
Designation : DO (East)

Dy. CFO (NDZ)

C.F.O. M. SCHELL

FT/M-

Ue
3/5-

T.T. Jolly is Prepared and put up for signed Mr.

490/CFO DM
8/5/15/615