GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2018/ 961

Dated: 9/5/18

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Le Sancy located at 7A/47 WEA, Karol Bagh, New Delhi110005 comprised of basement, ground plus two upper floors, using basement as hall/storage, ground floor as reception & office, first & second floor each having 09 guest rooms respectively (total 18 guest rooms), was granted FSC by this department vide letter No. F6/DFS/MS/GH/2015/SZ/417 dated 23.03.2015. The premises was re-inspected by the officer concerned of this department on 20/04/2018 in presence of Sh. Anup, manager, and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) with effect from 9/5/18 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued on <u>9/5//8</u> at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

1. Sh. Dayal Chand (Owner), M/s. Hotel Le Sancy, 7A/47 WEA, Karol Bagh, New Delhi- 05.3

2. The Addl. C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi.

Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building

: M/s. Hotel Le Sancy, 7A/47, WEA, Karol Bagh, New

Delhi- 110005.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/2015/SZ/417 dated 23.03.2015

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 20.04.2018

7. Name of the Inspecting Officers

: M.K. Chattopadhyay, DO(South West)

8. Name and designation of officers

from the building side

: Sh. Anup, manager

9. Year of Construction

: 2000-01

10. Applicant's letter No.

: 1363/ADDL/ C.P./Lic (H) dated New Delhi the 26.02.2018

The said guest house is comprised of basement, ground plus two upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as per letter dt. 23.03.2015	Provided at site	Remarks MR/NMR			
1	Access to building						
	Road width	06 mts	Provided	MR			
	Gate width	4.5 mts	Directly accessible	MR			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangemen	t of Exits					
	a. Number of staircases	-	-				
	Upper Floors	01	01	MR			
	Basements	01	01	MR being old case			
	b. Width of staircases	-		_			
	Upper Floors	Old Case	1.13 mts	MR being old case			
	Basements	Old Case	1.25 mts	MR being old case			
	c. Protection of exits	-	-	-			
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	e. No. of continuous staircases to	01	01	MR			
	g. Width of Corridor	Old Case	4.5, 1.4 mts.	MR			
	h. Door Size	Old case	0.80 mts	MR being old case			
3	Compartmentation.		3				
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	Sealed				
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4	Smoke Management System.		8				

_	Dasements	30 a/c per nour	Emilianot fair provided	IVIIC
	Upper floors	12 a/c per hour	Natural Ventilation	MR
5	Fire Extinguishers			
	Total numbers	12	Provided	MR
	• Types	CO ₂ , ABC, WCO ₂	Provided	MR
	IS marking	ISI marked	Provided	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	01	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	g system.	-	
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	Required	Provided	MR
	Hooters' Location	N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.		e e	
	Basement	Required	Provided	MR
	Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
-	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
10			11/12	1071
12	Yard Hydrants.	N/A	N/A	N/A
	Total number of hydrantsHose Box			
12		N/A	N/A	N/A
13	Pumping Arrangements. • Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump			
	Number of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
		N/A	N/A	N/A

		Auto Starting/ Manual stoppi	ng N/A	N/A	N/A	
		Pump House Access	N/A	N/A	N/A	
		Terrace level				
		Discharge of pump	450 LPN	450 LPM	MR	
		Head of the pump	30 mts	30 mts	MR	
		Power Supply	Required	8	MR	
		Auto Starting of pump	Required			
14	C	aptive Water Storage for fire fighting		1 TO VIGOU	MR	
		Underground tank capacity	N/A	N/A	N/A	
		➤ Draw-off connection	N/A	N/A	N/A	
		Fire service inlet	N/A	Provided		
		Access to tank	N/A	N/A	N/A	
		Overhead Tank capacity	Old Case	4,000 lts	MR, Old Case	
15	1 12	it Signage.	Required	Provided	MR	
16	Provision of Lifts.					
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
	•	Pressurization of Lift lobby	N/A	N/A	N/A	
	•	Communication In lift Car	Required	Provided	MR	
	•	Fireman's Grounding Switch	Required	Provided	MR	
	•	Lift Signage	Required	Provided	MR	
7	Star	ndby power supply	Required			
8	1	ige Area.	required	Provided	MR	
	5	Total Area	N/A	N/A	N/A	
	>	> Location	N/A			
)	Fire	Control Room		N/A	N/A	
	errenant besteht beste	Detector System Panel	N/A	N/A	N/A	
		Flow Switch Panel	N/A	N/A	N/A	
	and the second second	PA System Panel	N/A	N/A	N/A	
	The filth of the second second	Battery backup	Required	Provided	MR	
		• Building Floor Plans	N/A	N/A	N/A	
1	Specia	al Fire Protection Systems for	N/A	N/A	IN/A	

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/2015/SZ/417 dated 23.03.2015, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

str m-scell FTD.

We is for Sign.

Signature of the Inspecting Officer

Name M.K.CHATTOPADHYAY Div. Officer (South West)

337 DO/SW