## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F6 | DFS | ms | School | 2018 | M92 / 949

Dated: 8/5/18

## **FIRE SAFETY CERTIFICATE**

Certified that the Bapu Public School, Delhi Gandhi Smarak Nidhi, Patpargang, Delhi, comprised of ground plus one upper floor was issued FSC vide letter No. F6/MS/DFS/2013/NDZ/765 dated 21/08/13. The school building was inspected by the officer concerned of this department on 06/04/18 in the presence of Mrs. Madhurima Chail (Head Mistress) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular issued by Director of Education and the school building is fit for occupancy class "B" to conditions, printed overleaf.

Issued on.....at New Delhi by

(Vipin Kental) Chief Fire Officer

To,

The Head Mistress, Bapu Public School, Delhi Gandhi Smarak Nidhi, Patpargang, Delhi.

Copy to:-

The Director of Education. Government of N.C.T Delhi, Old Sectt, Delhi-110054.

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

1. Name & address of the building :Bapu Public School, Delhi Gandhi Smarak Nidhi,

Patpargang, Delhi.

2. Building is comprised of

: G+1 floors

3. Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous FSC letter

: F6/MS/DFS/2013/NDZ/765 dated 21/08/13

6. Fire Safety Circular No.

: NA

7. Date of Inspection

: 06/04/18

8. Name of the Inspecting officers: ADO R.K. Yadav

9. Name and designation of

Officer from the building side

: Mrs.Madhurima Chail (Head Mistress)

10. Year of Construction

: 1990

1. A	pplicant's letter No : BPS/[	GSN/PPG/2018/	1867Dated 12/03	/18	
N	Minimum Standards on fire	Dir. of	Provided at	Remarks	
Ο.	prevention and fire safety U/R33	Education	Site	4	
1	Access to building				
	Road width	06 M	15 M	MR	
	Gate width	4.5 m	4.0 m/on road	MR	
	Width of internal road	N/A	N/A	N/A	
2	Number, Width, Type and Arrangeme	ent of Exits			
	a. Number of Staircases		-		
	Upper Floor	02 Nos.	02 Nos.	MR	
	Basement	N/A	N/A	N/A	
	B. Width of Staircases			is	
	Upper Floor	1.5 M or less	1.6 M & .96 M	MR	
	Basement	N/A	N/A	N/A	
	c. Protection of exits				
	Fire check door	N/A	N/A	N/A	
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A	
	e. No. of continuous staircases to	1 No.	1 No.	MR	
	terrace			1.10	
	g. Width of Corridor	1.5 M	1.0 M	MR old	
	D	4.0.04	1.0 M	accepted MR	
	h. Door Size	1.0 M	1.0 101	IVIIX	
3	Compartmentation.	N/A	N/A	N/A	
	Fire check door	N/A N/A	N/A	N/A	
	Sealing of electrical shafts	N/A	N/A	N/A	
	Fire rating of shaft door	N/A	N/A	N/A	
	Water curtain	N/A N/A	N/A	N/A	
	Fire Dampers	IN/A	IN/A	14//4	
4	Smoke Management System.	N1/A	NI/A	N/A	
	Basement	N/A	N/A N/A	N/A N/A	
	Upper floor	N/A	IN/A	IN/A	
5.	Fire Extinguishers				
	Total numbers	03 Nos.	07 Nos.	MR	
	types	ABC & Co2	ABC & Co2	MR	
	IS marking	ISI marked	ISI marked	MR	

5	First-aid-Hose Reels.					
	Total numbers of each floor	N/A	N/A	N/A		
	<ul> <li>Length of hose reel hose</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Nozzle diameter</li> </ul>	N/A	N/A	N/A		
· /.	Automatic fire detection and alarming system.					
× r	Type of detectors	N/A	N/A	N/A		
	Location of main panel	N/A	N/A	N/A		
	Location of repeater panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooter's location	N/A	N/A	N/A		
3 -	MOEFA	N/A	N/A	N/A		
9	Public address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.					
	Basement	N/A	N/A	N/A		
77	upper floor	N/A	N/A	N/A		
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
A CALL P. MINISTER	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.	8				
	Total number of hydrants	N/A	N/A	N/A		
<del></del>	Hose Box	N/A	N/A	N/A		
3	Pumping Arrangements.					
	Ground Level	N/A	N/A	N/A		
(2)	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main Pump	N/A	N/A	N/A		
4 4	<ul> <li>Number of main pumps</li> </ul>	N/A	N/A	N/A		
	> Jockey pump out put	N/A	N/A	N/A		
× =	> Jockey pump head	N/A	N/A	N/A		
		N/A	N/A	N/A		
	<ul><li>Standby pump out put</li><li>Standby pump Head</li></ul>	N/A	N/A	N/A		
	Auto Starting /Manual	N/A	N/A	N/A		
	stopping	NI/A	NI/A	NI/A		
*	> Pump House Access	N/A	N/A	N/A		
	Terrace Level	\$1/A	K1/A	NI/A		
	> Discharge of pump	N/A	N/A	N/A		
(	> Head of the Pump	N/A	N/A	N/A		
***	Power supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
14	Captive Water Storage for Fire Fighting.		*			
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	N/A	N/A	N/A		
5	Exit Signage.	N/A	N/A	N/A		

16	Provision of Lifts.	N/A	N/A	N/A
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication in lift car	N/A	N/A	N/A
	Firemen's grounding switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	N/A	N/A	N/A
	Total area	N/A	N/A	N/A
	Location	N/A	N/A	N/A
19	Fire Control Room	N/A	N/A	N/A
	Detector system panel	N/A	N/A	N/A
	Flow switch panel	N/A	N/A	N/A
	PA system panel	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/MS/DFS/2013/NDZ/765 dated 21/08/13 renewal under the Circular of Director of Education is recommended Fire Safety Certificate.

Signature of the Inspecting Officer

Name

: R. K. Yadav

Designation: ADO(LN)

Submitted for approved Plens

DO(ED)

DYCFOLHDY,

FT better a put of for squake