GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 969

Dated :- 9-1-5-1-8---

FIRE SAFETY CERTIFICATE

Certified that the M/s Gian Plaza Guest House located at 759-61, S.P. Mukherjee Marg, Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception), 1st floor (05 guest rooms + office), 2nd floor (08 guest rooms), 3rd floor (08 guest rooms) and 4th floor (03 rooms for owner residence + Generator room), total 21 guest rooms owned/occupied by M/s Gian Plaza Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2015/NDZ/523 dated 13/04/15. The premises was re-inspected by the officer concerned of this department on 22/04/18 in the presence of Mr. Brijesh Singh (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 21 guest rooms only at 1st to 3rd floor with effect from ----2/-1/4------- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued --- 7-/---at New Delhi by.

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- 2. The Manager,
 M/s Gian Plaza Guest House at 759-61, S.P. Mukherjee Marg, Delhi.
 Condition for the validity of fire safety certificate

variatly of the safety contineate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT								
1. Name & address of the building	M/s Gian Plaza Guest House at 759-61, S.P.							
	Mukherjee Marg, Delhi							
2. Type of occupancy:-	Residential, Sub Division-A-1							
	Ground + 04 Upper floors (total 21 guest rooms)							
	Ground floor (Reception), 1 st floor (05 guest rooms + office), 2 nd floor (08 guest rooms), 3 rd floor (08 guest							
	rooms) and 4 th floor (03 rooms for owner residence +							
2 Transaction	Generator room)							
3. Type of case:-	Renewal							
4. Details of previous FSC:-	No. F6/DFS/MS/GH/2015/NDZ/523 dated							
	13/04/15.							
5. Fire safety directives No	N/A							
6. Date of inspection:-	22/04/18							
7. Name of the inspecting officer:	Sh. Manoj Kumar Sharma (ADO/CC)							
8. Name & designation of officer	James and the Orece)							
From the building side:-	Mr. Brijesh Singh (Manager)							
9. Year of construction:-	1945							
10	With the second							

	Year of construction:-	1945		
10.	Applicant's letter No:-	Nil dated 10	/04/2018.	
				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	
1.	Access to Building			
	1) Road width	Required	30 mtr. (Approx)	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
•	Number, Width Type & Ar	rangement of Ex	xits	1 1/7 1
	A. Number of staircases	3		
	1. Upper floors	01 Nos.	01 Nos.	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.80 mtr.	0.90 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
	staircase to terrace			25
	E. Width of corridor	1.5 mtr.	1.5 mtr.	MR
	F. Door size	01 mtr.	01 mtr.	MR
	Compartmentation		*	
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System			
	1) Basements	30 ACPH	N/A	N/A
	2) Upper floors	12 ACPH	Natural	MR
	Fire Extinguishers		7.32	
	1) Total numbers	08 Nos.	08 Nos.	MR

	2) T	1 D C 0 C C C	1.000.000	
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel	101		
	1) Total number of eachfloor	01	01	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
_	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &			
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			
11.	Internal Hydrants			1
	1) Size of riser/down-comer	N/A	N/A	N/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor	27/4	271	
10	3) Hose box	N/A	N/A	N/A
12.	Yard Hydrants	27/4	I S.V.	
	1) Total number of hydrants	N/A	N/A	N/A
12	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping			
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	MR
	b) Head of pump	40 mtr.	40 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fi			
	Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A

m

2	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	•	ы	
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syster Risk, if any:	em for Protect	tion of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. safety F6/DFS/MS/GH/2015/NDZ/523 dated 13/04/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Office

Name: - M.K. Sharma Designation: - ADO (CC)

Dy. CFO/NDZ

.4- m.scell 1/3/5. F.t. letter is put up for