GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/School/SZ/2018/ 1016

Dated: /0/05/18

FIRE SAFETY CERTIFICATE

Certified that Govt. Boys. Sr. Sec. School, West Patel Nagar, New Delhi-110008 having two blocks old Block &Two New Blocks. The Old Block is comprised of ground floor only & Both New Blocks are comprised of ground floor plus one upper floor was granted Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2014/SZ/1533 dated 09-12-2014. The school building was re-inspected by the officer concerned of Delhi Fire Service on 10.04.2018 in the presence of Sh. Birdhi Lal Meena, Principal of the school and found that the school management (Govt. of NCT of Delhi) have complied with the fire prevention and fire safety requirements in accordance with the Directorate of Education circular No. F.6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 and that the school building is fit for occupancy class "Educational", with effect from the date of issue of this certificate for a period of three years, subject to compliance of the under mentioned conditions.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to: -

1. The Principal, Govt. Boys. Sr. Sec. School, West Patel Nagar, New Delhi- 110008

2. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in

INSPECTION REPOR

: Govt. Boys. Sr. Sec. School, West Patel Nagar, New 1. Name & address of the building

Delhi- 110008.

: Educational 2. Type of Occupancy

: Renewal 3. Type of Case

: F6/DFS/MS/School/2014/1533 dated 09/12/2014 4. Details of previous NOC

: Directorate of Education circular No. F.16/Estate/CC/Fire 5. Fire Safety directives letter No

Safety/2011/3298 to 3398 dated 01-03-2011.

: 10.04.2018 6. Date of inspection

: M.K. Chattopadhyay, Divisional Officer (South West) 7. Name of the Inspecting Officers

8. Name and designation of officers

: Sh. Birdhi Lal Meena, Principal from the building side

: 1951,1996,2013-2014 9. Year of Construction

: Ref. GBSSS/WPN/2018/1797 dated 16.03.2018. 10. Applicant's letter No.

· No.	\mathbf{N}	ant's letter No. r. Sec. School, West Patel Nagar, is linimum Standards on fire vention and fire safety U/R 33	Requirements as per letter dt. 28.10.2011	110viaca at a	Remarks MR/NMR
	Access	to building	06-4-	Provided	MR
	•	Road width Gate width	06 mts 4.5 mts	Provided N/A	MR N/A
*	•	Width of internal road			
2	Numb	er, Width, Type & Arrangement o	t Exits		
	a. Nur	nber of staircases	02	04	MR
	•	Upper Floors	N/A	N/A	N/A
	•	Basements	11/12		
	b. Wi	dth of staircases	1.50 mts	1.65,1.62,1.55,142	MR
	•	Upper Floors Basements	N/A	mts N/A	N/A
	c Pro	otection of exits			
	0.110	Fire check door	N/A	N/A	N/A
		D	N/A	N/A	N/A
	e No	o. of continuous staircases to terrace	01	02	MR
		idth of Corridor	N/A	1.75 mts	
		oor Size	1.0mt	Provided (1.05 mts)	MR
3	Con	npartmentation.			
		Fire check door	N/A	N/A	N/A
		Sealing of electrical shafts	N/A	Sealed	
		 Fire Rating of shaft door 	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
		• Fire Dampers	N/A	N/A	N/A
-		oke Management System.			

				127/4		
	Basements	30 a/c per hour	N/A	N/A		
	 Upper floors 	12 a/c per hour	Natural Vent	MR A		
	Fire Extinguishers					
	Total numbers	13 nos.	Provided	MR		
	• Types	ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
5	First-Aid Hose Reels.					
	Total numbers on each floor		N/A	N/A		
	 Length of hose reel hose 	30 m	N/A	N/A		
	Nozzle diameter	5 mm	N/A	N/A		
7	Automatic fire detection and alarming	system No	t required			
•	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	N/A	N/A	N/A		
9	Public Address System.	N/A	Provided	MR		
10	Automatic Sprinkler System	DI/A				
	Basement	N/A	N/A	N/A		
	Upper Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	> Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		

> A	tandby Pump Head Auto Starting/ Manual	N/A N/A	N/A	N/A	
S	Auto Starting/ Manual	14/11			
1		NI/A	N/A	N/A	
	topping	N/A			
 Pump House Access Terrace level Discharge of pump Head of the pump Power Supply 			N/A	N/A	
		N/A	N/A	N/A	-
		N/A	IN/A		-
		N/A	N/A	N/A	-
		N/A	N/A	N/A	
	Auto Starting of pump				
• Underground tank capacity			N/A	N/A	
		N/A	N/A	N/A	
> Dr	aw-off connection	N/A	N/A N/A	N/A	
	re service inlet	N/A	N/A N/A	N/A	
	ccess to tank	N/A	N/A	N/A	
• 0	verhead Tank capacity	N/A		MR	
D. '4 Cian	2000	Required	Provided	MR	
Exit Signage. Provision of Lifts.		Not Applic	able	27/4	
	N/A	N/A	N/A		
	ressurization of Lift Shaft	N/A	N/A	N/A	
Pressurization of Lift lobby	N/A	N/A	N/A		
		-	N/A	N/A	
• I	Fireman's Grounding Switch	N/A		NI/A	
• I	Lift Signage	N/A	N/A		
- 11	gunnly	N/A	N/A	N/A	
				3	
		N/A	N/A	N/A	
			N/A	N/A	
		1772		0	
Fire C		N/A	N/A	N/A	
•			N/A	N/A	
•			NI/A	N/A	
•	PA System Panel			N/A	
	Batter backup	N/A		NI/A	
•		N/A		C	
	Building Floor Plans	14/11	01 ABC tv	Abc IIIc VVD	
1	Standb Refuge	 Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup 	 Communication In lift Car Fireman's Grounding Switch Lift Signage N/A Standby power supply Refuge Area. ➤ Total Area ➤ Location Fire Control Room Detector System Panel Flow Switch Panel PA System Panel N/A N/A N/A N/A 	 Communication In lift Car Fireman's Grounding Switch Lift Signage N/A N/A N/A N/A N/A Standby power supply N/A 	• Communication In lift Car N/A N/A N/A • Fireman's Grounding Switch N/A N/A N/A • Lift Signage N/A N/A N/A N/A N/A N/A N/A Standby power supply N/A N/A N/A Refuge Area. N/A N/A N/A ▶ Total Area N/A N/A N/A ▶ Location N/A N/A N/A Fire Control Room N/A N/A N/A • Detector System Panel N/A N/A N/A • PA System Panel N/A N/A N/A • Batter backup N/A N/A N/A

The fire protection systems provided in the building were tested / checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/School/2014/1533 dated 09/12/2014, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

DFA is put up for approval & signature please

12 fel 2018

Signature of the Inspecting Officer
(M.K. CHATTOPADHYAY)
Divisional Officer, (South West)

DCFO(\$2).