## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 013

Dated: 10 118

## FIRE SAFETY CERTIFICATE

Certified that the Metro Inn Guest House located at 3044/1, Chauna Mandi, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (reception + office), 1<sup>st</sup> floor (05 guest rooms), 2<sup>nd</sup> floor (06 guest rooms), 3<sup>rd</sup> floor (06 guest rooms), 4<sup>th</sup> floor (01 staff room + store room), total 17 guest rooms owned/occupied by Metro Inn Guest House granted FSC by this department vide letter No.F6/DFS/MS/EH/2015/NDZ/829 dated 21/05/15. The premise was re-inspected by the officer concerned of this department on 19/04/18 in the presence of Mr. Arun (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 17 guest rooms with effect from -1 of 18/10/2015/10/201

Issued -- 18---- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

## Copy to:-

10

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ref. letter no. 1630/Joint/C.P./Lic. (H) dated 03/04/18.
- 2. The Manager, Metro Inn Guest House at 3044/1, Chauna Mandi, Pahar Ganj, New Delhi.

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

827 8	INSPI	ECTION REPOR	RT		
1. Name & address of the building Metro Inn Guest House at 3044/1,					
1.	Traine & address of the banding	Mandi, Pahar Ganj, New Delhi			
2	Type of occupancy:-			-	
۷.	Type of occupancy.	Residential, Sub Division-A-1 Gr. + 04 Upper floors (total 17 Guest rooms)			
		Ground floor (	Ground floor (reception + office), 1 <sup>st</sup> floor (05 guest		
		rooms), 2 <sup>nd</sup> flo	or (06 guest rooms), 3	rd floor (06 guest	
		rooms), 4 <sup>th</sup> floor (01 staff room + store room)			
	Type of case:-	Renewal		7/000 1 1	
4.	MS/EH/2015/ND2	2/829 dated			
		21/05/15.			
	Fire safety directives No	N/A			
	Date of inspection:-	19/04/18			
	Name of the inspecting officer:				
	Name & designation of officer	4-			
	he building side:-	Mr. Arun (N	Manager)		
9.	9. Year of construction:- 2002				
10.	Applicant's letter No:-	1630/Joint C.P.	/Lic. (H) dated 03/		
		1		Old Case	
S.No.	Minimum Standards on fire	Requirement/ Existing fire safety	Provided at site	Remarks	
	Prevention and fire safety	arrangements	V	MR/NMR	
	U/R 33				
1.	Access to Building		0.6	140	
	1) Road width	N/A	06 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	its		
	A. Number of staircases	3			
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.90 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	01	01	MR	
	staircase to terrace		3		
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	1.0 mtr.	1.0 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	,	N/A	N/A	N/A	
1	5) Fire Dampers  Smake Management System		13/44	1 2 11 2 2	
4.	Smoke Management System	30 ACPH	N/A	N/A	
	1) Basements	12 a/c per	Natural	MR	
	2) Upper floors	hour	ivatuiai	1411	
		Hour			



5.	Fire Extinguishers			Contract of the Contract of th	
	1) Total numbers	08 Nos.	08 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	
6.	First-Aid Hose Reel				
	1) Total number of eachfloor	01	01	MR	
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR	
	3) Nozzle diameter	05 mm	05 mm	MR	
7.	<b>Automatic Fire Detection &amp;</b>	Alarming Syst	em		
	1) Type of detectors	N/A	N/A	N/A	
	2) Location of main panel	N/A	N/A	N/A	
	3) Location of repeater panel	N/A	N/A	N/A	
	4) Alternate source of power	N/A	N/A	N/A	
	5) Hooter's Location	N/A	N/A	N/A	
8.	MOEFA	N/A	N/A	N/A	
9.	Public Address System	Required	Provided	MR	
10.	Automatic Sprinkler System			.,,,,,	
	1) Basement	N/A	N/A	N/A	
	2) Upper floors	N/A	N/A	N/A	
	3) Sprinkler above false	N/A	N/A	N/A	
	ceiling			1771	
11.	Internal Hydrants				
	1) Size of riser/down-comer	N/A	N/A	N/A	
	2) Number of hydrants per	N/A	N/A	N/A	
	floor				
	3) Hose box	N/A	N/A	N/A	
12.	Yard Hydrants	/			
	1) Total number of hydrants	N/A	N/A	N/A	
	2) Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement				
	1) Ground level	N/A	N/A	N/A	
	a) Discharge of main	N/A	N/A	N/A	
	pump		8		
	b) Head of main pump	N/A	N/A	N/A	
	c) Number of main pump	N/A	N/A	N/A	
	d) Jockey pump out put	N/A	N/A	N/A	
	e) Jockey pump head	N/A	N/A	N/A	
	f) Stand by pump output	N/A	N/A	N/A	
	g) Stand by pump head	N/A	N/A	N/A	
	h) Auto starting/Manual	N/A	N/A	N/A	
	stopping		5	A	
	2) Terrace level				
	a) Discharge of pump	225 LPM	225 LPM	MR	
	b) Head of pump	30 mtr.	30 mtr.	MR	
	c) Power supply	Required	Provided	MR	
	d) Auto starting of pump	Required	Provided	MR	

1

14.	Captive Water Storage for	Fire Fighting		
	Under ground tank     capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	2500 ltr.	2500 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
-	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syste Risk, if any:	m for Protect	tion of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2015/NDZ/829 dated 30/05/18 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officen

Name: - M.K. Sharma Designation: - ADO (CC)

549/06 MOZ DERO(NIDZ)