## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/Hospital/2018/SZ/ / 657

Dated: 1.1.7.1.18

## FIRE SAFETY CERTIFICATE

Certified that the **Laundry Block at Safdarjung Hospital Complex**, Ring Rod, New Delhi-110029, comprised of **Ground + 03 upper floors** have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by officers concerned of this department on 29/06/2018 in presence of Mr. Shankar B (JE/Elect.) and that the building is fit for occupancy class "**Industrial**" **Group-G** (Laundry & Blood Bank) as above with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 3010

Issued on 16718 at New Delhi by

(Vipin Kental) Chief Fire Officer Ph.: 011-23412225

Copy to: -

1. Ex. Engineer (E), PWD, Safdarjung Hospital Complex, Ring Road, New Delhi-110029

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

	INSDECTI	ON REPORT				
1	Name & Address of the Building	Laundry Block, Safdarjung Hospital Complex,				
		Ring Road, New Delhi–110029				
2	Type of Occupancy	Industrial Building "G" (Laundry & Blood Bank)				
3	Building Comprised of	Ground + 03 upper floors				
4	Type of Case	New				
5	Details of Previous NOC	Nil				
6	Fire Safety Directives Letter No	F.6/MS/DFS/85/Hospital/823 dated 23-09-1985				
7	Date of Inspection	29-06-2018				
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)				
9	Name & Designation of Officers from the building side	Mr. Shankar B (JE/Elect.)				
10	Year of construction	1965				
11	Applicant letter No.	Outdoor Diary No. 5992 dated 12-04-2018				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	FS Directives requirements	Provided at Site	Remarks MR/NMF		
1	Access to Building.			TVIII TVIII		
	Road width	6m within	Provided	MR		
	Gate width	Hospital	-NA-	-NA-		
	Width of internal road	Complex	-NA-	-NA-		
_ 2	Number, width, type and arrangements of	of exits.	4			
	a. Number of Staircase					
5	Upper floors	2 Nos	2 Nos	MR		
	> Basement floor	-NA-	-NA-	-NA-		
	b. Width of Staircase		()	· · · · · · · · · · · · · · · · · · ·		
	> Upper floors	1.35m	1.35m each	MR		
	➤ Basement floor	-NA-	-NA-	-NA-		
	c. Protection of exits					
	> Fire check door	Required	Provided	MR		
	> Pressurization	-NA-	-NA-	-NA-		
	d. No. of continuous staircase to terrace	2 Nos	Provided	MR		
	e. Width of corridor	-NA-	-NA-	-NA-		
	f. Door size	-NA-	-NA-	-NA-		
3	Compartmentation.			1111		
	Fire check door.	Required	Provided	MR		
	<ul> <li>Sealing of electrical shafts.</li> </ul>	Required	Provided	MR		
	• Fire rating of shaft door.	-NA-	-NA-	-NA-		
	Water curtain	-NA-	-NA-	-NA-		
	Fire dampers.	-NA-	-NA-	-NA-		
4.	Smoke Management system.					
	Basement	30 ACPH	-NA-	-NA-		
	Upper floors	12 ACPH	Exhaust fan provided	MR		
5.	Fire Extinguishers.	4				
	Total numbers	20 Nos.	20 Nos	MR		
	• Types	ABC / Co2	ABC, CO2 & W.CO2	MR		
	ISI Marking	Required	Provided	MR		
6.	First Aid Hose Reels.					
0.	Total numbers on each floor.	2 Nos	2 Nos	MR		
	• Length of hose-reel hose.	30m	30m	MR		
	Nozzle Diameter	5mm	5mm	MR		
New Ca		1	fdarjung Hospital Complex,	700.000		

19.	Fire Control Room.			
-	Detector system panel.	Required	Provided	MR
	Flow switch panel.	-NA-	-NA-	-NA-
	PA system panel.  Battery backup  Building floor plan	Required	Provided	MR
		Required	Provided	MR
		-NA-	-NA-	-NA-
20.	Special Fire Protection System for the	Required	CO2 & ABC fire extinguishers	MR
	Protection of special Risk, if any.		provided near LT & HT Panel	

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. The shortcomings communicated by this department vide even letter No. F6/DFS/MS/Hospital/2017/55 dated 06/01/17 (C-6) found complied.

Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

New Case

Laundry Block, Safdarjung Hospital Complex, New Delhi

DO (SD) Julesta April 8 De Crocos

Cross

1629/CP0/32

M-SCELL

FT M.

N. 6.-7. Idlan 800

but no

January (50)

C (1)

m.scell

4/6/7