GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2018/SZ/ | 666

Dated: ./.6./7/18

FIRE SAFETY CERTIFICATE

Certified that the "Musical Fountain Complex" (Block-3) located at Netaji Nagar, New Delhi, comprised of Ground floor only Owned/Occupied by Applause Hospitality Services Pvt. Limited was issued FSC by this department vide letter No. F.6/DFS/MS/2014/SZ/1071 dated 27/08/2014. The premises was re-inspected by the officer concerned of this department on 05/07/2018 in the presence of Mr. Bimal Prakash (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Group-D" as above with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions mentioned below.

Issued on _____ at New Delhi by

(Vipin Kental) Chief Fire Officer Ph. 011-23412225

Copy to: -

- 1. Authorized Signatory, M/s Applause Hospitality Services Pvt. Ltd. Musical Fountain Complex, Netaji Nagar, New Delhi.
- 2. Medical Officer of Health, NDMC Health Department, Palika Kendra, New Delhi-110001

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept unlocked & free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

	INSPECT	ION REPORT			
1	Name & Address of the Building Musical Fountain Complex (Block-3),				
		Netaji Nagar, New Delhi			
2	Type of Occupancy	Assembly 'Group-D'			
3	Building comprised of	Ground floor only			
4	Type of Case	Renewal			
5	Details of Previous NOC	F.6/DFS/MS/2014	I/SZ/1071 Dated 27-08-20	014	
6	Fire Safety Directives Letter No	F.6/DFS/MS/2014	1/170 dated 16-06-2014		
7	Date of Inspection	05-07-2018			
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)			
9	Name & Designation of Officers from the building side	Mr. Bimal Praksah (Manager)			
10	Year of construction	2014			
11	Applicant letter No.	Outdoor Diary No. 9373 dated 29/06/2018			
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirement	Provided at Site	Remarks MR/NMF	
1	Access to Building.				
	Road width	6 mtr	Provided	MR	
	Gate width	5 mtr	6 mtr	MR	
	• Width of internal road	N/A	N/A	N/A	
2	Number, width, type & arrangement of exits				
2	a) Number of Staircase				
	• Upper floors	N/A	N/A	N/A	
	Basement floor	N/A	N/A	N/A	
	b) Width of Staircase				
	Upper floors	N/A	N/A	N/A	
	Basement floor	N/A	N/A	N/A	
		IN/A	IN/A	IN/A	
	c) Protection of exits • Fire check door	Deguined	D	MD	
		Required	Provided	MR	
	• Pressurization	N/A	N/A	N/A	
	d) No. of continuous staircase to terrace	N/A	N/A	N/A	
	e) Width of corridor	N/A	N/A	N/A	
_	f) Door size	2m x 3 Nos	Provided	MR	
		1m x 2 No		41	
3	Compartmentation.	27/4			
				N/A	
	Fire check door.	N/A	N/A	N/A	
	 Sealing of electrical shafts. 	N/A	N/A	N/A	
-	Sealing of electrical shafts.Fire rating of shaft door.	N/A N/A	N/A N/A	N/A N/A	
8	Sealing of electrical shafts.Fire rating of shaft door.Water curtain	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A	
	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	N/A N/A	N/A N/A	N/A N/A	
4.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system.	N/A N/A N/A N/A	N/A N/A N/A N/A	N/A N/A N/A N/A	
4.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	N/A N/A N/A N/A 30 ACPH	N/A N/A N/A N/A	N/A N/A N/A N/A	
4.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system.	N/A N/A N/A N/A	N/A N/A N/A N/A	N/A N/A N/A N/A	
4.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement 	N/A N/A N/A N/A 30 ACPH 12 ACPH	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	
,	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors 	N/A N/A N/A N/A 30 ACPH 12 ACPH	N/A N/A N/A N/A N/A N/A Provided	N/A N/A N/A N/A N/A N/A N/A N/A N/A	
,	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers.	N/A N/A N/A N/A 30 ACPH 12 ACPH 08 Nos ABC/Co2	N/A N/A N/A N/A N/A N/A N/A Provided W.CO2 & CO2	N/A N/A N/A N/A N/A	
,	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers 	N/A N/A N/A N/A 30 ACPH 12 ACPH	N/A N/A N/A N/A N/A N/A Provided	N/A N/A N/A N/A N/A N/A N/A N/A N/A	
,	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types 	N/A N/A N/A N/A 30 ACPH 12 ACPH 08 Nos ABC/Co2	N/A N/A N/A N/A N/A N/A N/A Provided W.CO2 & CO2 Provided	N/A N/A N/A N/A N/A N/A N/A N/A MR	
5.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking 	N/A N/A N/A N/A 30 ACPH 12 ACPH 08 Nos ABC/Co2	N/A N/A N/A N/A N/A N/A N/A Provided W.CO2 & CO2	N/A N/A N/A N/A N/A N/A N/A N/A MR	
5.	 Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. Smoke Management system. Basement Upper floors Fire Extinguishers. Total numbers Types ISI Marking First Aid Hose Reels.	N/A N/A N/A N/A N/A 30 ACPH 12 ACPH 08 Nos ABC/Co2 ISI marked	N/A N/A N/A N/A N/A N/A N/A Provided W.CO2 & CO2 Provided	N/A N/A N/A N/A N/A N/A N/A MR MR	

Musical Fountain Complex (Block-3), Netaji Nagar, New Delhi

7	Automatic fire detection & alarming sys	tem.		
	Type of detectors	N/A	N/A	N/A
1	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants.			
11.	Size of Riser/Down-comer	Required	100 mm	MR
		Required	One	MR
	Number of Hydrant per floor	Required	One	MR
	Hose box.	Required	One	14117
12.	Yard Hydrants.	27/4	DT/A	NT/A
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.	N/A	N/A	N/A
13.	Pumping arrangements.	×		
	Ground Level	27/4	».	N/A
	Discharge of main pump.	N/A	N/A	N/A N/A
	> Head of main pump.	N/A	N/A	
	Number of main pumps.	N/A	N/A	N/A N/A
	> Jockey Pump output.	N/A	N/A N/A	N/A
	> Jockey Pump head.	N/A N/A	N/A N/A	N/A
	Standby Pump output.Standby Pump head.	N/A N/A	N/A	N/A
	> Auto Starting/Manual Stop		N/A	N/A
	Terrace Level	ping. IV/A	IV/A	11//1
		450 LPM	Provided	MR
	Discharge of pump.Head of pump.	40m	Provided	MR
	> Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for Fire Fight			
_ 11	 Underground tank capacity. 	N/A	N/A	N/A
	> Draw-off connection.	N/A	N/A	N/A
	> Fire Service Inlet.	Required	Provided	MR
	> Access to tank.	N/A	N/A	N/A
	Overhead tank capacity.	10,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	N/A	N/A	N/A
	 Pressurization of lift lobby. 	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	Total area	N/A	N/A	N/A
	 Location 	N/A	N/A	N/A

Musical Fountain Complex (Block-3), Netaji Nagar, New Delhi

19.	Fire Control Room.			
	Detector System Panel.	N/A	N/A	N/A
	Flow Switch Panel.	N/A	N/A	N/A
	PA system Panel.	N/A	N/A	N/A
	Battery backup	N/A	N/A	N/A
	Building floor plan	N/A	N/A	N/A
20. Special Fire Protection System for the Protection of special Risk, if any:				N/A

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection. Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate issued vide letter No. F.6/DFS/MS/2014/SZ/1071 dated 27.08.2014, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

Musical Fountain Complex (Block-3), Netaji Nagar, New Delhi

DO (8D)

1625/0/20152

G. T. Lellin Par up for Signation blease

COOCS2P M. SCOU WE 1677