

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO.F6/DFS/MS/School/2018/SZ/ 1638

Dated: 13/7/18

FIRE SAFETY CERTIFICATE

Certified that the Siddharth Public School, RZH-330B, Street No. 11, Raj Nagar-II Palam Colony, New Delhi-110045, comprised of ground plus two upper floors was issued fire Safety certificate vide letter no. F6/DFS/MS/School/2015/SZ/1371 dated 30.07.2015. The premise was re-inspected by the officer concerned of this department on 03.07.2018 in presence of Ms. Renu Sharma (Admin.) and found that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Directorate of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class B "Educational building" with effect from... 13/7/18.... for a period of **three** years subject to compliance of the conditions printed overleaf.

Issued on ... 13/7/18 at New Delhi by


Vipin Kental
Chief Fire Officer



Copy to:-

1. The Dy. Director, (Education), G.N.C.T of Delhi, Old Secretariat, New Delhi-54.
2. Manager, Siddharth Public School, RZH-330 B, Street No. 11, Raj Nagar-II Palam Colony, New Delhi-110045.

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

N/13

Siddharth Public School, RZH-330B, Gali No.11 Raj Nagar-II,
Palam Colony, New Delhi-110045

1	Name & address of the building	Siddharth Public School, RZH-330B, Gali No.11 Raj Nagar-II, Palam Colony, New Delhi-110045		
2	Type of Occupancy	Educational Building "B"		
3	Type of case	Renewal (Ground Plus Two Upper Floors)		
4	Details of previous NOC	F/6/DFS/MS/School/2015/SZ/1371 dated 30.07.2015		
5	Fire safety directives letter No	DOE Education Cir. No. dated 1.3.2011		
6	Date of inspection	03.07.2018		
7	Name of the inspecting Officers	ADO S.P. Bhardwaj		
8	Name and designation of officers from the building side	Mrs. Renu Sharma (Admin.)		
9	Year of construction	Before 2006		
10	Applicant's letter No.	Nil Dated 14.06.2018	Ground plus Two upper Floors	
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR / NMR
1	Access to building			
	1) Road width	6 Mtrs.	Provided	MR
	2) Gate width	4.5 Mtrs.	Direct accessible from road	MR
	3) Width of internal road	N/A	N/A	N/A
2	Number, width Type & arrangement of exits			
	a. Number of staircases			
	1. Upper floors	2 Nos.	2 Nos.	MR
	2. basements	N/A	N/A	N/A
	b. Width of staircase			
	1. Upper floors	1.50 Mtrs. If less than 1.50 additional staircase of .75 Mtr. Is required	100, 85 Mtrs.	MR
	2. basements	N/A	N/A	N/A
	c. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	1 No.	Provided	MR
	e. Width of corridor	1.50 Mtrs.	208 Cms.	MR
	f. Door size	88 & 206 Cms.	88 & 206 Cms.	MR being old case
3	Compartmentation.			
	1. Fire check door	N/A	N/A	N/A
	2. Sealing of electrical shafts	N/A	Sealed	N/A
	3. Fire Rating of shaft door	N/A	N/A	N/A
	4. water curtain	N/A	N/A	N/A
	5. Fire dampers	N/A	N/A	N/A
4	Smoke Management system.			
	basement		N/A	N/A
	upper floors	12 a/c charge	Natural Vent.	MR

5	Fire Extinguishers			
	total numbers	Two each floor ABC 5	8 Nos.	MR
	Types	KG. Capacity	ISI	MR
	ISI marking	Marked	ABC	MR
6	First-Aid Hose Reels.		Provided	MR
	total numbers on each floor	One	One	MR
	Length of Hose reel hose	30 m	Mtrs.	MR
	Nozzle Diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	location of Main Panel	N/A	N/A	N/A
	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	hooter's location	N/A	N/A	N/A
8	MOEFA	N/A	Provided	N/A
9	Public Address System.	N/A	Provided	N/A
10	Automatic Sprinkler System.			
	basement	N/A	N/A	N/A
	upper floors	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants			
	Size of riser/down-corner	N/A	100 MM	N/A
	Number of Hydrants per floor	N/A	One	N/A
	hose Box	N/A	Provided	N/A
12	Yard Hydrants.			
	total number of hydrants	N/A	N/A	N/A
	hose box	N/A	N/A	N/A
13	Pumping arrangements			
	1. Ground level			
	a. Discharge of main Pump	N/A	N/A	N/A
	b. Head of main pump	N/A	N/A	N/A
	c. Number of main pumps	N/A	N/A	N/A
	d. jockey pump out put	N/A	N/A	N/A
	e. jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g. Stanby Pump head	N/A	N/A	N/A
	h. Auto Starting/Manual stopping	N/A	N/A	N/A
	pump house access	N/A	N/A	N/A
	2. Terrace level			
	a. Discharge of pump	220 LPM	220 LPM	old case
	b. head of the pump	30 Mtrs.	30 Mtrs	MR
	c. Power supply	Required	Provided	MR
	d. Auto starting of pump	Required	Provided	MR
14	Captive water storage for fire fighting			
	1. Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	N/A	Provided	MR
	c. Access to tank	N/A	N/A	N/A
	Over head tank Capacity	5000. Ltrs.	5000 Ltrs.	MR
15	Exit Signage:	Required	Provided	MR

N/15

16	Provision of lifts.			
	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A
	e. Lift signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.	Not Required		
	total area			
	location			
19	Fire control room			
	a. detector system Panel	N/A	N/A	N/A
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup	N/A	N/A	N/A
	e. Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special risks, if any: ABC fire extinguisher near electric panel			MR

The fire protection systems provided in the building were checked and found functional at the time of inspection. Keeping in view deemed compliance of the minimum standards on fire prevention and fire safety requirement under the rules, renewal of FSC issued vide letter no. F6/DFS/MS/School/2015/SZ/1371 dated 30.07.2015 is recommended.

Accordingly DFA is put up for your approval and signature please.

Samp
4/7/18

S.P. Bhardwaj
ADO Dwarka

~~DO/SW~~

~~5/7/18~~

776/DO/SW
5/7/18

~~DCFO (S2)~~



~~Samp~~

~~CFO (S2)~~

5/7

M. S. Cell

FT OR
10/7

1622/CF/S2
12/7

FT is put up for signature please.

~~CF/S2~~ M. S. Cell
13/7

~~Samp~~
13/7/18