GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

No. F6/DFS/MS/School/2018/ 16 18

Dated: 11/07/2018

FIRE SAFETY CERTIFICATE

Certified that M/s Gandhi Co-Ed. Sr. Sec School at Brahmpuri, Delhi-110053, comprised of ground plus one upper floors, owned/occupied by Gandhi Co-Ed. Sr. Sec School was issued FSC vide letter No. F6/DFS/MS/School/2015/1453 dated 12/08/15. The school building was re-inspected by the officer concerned of this department on 26/06/18 in the presence of Mr. Jagmeher Singh, Vice-Principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular Letter No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/11 issued by Director of Education and observed that the school building is fit for occupancy class "B" 'Educational Building' with effect from 11/07/2018 for a period of three years, subject to conditions, printed overleaf.

Issued on 11 07 2018 at New Delhi by

(Vipin Kental) Chief Fire Officer

To,

The Vice-Principal, Gandhi Co-Ed. Sr. Sec School Brahmpuri, Delhi-110053

Copy:-

The Dy. Director of Education, B- Block, Yamuna Vihar, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

NIII

1. Name & address of the building

: Gandhi Co-Ed. Sr. Sec. School,

Brahmpuri, Delhi-110053

Building is comprised of

: Ground plus one upper floor

Type of Occupancy

: Educational

4. Type of Case

: Renewal

5. Details of Previous FSC letter

: F6/DFS/MS/School/2015/1453 dated 12/08/15

6. Fire Safety direction letter No

: F16/Estate/CC/FireSafety/2011/3298to3398 dt-01/03/11

7. Date of Inspection

: 26/06/2018

8. Name of the Inspecting officers

: ADO Vijay Bahadur

9. Name and designation of officer

from the building side

: Mr. Jagmeher Singh, Vice Principal

10. Year of Construction

: 2001

11. Applicant's letter No

: G. Co.Ed.SSS/18-19/32, Dated- 22/05/2018

Sr. No	Prevention and Fire Safety U/R	Circular	Provided at Site	Remark				
01	Access to Building Requirement MR/NN							
	Road width	06 mtr.	15 mtr.	145				
	Gate width	4.50 mtr	3.70 mtr	MR				
	10/inlth = 5 : 1	* ⁴	3.70 11111	MR/old				
02	• Width of internal road	N/A	N/A	accepted				
	Number, Width, Type and Arrang	gement of Exits	10//	N/A				
	a. Number of Staircases							
	Upper floor	00						
	Basement	02 nos	02 nos	MR				
		N/A	N/A	N/A				
	b. Width of Staircases	4.50		1 177 (
	Upper floor	1.50 mtr	1.20 mtr each	MR/old				
	 Basement 			accepted				
	c. Protection of exits	N/A	N/A	N/A				
	Fire check door	N//A	*					
	 Pressurization 	N/A	N/A	N/A				
	d. No. of Continuous Staircases	N/A	N/A	N/A				
	to Terrace	N/A	N/A	N/A				
	e. Width of corridor	1.50 mtr	1.50 mtr & 2.60 mtr	MR				
)3	f. Door Size	01 mtr.	01 mtr.	MR				
/3	Compartmentation.							
	 Fire check door 	N/A	NI/A					
	 Sealing of electrical shafts 	N/A	N/A N/A	N/A				
	 Fire rating of shaft door 	N/A	N/A	N/A				
	 VVater curtain 	N/A	N/A	N/A				
4	• Fire dampers	N/A	N/A	N/A				
+	Smoke Management System.		IVA	N/A				
	 Basement 	N/A	N/A					
5. F	Upper floor	N/A	N/A N/A	N/A				
). h	Fire Extinguishers		IV/A	N/A				
	 Total numbers 	10 nos.	10	- 25				
	 types 	ABC /CO ₂	10 nos.	MR				
	IS marking	ISI marked	ABC /CO ₂	MR				
		. or marked	ISI marked	MR				

06	First-Aid-Hose Reels.	3		
	Total numbers on each floor	N/A		
	 Length of hose reel hose 		N/A	N/.
	Nozzle diameter	N/A	N/A	N/
07	Automatic fire detection and alarming s	N/A vstem	N/A	N/
	Type of detectors			
	 Location of main panel 	N/A	N/A	N/A
	Location of repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	N/A	N/A
80	MOEFA	N/A	N/A	N/A
09	Dublic A LL	N/A	N/A	N/A
	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			
	Basement	NI/A		
	• upper floor	N/A	N/A	N/A
	 sprinkler above false ceiling 	N/A N/A	N/A	N/A
11	Internal Hydrants	IN/A	N/A	N/A
	size of riser/down-comer	N/A	1	
1	Number of hydrants per floor	N/A	N/A	N/A
	 Hose box 	N/A	N/A	N/A
12	Yard Hydrants.	IN/A	N/A	N/A
	 Total number of hydrants 	N/A	NI/A	
_	 Hose box 	N/A	N/A	N/A
3	Pumping Arrangements.	IV/A	N/A	N/A
	Ground Level			-
	Discharge of main pump	N/A	NI/A	
	 Head of Main pump 	N/A	N/A	N/A
	 Number of main pumps 	N/A	N/A	N/A
	 Jockey pump out put 	N/A	N/A N/A	N/A
5 1	 Jockey pump head 	N/A	N/A	N/A
	 Standby pump out put 	N/A	N/A	N/A
	 Standby pump head 	N/A	N/A	N/A N/A
	 Auto starting /manual stopping 	N/A	N/A	N/A
	 Pump house access 	N/A	N/A	N/A
	Torrade Lever		2	
	Discharge of pump	N/A	N/A	NI/A
	 Head of the pump 	N/A	N/A	N/A
	 Power supply 	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A N/A
. (Captive Water Storage for Fire Fighting.			14//
	Underground tank capacity	NI/A	.	
	Draw-off connection	N/A N/A	N/A	N/A
4	Fire service inlet	N/A N/A	N/A	N/A
2 2	Access to tank	N/A N/A	N/A	N/A
	Overhead tank capacity	N/A N/A	N/A	N/A
E	Exit Signage.		N/A	N/A
A TOTAL		N/A	N/A	N/A

16	Provision of Lifts.					
	Pressurization of lift shaft	N/A	N/A	N/A		
	 Pressurization of lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	 Lift signage 	N/A	N/A	N/A		
17	Standby Power Supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
51	 Location 	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	 Flow switch panel 	N/A	N/A	N/A		
	 PA system panel 	N/A	N/A	N/A		
	 Battery backup 	N/A	N/A	N/A		
	 Building floor plans 	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by Director of Education, it is recommended to renew Fire Safety Certificate.

Signature of the Inspecting Officer

:- Vijay Bahadur

Designation

:- A.D.O (TP)

GENICONDE (F. M. SCELL Ways 5/7 FT letter us put sep for signature blacete efo(NDZ)/ M. SCELL Wy. 3/7/18