GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ 609

Dated: --11-17-18--

FIRE SAFETY CERTIFICATE

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi Ref. letter no. 3818/Addl. C.P/Lic. (H) dated 31/05/2018.
- 2. The Manager,

Chitra Guest House at P. No. 176, Katra Baryan, Fatehpuri, Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building Chitra Guest House at P. No. 176, Katra

Baryan, Fatehpuri, Delhi. 2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 02 Upper floors (total 06 Guest rooms) Ground floor (Commercial use), 1st floor (12 guest rooms + dining hall), 2nd floor (15 guest rooms + 05 store)

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/2015/NDZ/574 dated

5. Fire safety directives No.-N/A

6. Date of inspection:-

7. Name of the inspecting officer:-

8. Name & designation of officer From the building side:-

9. Year of construction:-

10. Applicant's letter No:-

21/04/15.

01/07/18

Sh. Manoj Kumar Sharma (ADO/CC)

Sh. Sarjeet Yadav(Manager)

3818/Addl.C.P/Lic.(H) dated 31/05/2018.

| S.No. | Minimum Cr. 1 | | | Old Cas | |
|--------|--|----------------------------------|------------------|--|--|
| 5.110. | Minimum Standards on fire Prevention and fire safety U/R 33 | Requirement/ | Provided at site | Remarks | |
| | | Existing fire safet arrangements | У | MR/NMF | |
| 1. | Access to Building | - Tangomonis | | TVIIV/TVIVI | |
| | 1) Road width | N/A | 06 mtr. | N/A | |
| | 2) Gate width | N/A | N/A | N/A N/A | |
| | 3) Width of internal road | N/A | NI/A | | |
| 2. | Number, Width Type & Al | rrangement of F | vite | N/A | |
| | A. Number of staircases | goment of E | Aits | * | |
| | 1. Upper floors | 01 Nos. | 01 Nos. | MR | |
| | 2. Basements | N/A | N/A | The second secon | |
| | B. Width of staircase | | 14/21 | N/A | |
| | 1. Upper floors | 0.80 mtr. | 0.85 mtr. | MR | |
| 4 | 2. Basements | N/A | N/A | N/A | |
| | C. Protection of exits | | | IN/A | |
| | 1. Fire check door | N/A | N/A | N/A | |
| - | 2. Pressurization | N/A | N/A | N/A | |
| | D. No of continuous staircase to terrace | 01 | 01 | MR | |
| | E. Width of corridor | N/A | N/A | N/A | |
| | F. Door size | 01 mtr. | 1.08 mtr. | | |
| 3. | Compartmentation | y · | 1.00 11111. | MR | |
| | 1) Fire check door | N/A | N/A | N/A | |
| | 2) Sealing of electrical shafts | N/A | N/A | N/A N/A | |
| | 3) Fire rating of shaft door | N/A | N/A | N/A N/A | |
| | 4) Water curtain | N/A | N/A | N/A N/A | |
| | 5) Fire Dampers | N/A | N/A | N/A | |
| | Smoke Management System | | | | |
| | 1) Basements | 30 ACPH | N/A | N/A | |
| | 2) Upper floors | | 21 | MR | |
| | Fire Extinguishers | | | 1411 | |
| | 1) Total numbers | 07 Nos. | 07 Nos. | MR | |
| | 2) Types | | | MR | |
| 3 | 3) ISI marking | - | D 111 | MR | |

| 6. | First-Aid Hose Reel | \ | | |
|---------|-------------------------------|------------|----------------|------------|
| 0. | 1) Total number of eachfloor | 01 | 01 | MR |
| | 2) Length of hose reel hose | 30 mtr. | 30 mtr. | MR |
| | 3) Nozzle diameter | 05 mm | 05 mm | MR |
| 7. 8. | Automatic Fire Detection & | | | IVIIX |
| | 1) Type of detectors | N/A | N/A | N/A |
| | 2) Location of main panel | N/A | N/A | N/A N/A |
| | 3) Location of repeater panel | N/A | N/A | N/A |
| | 4) Alternate source of power | N/A | N/A | N/A |
| | 5) Hooter's Location | N/A | N/A | N/A |
| | MOEFA | N/A | N/A | N/A |
| 9. | Public Address System | Required | Provided | MR |
| 10. | Automatic Sprinkler System | Required | Provided | MR |
| 10. | 1) Basement | N/A | NI/A | NI/A |
| | 2) Upper floors | N/A | N/A N/A | N/A N/A |
| | 3) Sprinkler above false | N/A N/A | N/A N/A | N/A N/A |
| | ceiling | 1 1/ 1/1 | 18/71 | IN/A |
| 11. | Internal Hydrants | | | |
| | 1) Size of riser/down-comer | N/A | N/A | N/A |
| | 2) Number of hydrants per | N/A | N/A | N/A |
| | floor | 1 4/ 1 1 | 14/74 | 1 1//4 |
| | 3) Hose box | N/A | N/A | N/A |
| 12. | Yard Hydrants | | 1 1// 1 | 11/21 |
| | 1) Total number of hydrants | N/A | N/A | N/A |
| | 2) Hose box | N/A | N/A | N/A |
| 13. | Pumping Arrangement | T | | |
| | 1) Ground level | N/A | N/A | N/A |
| | a) Discharge of main | N/A | N/A | N/A |
| | pump | | , | |
| | b) Head of main pump | N/A | N/A | N/A |
| | c) Number of main pump | N/A | N/A | N/A |
| | d) Jockey pump out put | N/A | N/A | N/A |
| | e) Jockey pump head | N/A | N/A | N/A |
| | f) Stand by pump output | N/A | N/A | N/A |
| | g) Stand by pump head | N/A | N/A | N/A |
| | h) Auto starting/Manual | N/A | N/A | N/A |
| | stopping | | A Side Control | |
| | 2) Terrace level | | , | 4 |
| | a) Discharge of pump | 225 LPM | 225 LPM | MR |
| | b) Head of pump | 40 mtr. | 40 mtr. | MR |
| | c) Power supply | Required | Provided | MR |
| | d) Auto starting of pump | Required | Provided | MR |
| 14. | Captive Water Storage for F | | 20 | |
| | 1) Under ground tank | N/A | N/A | N/A |
| | capacity | | | 2 |
| | a) Draw-off connection | N/A | N/A | N/A |
| | b) Fire service inlet | N/A | N/A | N/A |
| | c) Access to tank | N/A | N/A | N/A |

hur

| | d) Over head tank capacity | 5,000 ltr. | 5,000 ltr. | MR |
|----------|--|------------------|------------|------------|
| 15. | Exit Signage. | Paguine 1 | | |
| 16. | Provision of Lifts. | Required | Provided | MR |
| | a) Pressurization of lift shaft | N/A | N/A | N/A |
| | b) Pressurization of lift lobby | N/A | N/A | N/A |
| | c) Communication in lift car | N/A | N/A | N/A |
| | d) Fireman's switch | N/A | N/A | NI/A |
| 17. | e) Lift signage | N/A | N/A | N/A |
| 18. | Stand by Power Supply | Required | Provided | N/A |
| 10. | Refuge Area | N/A | N/A | MR |
| | Total area location | N/A | N/A | N/A N/A |
| 19. | Fire Control Room | N/A | | IN/A |
| | a) Detector system | | N/A | N/A |
| | panel | N/A | N/A | N/A |
| | b) Flow switch panel | N/A | N/A | NI/A |
| | c) PA system panel | N/A | N/A | N/A |
| | d) Battery backup | N/A | N/A | N/A N/A |
| | e) Building floor plan | | | IN/A |
| 0. | Special E: | N/A | N/A | N/A |
| <i>.</i> | Special Fire Protection System Risk, if any: | n for Protection | of special | N/A |

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/574 dated 21/04/15 renewal under rule 35 of the Delhi Fire Service rules

Signature of the Inspecting Officer

Dy. CFO (NDZ)

co on

CF.Q. miscell re-

Name: - M.K. Sharma Designation: - ADO (CC)

FJ. Litter is put up for sign

CRO(NDD) MISCELL MET