GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2018/ (604

Dated :--11-17-18--

FIRE SAFETY CERTIFICATE

Certified that the Chanchal Deluxe Guest House located at 8575, Arakashan Road, Pahar Ganj, New Delhi comprised of Ground + 05 Upper floors, Ground floor (04 guest rooms + reception + lobby), 1st floor to 4th floor (10 guest rooms at each floor), 5th & terrace floor is sealed, total 44 guest rooms owned/occupied by Chanchal Deluxe Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2015/NDZ/898 dated 02/06/15. The premise was re-inspected by the officer concerned of this department on 02/07/18 in the presence of Sh. Shree Ram (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 44 guest rooms at Ground to 4th floor only with effect from -------- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi ref. letter no. 3828/Addl./C.P./Lic. (H) dated 31/05/18.
- 2. The Manager,

Chanchal Deluxe Guest House at 8575, Arakashan Road, Pahar Ganj, New Delhi. Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

1	Nama & add S. I INSPECTION REPORT		
1.	Name & address of the building	Chanchal Deluxe Guest House at 8575	
2.	Type of occupancy:-	Residential, Sub Division-A-1	
		Gr. + 05 Upper floors (total 44 Guest rooms)	
		Ground floor (04 guest rooms + reception + lobby). 1 st floor to 4 th floor (10 guest rooms at each floor), 5 th & terrace floor is a selection of the second of the	
3.	Type of case:-	terrace moor is sealed	
4.	Details of previous FSC:-	Renewal	
-		No. F6/DFS/MS/GH/2015/NDZ/898 dated 02/06/15.	
5. 6.	Fire safety directives No	N/A	
0. 7	Date of inspection:-	02/07/18	
8.	Name of the inspecting officer:- Name & designation of officer	Sh. Manoj Kumar Sharma (ADO/CC)	
	From the building side:-		
9.	Year of construction:-	Sh. Shree Ram (Manager)	
10. A	Applicant's letter No:-	828/Add /C P /Lio (II) der 121/05/15	

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safet arrangements	Provided at site	Old Cas Remarks MR/NMF
1.	Access to Building	<i></i>		TVIIC/TVIVII
	1) Road width	DI/A		
	2) Gate width	N/A	06 mtr.	MR
		N/A	N/A	N/A
2.	3) Width of internal road	N/A	N/A	N/A
4.	Number, Width Type & A. A. Number of staircases	rrangement of E	xits	
	11. Number of staircases		er i e	
	 Upper floors Basements 	01 Nos.	01 Nos.	MR
		N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	0.90 mtr.	1.25 mtr.	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits		V. V.	1071
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous	N/A	N/A	N/A
+	staircase to terrace			1 1/71
-	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1.0 mtr.	1.0 mtr.	MR
•	Compartmentation			THE STATE OF THE S
_	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
-	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System			IN/A
	1) Basements	30 ACPH	V/A	N/A
	2) Upper floors	100	Υ	MR



May

5.	Fire Extinguishers			
	1) Total numbers	10 Nos.	24 Nos.	MG
	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided Provided	MR
6.	First-Aid Hose Reel	required	Provided	MR
	1) Total number of eachfloor	01	01	1.40
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05	MR
7.	Automatic Fire Detection &	Alarming Syst	tom	MR
	1) Type of detectors	N/A	N/A	21/4
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A		N/A
8.	MOEFA		N/A	N/A
9.	Public Address System	Required Required	Provided	MR
10.	Automatic Sprinkler System	Required	Provided	MR
	1) Basement	N/A	21/4	
	2) Upper floors	N/A N/A	N/A	N/A
	3) Sprinkler above false	N/A N/A	N/A	N/A
	ceiling	IN/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm	100	
	2) Number of hydrants per	01	100 mm	MR
	floor	01	01	MR
	3) Hose box	01	0.1	
12.	Yard Hydrants	O1	01	MR
	1) Total number of hydrants	N/A	NI/A	
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement	IVA	N/A	N/A
	1) Ground level	NI/A	2.4	
	a) Discharge of main	N/A	N/A	N/A
	pump	N/A	N/A	N/A
-	b) Head of main pump	NI/A	7.4	91. 10
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual	N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	2) Terrace level			
		150 7 77		
	- B- or painp		450 LPM	MR
	7		30 mtr.	MR
	c) Power supply		Provided	MR
	d) Auto starting of pump	Required	Provided	MR
1				

m

14.	Captive Water Storage for	Fire Fighting	1	
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
1.5	d) Over head tank capacity	25,000 ltr.	25,000 ltr.	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		1000	IVIIX
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
17.	e) Lift signage	N/A	N/A	N/A
	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
-	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System Risk, if any:	n for Protecti	on of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/898 dated 02/06/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Office

Name: - M.K. Sharma Designation: - ADO (CC)

Dy. CFO/NDZ

F.J. Letter is put up for