

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110 001

No.F.6/DFS/MS/School/2018/SZ/ 1579

Dated: 06/07/18

FIRE SAFETY CERTIFICATE


Certified that the **Sri Ram International School**, Prem Nursery, Gopal Nagar, Najafgarh, New Delhi-110043 comprised of two blocks namely Old Block & New Block. Old Block is having ground floor plus three upper floors and New block (not in use as stated by Admn. Officer) owned/occupied by Sri Ram International School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2014/SZ/773 dated 23.06.14. The School building was re-inspected by the officer concerned of this department on 22.06.2018 in the presence of Smt. Jyoti (Admin. Officer) and found that Now school comprised of three Blocks namely Old Block (A-Block), New Block (B-Block) & (C-Block as per undertaking is not in use). Old block having total 41 rooms 11 rooms on GF, 11 rooms on FF, 09 rooms on SF & 10 rooms on TF, New Block having total 02 rooms & open auditorium on GF, 08 rooms on FF, 08 rooms on SF, 08 rooms on TF (01 room on library side/hall not in use on FF, SF & TF). Sri Ram International School have complied/deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises **(Except Library side hall/area and Block-C)** is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as overleaf.

Issued on.....06/07/18..... at New Delhi.


(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

1. The Chairman,
Sri Ram International School,
Prem Nursery, Gopal Nagar, Najafgarh, New Delhi-110043
2. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi – 110054


2/7/18

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

use). Old block is having Ground floor plus three upper floors and New block is having ground plus three upper floors and C-block having ground floor plus three upper floors. All blocks are interconnected at each floor level.

INSPECTION REPORT

1. Name & address of the building : Sri Ram International School, Prem Nursery, Gopal Nagar, Najafgarh, New Delhi-110043
2. Type of Occupancy : Educational
3. Type of Case : New/Renewal
4. Details of Previous NOC : F.6/DFS/MS/School/2014/SZ/773 dated 23.06.14 (For old block)
5. Fire Safety directives letter No : N/A
6. Date of inspection : 22.06.2018
7. Name of Inspecting Officer : A.D.O. Sandeep Duggal
8. Name and designation of officers
From the building side : Smt. Jyoti (Admin. Officer)
9. Year of Construction : 2001 (Old Block) & 2016-17 (New Block & C-Block)
10. Applicant's letter No. : SRIS/2018-19/827 dated 17.04.2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirements	Provided at site	Remarks MR/NMR
1.	Access to building			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	Accessible 06 mtrs 4.5 mtrs N/A	12 mtrs 4.7 mtrs N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	<ul style="list-style-type: none"> • Upper Floors • Basements 	03 No's	03 No's & 01 ramp (01 staircase & 01 ramp are common with RCIT)	MR
		N/A	N/A	N/A
	b. Width of staircases			
	<ul style="list-style-type: none"> • Upper Floor • Basements 	150 cms in New block & 150 cms/additional staircase of 75 cms if less than 150 cms in old block	130, 150 cms & 138 cms 160 cms ramp. (138 cms S.case & 160 cms ramp are common with RCIT)	MR
		N/A	N/A	N/A
	c. Protection of exits			
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A	N/A	N/A
		N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Required	Provided	MR
	e. Width of Corridor	150 cms	135/280 cms in O blk & 260 cms in N Blk	MR, being old case
	f. Door Size	100 cms 120 cms in NB	90 to 100 cms in O blk & 120 cms in N blk	MR, being old case
3.	Compartmentation			
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	Smoke Management System			
	<ul style="list-style-type: none"> • Basements • Upper floors 	N/A	N/A	N/A
		Required	Natural ventilation	MR
5.	Fire Extinguishers			
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	24 no.'s	Provided	MR
		ABC/CO ₂ type	Provided	MR
		ISI marked	ISI marked	MR
6.	First-Aid Hose Reels			
	<ul style="list-style-type: none"> • Total numbers on each floor • Length of hose reel hose 	02 no.'s	Provided	MR
		30 mtrs	Provided	MR

Automatic fire detection and alarming system				
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement Ground Floor Sprinkler above false ceiling 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	N/A	100 MM	N/A
		N/A	One	N/A
		N/A	One	N/A
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A	N/A	N/A
		N/A	N/A	N/A
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual Stopping 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	<ul style="list-style-type: none"> Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	N/A	N/A	N/A
		450 LPM	Provided	MR
		40 mtrs	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> Underground tank capacity <ul style="list-style-type: none"> Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	Provided	N/A
		N/A	N/A	N/A
		10000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			No Lift
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
	<ul style="list-style-type: none"> Total Area Location 	N/A	N/A	N/A

19/20

19.	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/School/2017/SZ/1737 dated 11.07.17 has been complied. ✓

In view of the compliance/deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2014/SZ/773 dated 23.06.14 renewal/grant under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per the undertaking given by the Principal (placed at C-46) New Block the library side area/hall on each floor are not in use for schooling purpose. These halls are used only for personal purpose and further certified that Block-C is not in use. There are less than 45 students in each class.

Sandeep
22/6/18

Signature of Inspecting Officer
Name:- Sandeep Duggal
Designation:- Asstt. Divisional Officer



D.O. (South West)

[Signature]
26/6/18

624 DWSW
26/6/2018

DWSW (SW)

[Signature]
27/6

CFO S24

m. specul

FT/M.

29/6

F.T. letter is put up for sign please.

[Signature]