GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

No.F6/DFS/MS/NDZ/2018/ 1487

Dated: 25/6/18

FIRE SAFETY CERTIFICATE

Certified that the **Dharamshala for Dr. R.M.L Hospital** at **Sarai Complex, Mandir Marg, DIZ Area, New Delhi** comprised of **Ground + 03 Upper floors** owned/occupied by Dr. RML Hospital was granted FSC by this department vide letter No. **F6/DFS/MS/2015/NDZ/556 dated 20/04/2015.** The premises was re-inspected by the officer concerned of this department on 08/06/18 in the presence of Mr. Dubey (J.E) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group A Sub Division C-1, Gr. + 3 upper floor with effect from **24/6/18** for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued -- 25/12--- at New Delhi by.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

 Sh. Sanjeev Aggarwal, Executive Engineer (E), Dr. RMLHED, CPWD, New Delhi – 110001.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : Dharamshala for Dr. R.M.L Hospital at Sarai Complex, Mandir Marg, DIZ Area,

New Delhi

2. Type of occupancy

: Ground + 03 Upper floors, LR 13.35 mtr.

3. Type of case:-

: Renewal

4. Details of previous FSC 5. Fire safety directives No.

: F6/DFS/MS/NDZ/556 dated 20/04/2015.

6. Date of inspection:-

: N/A

08/06/18

7. Name of the inspecting officer 8. Name & designation of officer

: Sh. M.K. Sharma ADO/CC

From the building side 9. Year of construction

: Sh. Dupey (J.E)

: 2007

10. Applicant's letter No

: 20(8)/Dr.RMLCPWD/2018-19/714 dated

S.No.	Minimum Ctanda 1 C	28/05/20				
5.140.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety	Provided at site	Remarks MR/NMF		
1.	Access to Building	arrangements				
	1) Road width	06 mtr.	10			
	2) Gate width	05 mtr.	12 mtr.	MR		
	3)Width of internal road		05 mtr.	MR		
	Number Width Type & A	06 mtr.	06 mtr.	MR		
	Number, Width Type & Arra A. Number of staircases	ingement of Exit	S			
	1. Upper floors	0127				
	2. Basements	01 No.	01 No.	MR		
	B. Width of staircase	N/A	N/A	N/A		
	1. Upper floors					
	2. Basements	1.5 mtr.	2 mtr.	MR		
	C. Protection of exits	N/A	N/A	N/A		
	1. Fire check door					
		N/A	N/A	N/A		
-	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	01	01	MR		
	staircase to terrace					
-	E. Width of corridor	1.5 mtr.	2 mtr.	MR		
	F. Door size	1 mtr.	1 mtr.	MR		
	Compartmentation					
-	1) Fire check door	N/A	N/A	N/A		
	2) Sealing of electrical shafts	Required	Provided	MR		
-	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Natural	MR		
	Fire Extinguishers		raturar	IVIR		
	1) Total numbers	12 Nos.	15 Nos.	MD		
	2) Types	ABC & CO2	ABC, CO2 &	MR		
	3) ISI marking	Required	Provided	MR		
	First-Aid Hose Reel	Total Carlo	Tiovided	MR		
	1)Total number of each	02	02	MR		

			1			
	floor					
	2) Length of hose reel hose	30 m	30 m	MR		
	3) Nozzle diameter	5 mm	5 100.00	MR		
7.	Automatic Fire Detection &	Alarming Syste	em	IVIIC		
3	1) Type of detectors	N/A	N/A	N/A		
	2) Location of main panel	N/A	N/A	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	N/A	N/A		
0	5) Hooter's Location	N/A	N/A	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided			
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors	N/A	N/A			
	3) Sprinkler above false		IVA	N/A		
-	ceiling	NA	NA	NA		
11.	Internal Hydrants					
	1) Size of riser/down-comer	N/A	N/A	NI/A		
	2) Number of hydrants per	N/A	N/A N/A	N/A		
	floor	1071	IN/A	N/A		
	3) Hose box each floor	N/A	N/A	21/4		
12.	Yard Hydrants	11/11	IN/A	N/A		
	1) Total number of hydrants	N/A	N/A	127/4		
	2) Hose box	N/A	N/A N/A	N/A		
3.	Pumping Arrangement	14/11	IV/A	N/A		
	1) Ground level					
	a) Discharge of main	N/A	DI/A			
	pump	IN/A	N/A	N/A		
	b) Head of main pump	N/A	DT/A			
	c) Number of main pump	N/A	N/A	N/A		
	d) Jockey pump out put	N/A	N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump output		N/A	N/A		
	g) Stand by pump head	N/A	N/A	N/A		
	h) Auto starting/Manual	N/A	N/A	N/A		
	stopping	N/A	N/A	N/A		
	2) Terrace level					
		450 1 77 6				
	a) Discharge of pumpb) Head of pump	450 LPM	450 LPM	MR		
		35 mtr.	35 mtr.	MR		
	T-I-J	Required	Provided	MR		
		Required	Provided	MR		
-	Captive Water Storage for Fire Fighting					
	1) Under ground tank	N/A	N/A	N/A		
	capacity					
		N/A	N/A	N/A		
	b) Fire service inlet	N/A	N/A	N/A		
	1) 0 1 1	N/A	N/A	N/A		
	d) Over head tank	5000 ltr.	5000 ltr.	MR		

	capacity		•	
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any: Co2 & ABC			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/556 dated 20/04/2015 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation:- ADO (CC)

Dy. CFO/NDZ

miscell FT/D.

6121 Cre/122-15.

F.T. letter is put up for