## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/CGHS/2018/SZ/

Dated: 2/7/18

## **FIRE SAFETY CERTIFICATE**

(Vipin Kental)
Chief Fire Officer

## Copy to:-

- 1 President, the Jai Bhawani CGHS Ltd. Plot No. 5 B, Sector-22, Phase-I, Dwarka, New Delhi-110077.
- 2 The Joint Director, (Bldg.) DDA, Vikas Sadan, INA, New Delhi.

## **CONDITIONS**

- 1. Access road for fire tenders movement all around the building shall be kept free from any hindrance.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing Department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

Aso Owntes

0.1	Name & address of the building	The Jai Bhawani CGHS Ltd., Plot No.5B, Sector-22, Phase-1, Dwarka, New Delhi-110077			
2	Type of Occupancy	Residential Building "A" (CGHS)			
3	Type of case	Renewal	Stilt/Ground plus Ten upper floors		
4	Details of previous NOC	F6/DFS/MS/CGH	F6/DFS/MS/CGHS/2005/1174 Dated 7.6.2015		
5	Fire safety directives letter No	F6/DFS/MS/CGHS/2001/581 Dated 4.4.2001			
6	Date of inspection	15.6.2018			
7	Name of the inspecting Officers :	M K Chattopadhyay (DO S/W) SP Bhardwaj ADO (Dwarka)			
8	Name and designation of officers				
0	from the building side	Col K S Chaudhary (President)			
9	Year of construction	2001	8		
10	Applicant's letter No.	JBS/CGHS/Fire/2 018 Dated 28.5.2018	Stilt/Ground plus ten upper floors	Two blocks	
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	BBL Requirement/ letter dated 7.6.2005	Provided at site	Remarks MR / NMR	
1	Access to building				
	1) Road width	12 Mtrs.	Provided	MR	
	2) Gate width	4.5 Mtrs.	Provided	MR	
*	3) Width of internal road	6 Mtrs.	5.10 to 6 Mtrs.	MR being old case	
2	Number, width Type & arrangemen	it of exits	2 18	×	
	a. Number of staircases				
	1. Upper floors	2 No. each block	2 No. each Block	MR	
	2. basements	N/A	N/A	N/A	
	b. Width of staircase				
	1. Upper floors	1.25 Mtrs.	1.22 Mtrs.	MR being old case	
	2. basements	N/A	N/A	N/A	
	c. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
2	d. No. of continuous staircase to terrace	Two each block	Two each block	MR	
	e. Width of corridor	N/A	N/A	N/A	
	f. Door size	1 Mtr.	1 Mtr.	MR	
3	Compartmentation.				
	1. Fire check door	N/A	N/A	N/A	
	2. Sealing of electrical shafts	Required	Provided	MR	
	3. Fire Rating of shaft door	N/A	N/A	N/A	
	4. water curtain	N/A	N/A	N/A	
	5. Fire dampers	N/A	N/A	N/A	
4	Smoke Management system.	The state of the s			
	basement	N/A	N/A	N/A	
	upper floors	Page	Natural Ventilation	MR *	

		In trad	Provided	MR	
15	Exit Signage.	Required	Flovided		
	Provision of lifts.		N/A	N/A	
	a. Pressurization of lift shaft	N/A	N/A	N/A	
	b. pressurization of lift lobby	N/A	Provided	MR	
	c. communication in lift car	Required		MR	
	d. Fireman's grounding switch	Required	Provided	MR	
	e. Lift signage	Required	Provided	MR	
17	Standby power supply	Required	DG Set		
18	Refuge Area.	Not Required			
	total area				
	location				
19	Fire control room		INI/A	N/A	
	a. Detector system Panel	N/A	N/A	N/A	
	b. Flow switch Panel	N/A	N/A	MR	
	c. PA system Panel	Required	Provided	MR	
	d. Batter backup	Required	Provided	MR	
		Required	Provided		
20	Special Fire Protection system	s for protection o	of special risks, if an	y: ABC fire etinguisher MR	
	provided near electric panel				

Fire protection systems provided in the building were checked & found functional at the time of inspection. Shortcomings vide letter no. F6/DFS/MS/2017/SZ/1879 dated 26.7.2017 found rectified. Keeping in view deemed compliance of the minimum standards on fire prevention and fire safety requirements under the rules FSC issued vide letter no. F6/MS/DFS/CGHS/2005 dated 7.6.2005 is recommended.

Accordingly DFA is put up for approval and signature please.

M K Chattoupadhyay

DO (S/W)

S P Bhardwaj ADO (DWARKA)

678/DO(SD) dl. 18/06/18

DCFO(\$2)

Chol

m.scell FTM.

2/16

1570/C/0)52

cforest miscell legis

27/6/18