

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/EH/2018/NDZ/ 1572

Dated: 28/6/18

FIRE SAFETY CERTIFICATE

Certified that the M/S Bawa Palace Eating House running at first floor of the building is comprised of Basement, ground plus two upper floors (Basement storage, ground floor bank & second floor residence) at U-38 B, Shakarpur, Delhi-92. The premises was issued NOC vide letter no. F6/DFS/MS/EH/2010/3273 Dated 30/11/10. The Assembly (Eating House) building was inspected by the officer concerned of this department on 05/06/18 in the presence of Sh.Ijhar Khan (Manager) and found that the Assembly building have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 35 of the Delhi Fire Service Rule 2010, and that the building (First floor) is fit for occupancy "Assembly (Eating House)" with effect from 28/6/18 for a period of three years, subject to conditions printed overleaf.

Issued on 28/6/18 at New Delhi by


(Vipin Kental)
Chief Fire Officer



To,

1. The Manager,
M/S Bawa Palace Eating House,
U-38 B, Shakarpur, Delhi-92.
2. The Dy.Health Officer,
East MCD Health Department,
Shahdara South Zone, Karkardooma, Shahdara Delhi.

CONDITIONS:

1. All the means of escape shall be kept free of all the type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. All comments/ directions of the Licensing Department shall always be permitted and followed.
7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : Bawa Palace Pvt. Ltd at U-38 B, Shakarpur, Delhi-92.
2. Building is comprised of : B+G+2 (Eating House running at first floor)
3. Type of Occupancy : Assembly building
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/2010/3273 Dated 30/11/10
6. Fire Safety direction letter No : BBL
7. Date of Inspection : 05/06/18
8. Name of the Inspecting Officers: : ADO R.K.Yadav
9. Name of the designation of Officer from the building side : Sh.Ijhar Khan (Manager)
10. Year of Construction : 1993
11. Applicant's letter No : Nil dated 08/05/18

S.No	Minimum Standards on fire prevention and fire safety U/R33	BBL Requirement	Provided at Site	Remarks MR/NMR
1	Access to building			
	Road width	6 m	10 m	MR
	Gate width	N.A	N.A	N.A
	Width of internal road	N.A	N.A	N.A
2	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases			
	Upper Floor	2 nos.	3 nos.	MR
	Basement	2 nos.	2 nos.	MR
	B. Width of Staircases			
	Upper Floor	1.5 m	1.5 m, 1.25 m & 1.05 m	MR
	Basement	1.25 M	1.25 M & 1.05 m	MR
	c. Protection of exits			
	Fire check door	Required	Provided	MR
	Pressurization	N.A	N.A	N.A
	e. No. of continuous staircases to terrace	2 no.	2 nos.	MR
g. Width of Corridor	N.A	N.A	N.A	
h. Door Size	2 m	2 m	MR	
3	Compartmentation.			
	Fire check door	Required	Provided	MR
	Sealing of electrical shafts	Required	Provided	MR
	Fire rating of shaft door	N.A	N.A	N.A
	Water curtain	N.A	N.A	N.A
	Fire Dampers	N.A	N.A	N.A
4	Smoke Management System.			
	Basement	Required	Ventilated	MR
	Upper floor	Required	Ventilated	MR

M/7

5.	Fire Extinguisher			
	Total numbers	08 nos.	10 nos.	MR
	types	CO ₂ & ABC	CO ₂ & ABC	MR
	ISI marking	ISI marked	ISI marked	MR
6	First-aid-Hose Reels.			
	Total numbers	01 no.	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	N.A	N.A	N.A
	Location of main panel	N.A	N.A	N.A
	Location of repeater panel	N.A	N.A	N.A
	Alternate source of power	N.A	N.A	N.A
	Hooters's location	N.A	N.A	N.A
8	MOEFA	Required	Provided	MR
9	Public address System.	N.A	N.A	N.A
10	Automatic Sprinkler System.			
	basement	Required	Provided	MR
	upper floor	Required	Provided	MR
	sprinkler above false ceiling	N.A	N.A	N.A
11	Internal Hydrants			
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants per floor	01 no.	01 no.	MR
	Hose Box	01 no.	01 no.	MR
12	Yard Hydrants.			
	Total number of hydrants	N.A	N.A	N.A
	Hose Box	N.A	N.A	N.A
13	Pumping Arrangements.			
	• Ground Level	N.A	N.A	N.A
	➤ Discharge of main Pump	N.A	N.A	N.A
	➤ Head of Main Pump	N.A	N.A	N.A
	➤ Number of main pumps	N.A	N.A	N.A
	➤ Jockey pump out put	N.A	N.A	N.A
	➤ Jockey pump head	N.A	N.A	N.A
	➤ Standby pump out put	N.A	N.A	N.A
	➤ Standby pump Head	N.A	N.A	N.A
	➤ Auto Starting /Manual stopping	N.A	N.A	N.A
	➤ Pump House Access	N.A	N.A	N.A
	• Terrace Level			
	➤ Discharge of pump	450 LPM	450 LPM	MR
	➤ Head of the Pump	40 m	Provided	MR
	➤ Power supply	Required	Provided	MR
	➤ Auto Starting of pump	Required	Provided	MR

N18

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	N.A	N.A	N.A
	Draw-off connection	N.A	N.A	N.A
	Fire service inlet	N.A	N.A	N.A
	Access to tank	N.A	N.A	N.A
	Overhead Tank capacity	10,000 Liters	10,000 Liters	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	N.A	N.A	N.A
	Pressurization of Lift lobby	N.A	N.A	N.A
	Communication in lift car	N.A	N.A	N.A
	Firemen's grounding switch	N.A	N.A	N.A
	Lift Signage	N.A	N.A	N.A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total area	N.A	N.A	N.A
	Location	N.A	N.A	N.A
19	Fire Control Room			
	Detector system panel	N.A	N.A	N.A
	Flow switch panel	N.A	N.A	N.A
	PA system panel	N.A	N.A	N.A
	Batter backup	N.A	N.A	N.A
	Building Floor Plans	N.A	N.A	N.A
20	Special Fire Protection systems for protection of special Risks, if any:	N.A	N.A	N.A

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The FSC issued vide letter no. F6/DFS/MS/EH/2010/3273 Dated 30/11/10 renewal under the rule 35 of the Delhi Fire Service Rule 2010, is recommended.

R. K. Yadav
14/6/2018

Signature of the Inspecting Officer

Name: R. K. Yadav

Designation: ADO (LN)

DO(ED)

[Signature]
18/6/18
DY CPD/Manu

[Signature]