## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2018/ 1 49 (

Dated: 26/6/18

## FIRE SAFETY CERTIFICATE

Issued on 16/6/18 at New Delhi by.

(VIPEN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- 1. Sh. Arpit Jain (Director), M/s. Guest House J.P. Inn, 5/2, East Patel Nagar, New Delhi- 08.
- 2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi

## Following Fire Safety Directives must be adhered to: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## **INSPECTION REPORT**

1. Name & address of the building

: M/s. guest house J.P. Inn, 5/2, East Patel Nagar, New

Delhi- 110008.

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/2015/SZ/143 dated 02.02.2015.

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 19.06.2018

7. Name of the Inspecting Officers

: M.K. Chattopadhyay, DO(South West)

8. Name and designation of officers

from the building side

: Sh. Anand Kumar (manager)

9. Year of Construction

: 2009-2010

10. Applicant's letter No.

: nil dated 13.06.2018

The said guest house is comprised of basement, ground plus three upper floors.

S. No.		linimum Standards on fire ention and fire safety U/R 33	Fire safety requirements as per letter dt. 02.02.2015	Provided at site	Remarks MR/NMR		
1	Access	to building			- I,-		
	•	Road width	06 mts	Provided	MR		
	•	Gate width	4.5 mts	2.25 mts	MR being old case		
	•	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits						
	a. Num	ber of staircases	-	-			
	•	Upper Floors	Old Case	01	MR being old case		
	•	Basements	02	02	MR		
	b. Wid	th of staircases	-	-	- 101		
	•	Upper Floors	Old case	1.26 mts	MR being old case		
	•	Basements	Old case	1.26, 1.15 mts	MR being old case		
	c. Prote	ection of exits	-	-	-		
	•	Fire check door	N/A	N/A	N/A		
	•	Pressurization	N/A	N/A	N/A		
	e. No. o	f continuous staircases to terrace	01	01	MR		
	g. Widt	h of Corridor	Old case	1.44 mts	MR		
	h. Door	Size	Old case	0.86 mts	MR being old case		
3	Compa	rtmentation.	6				
	•	Fire check door	N/A	N/A	N/A		
	•	Sealing of electrical shafts	N/A	Sealed			
	•	Fire Rating of shaft door	N/A	N/A	N/A		
	•	Water Curtain	N/A	N/A	N/A		
	•	Fire Dampers	N/A	N/A	N/A		
4	Smoke	ke Management System.					
		Basements	30 a/c per hour	Exhaust fan provided	MR		

	Fire Extinguishers					
	Total numbers	14	D			
	<ul> <li>Types</li> </ul>	CO <sub>2</sub> , ABC, WCO	Provided	MR		
_	IS marking	ISI marked	1 Tovided	MR		
	First-Aid Hose Reels.		Provided Provided			
	<ul> <li>Total numbers on each floor</li> </ul>	01	Dues 1 1			
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarm	ing system	Provided	MR		
	Type of detectors	N/A	N/A			
	<ul> <li>Location of Main Panel</li> </ul>		IN/A	N/A		
		N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	Required	D.G. set 62.5 KVA	MR		
0	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	Required	Provided	MR		
10	- 144tomatic Sprinkler System.			IVIIC		
	• Basement	N/A	Provided	Area less than		
	• Upper Floor	N/A	N/A	200 sq. mts.		
	Sprinkler above false ceiling		IVA	N/A		
11	Internal Hydrants	N/A	N/A	N/A		
	Size of riser/down-comer	N/A				
	Number of hydrants per floor		N/A	N/A		
	Hose Box	N/A	N/A	N/A		
	,	N/A	N/A	N/A		
12	Yard Hydrants.			IN/A		
	<ul> <li>Total number of hydrants</li> </ul>	N/A	NI/A			
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.	14/11	N/A	N/A		
	Ground Level					
	Discharge of main Pump	N/A		>T/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A N/A	N/A		
	Jockey Pump out put	N/A		N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A N/A	N/A		
	Standby Pump Head	N/A	N/A N/A	N/A		
	Auto Starting/ Manual stopping	NI/A	N/A N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level	- 1124	IN/A	N/A		

	1	> Power Supply								
	Auto Starting of pump		Required	Provided	MR					
			Required	Provided	MR					
14	Capti	Captive Water Storage for fire fighting.								
	•	Underground tank capacity	N/A	N/A	N/A					
	>	Draw-off connection	N/A	N/A	N/A					
	>	Fire service inlet	N/A	Provided						
	>	Access to tank	N/A	N/A	N/A					
	•	Overhead Tank capacity	Old case	5000 lts	MR, Old case					
15	Exit Signage.		Required	Provided	MR					
16	Provis	Provision of Lifts.								
	•	Pressurization of Lift Shaft	N/A	N/A	N/A					
	•	Pressurization of Lift lobby	N/A	N/A	N/A					
	•	Communication In lift Car	Required	Provided	MR					
	•	Fireman's Grounding Switch	Required	Provided	MR					
	•	Lift Signage	Required	Provided	MR					
17	Standl	y power supply	Required	Provided	MR					
18	Refuge	fuge Area.								
	>	Total Area	N/A	N/A	N/A					
	4	Location	N/A	N/A	N/A					
19	Fire C	re Control Room								
	•	Detector System Panel	N/A	N/A	N/A					
	•	Flow Switch Panel	N/A	N/A	N/A					
	•	PA System Panel	N/A	N/A	N/A					
	•	Battery backup	Required	Provided	MR					
	•	Building Floor Plans	N/A	N/A	N/A					
20	Special Protection	Fire Protection Systems for on of special Risks, if any:	N/A	N/A	N/A					
					10					

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2015/SZ/143 dated 02.02.2015, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Note: All the shortcomings pointed out by this department vide letter No. F6/DFS/MS/GH/2018/SZ/2618 dated 19.06.2018.

DFA is put up for approval & signature please.

778/Dasw) 19.06.2018

Lond

Signature of the Inspecting Officer Name M.K. CHATTOPADHYAY Div. Officer (South West)