FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE [See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2018/WZ/ 1685

Dated: / 8/ 7 /2018

FIRE SAFETY CERTIFICATE

Certified that the Kapo Footwears Pvt. Ltd. at Plot No. H-36, Udyog Nagar Industrial Area, Rohtak Road, New Delhi-41 comprised of Basement, Ground Floor, Mezzanine Floor and First Floor only owned / occupied by Kapo Footwears pvt. Ltd, has already been issued Fire Safety Certificate vide letter No. F6/DFS/MS/2015/WZ/1163 dated 03.07.2015. The premises / Building was re-inspected by the officer concerned of Fire Service on 29.06.2018 in the presence of Sh. Sh. Ashwini Kapoor and found that building / premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building / premises is fit for occupancy class Industrial Group (G) with effect from \$\int \gamma \lambda \lambda \lambda \lambda \rangle \lambda \rangle \lambda \lambda \rangle \text{2018} for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued on 18/7/18 at New Delhi by

CHIEF FIRE OFFICER.

Copy to :-

1. Sh. **Ashwini** Kapoor, Kapo Footwears pvt. Ltd. Plot No. H-36, Udyog Nagar Industrial Area, Rohtak Road, New Delhi-110041.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc. shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provision of building bye laws.
- 6. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Kapo Footwears Pvt. Ltd. Plot No. H-36, Udyog

Nagar Industrial Area, Rohtak Road, New Delhi-41

2. Type of Occupancy : Industrial (Class-G)

Type of Case
 Renewal (Basement + G.F. +Mezz.F.+1st Floor)
 Details of previous NOC
 No.F6/DFS/MS/2015/WZ/1163 dated 03.07.2015

5. Fire Safety directives Letter No.: F6/DFS/MS/BP/86/114 dated 10.02.1986

6. Date of inspection : 29/06/2018

7. Name of the Inspecting Officer: A. K.-Jaiswal

8. Name and designation of Officer

from the building side

: Sh. Ashwini Kapoor

9. Year of Construction : 1992-93

10. Applicant's letter No.: -Nil Dated 12/06/2018

No	Minimum standards on fire prevention and fire safety U/R 33	BBL Require	ments	Provided at site	Remarks MR/NMF		
1.	Access of building						
	Road width	06 mtr		15 mtr.	MR		
	Gate width	4.5 mtr		4.5 mtr	10000 1000 10		
	Width of internal road			3 mtr	MR		
2.	Number, width, Type & Arra		of evite	3 1110	MR		
	a. Number of staircases	ingernents (CAILS	2			
	 Upper floors 	2	2		MR		
	Basements	2			MR		
	b. Width of staircases				IVIN		
	 Upper floors 	1.20	1.20 x 1 & 1.00 x 1		MR (Old Case		
	• Basements	1.20		, 1.20 x1, 0.90 x 2	MR (Old Case)		
	c. Protection of exits	2,20	1.00 X1,	, 1.20 XI, 0.30 X Z	IVIR (Old Case		
	Fire check door	Required		Provided	NAD		
	Pressurization	N/A	-	N/A	MR		
	d. No of continuous	As per		1	N/A		
	staircase to terrace	sanctione	nela h	1	MR		
	e. Width Of Corridor	N/A	u pian	N/A	NI/A		
	f. Door Size	1.00 mtr		1.00 mtr	N/A MR		
3.	Compartmentation			1.00 111(1	IVIK		
	Fire check door	Required		Provided	MR		
-	Sealing of electrical	N/A		N/A			
	shafts	,		IV/A	N/A		
	Fire Rating of shaft door	N/A		N/A	N/A		
	Water Curtain	N/A	ii.	N/A	N/A		
	• Fire Dampers			14//	IN/A		
	Smoke managements System						
	Basements	Required		Provided	MR		
-	• Upper floors	N/A		N/A	N/A		
-				.,,,,	IN/A		
.]	Fire Extinguishers						
	 Total numbers 	8		15	MR		
	• Types	ISI marke		Provided	MR		
	IS marking	Required	2	Provided	MR		
		OK.S					

	each floor		1	IVIK
	 Length of hose reel hose 	30 mtr	30 mtr	MR
	Nozzle diameter	5 mm	5 mm	MR
7	. Automatic fire detection and	l alarming system		
	Type of detector	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater	N/A	N1/0	
	Panel	N/A	N/A N/A	N/A
				N/A
	Alternate source of power	N/A	N/A	N/A
•	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10	Sprinkler System		·	,
	• Basements	Required	Provided	MR
	Upper Floor	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-	N/A	NI/A	1 21/2
	comer	14/7	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	 Total number of 	N/A	N/A	N/A
	hydrants			
13.	Hose Box	N/A	N/A	N/A
***************************************	Pumping Arrangements			
	Ground Level Discharge of main nump	N/A	1	
	Discharge of main pumpHead of main pump	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A
	Jockey pump out put	N/A	N/A	N/A
-	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
,	Auto Staring/Manual	N/A	N/A	N/A N/A
	stopping		14/74	IN/A
)	Pump House Access	N/A	N/A	N/A
6	TOTTAGE TEVEL			
>	- isomarge or pump	900 Lit/min.	900 Lit/min.	MR
,	Trade of the pamp	30 mtr.	30 mtr.	MR
,	Power supply	Required	Provided	MR
	- Starting of pump	Required	Provided	MR
14.	Captive water Storage for fire fi	ghting		-
	 Underground tank capacity 	50,000 lts.	50,000 lts.	M/R
	Draw of connection	Required	Provided	M/R
	Fire service inlet	Required	Provided	M/R
	Access to tank	Required	Provided	NA/P

15	Exit Signage	Required	Provided	M/R	
16.	Provision of Lifts				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of lift lobby	N/A	N/A	N/A	
	Communication in lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
7.	Standby power supply	Required	Provided	MR	
8.	Refuge Area	N/A	N/A	14117	
-	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
9.	Fire control room				
_	Detector system panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
-	PA System Panel	N/A	N/A	N/A	
-	Battery backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
3	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring has also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/2015/WZ/1163 dated 03.07.2015 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

Signature of the Inspecting Officer Name

: Ashok Kumar Jaiswal Designation: A.D.O. (Jwala Puri)