GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DLEHI - 110 001

No. F.6/DFS/MS/Business/SZ/2018/ [67]

Dated: 16/7/18

FIRE SAFETY CERTIFICATE

Certified that the Office Block (Tower-3), Kidwai Nagar(East) for GPRA, New Delhi-110023comprises of three tier Basement, Ground & FourUpper Floors was inspected by the officer concerned of this department on 06/07/2018in the presence of Sh.Mahaveer (Project Manager)and found that the said office blockbuilding (excluding basements)have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group-B (Business)" with effect from -1-6-7-7-1-2018 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to:-

1. The Executive Engineer, (Bldg.), NDMC, Palika Kendra, New Delhi-110002.

2. Sh. N J Kaul, GM (Engg.), Project office- Redevelopment of Kidwai Nagar (East), Aurobindo Marg, Near INA Metro Station, Kidwai Nagar (East), New Delhi-110023

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 7. Basements underneath of Office Block-3 shall not be occupied or used till the receipt of its clearance/FSC from DFS as undertook by NBCC vide its letter no. NBCC/EKN-Office Block-3/GM/DFS/2018/584 dated 14/05/2018.
- 8. NBCC shall ensure that internal layout/fire prevention & fire safety measures as and when carried out by the tenants/occupiers are in conformity with provision of UBBL/NBC as undertook by itvide letter no. NBCC/EKN-Office Block-3/GM/DFS/2018/584 dated 14/05/2018and plans of the same shall be submitted to this department on compliance for record.

1. Name& address of the building: Office Block (Tower-3), Kidwai Nagar(East) for GPRA, New Delhi

2. Type of Occupancy : Class-E "Business" : New Office Block (1)

3. Type of Case : New [Office Block (Tower-1): 3 tier Basement*, G. Floor+4Upper floors]

4. Details of Previous NOC : NA

5. Fire Safety directives letter No : F6/DFS/MS/BP/2013/196 dated 16/07/2013

6. Date of inspection : 06/07/2018
7. Name of Inspecting Officer : A. K. Malik

8. Name and designation of officers

From the building side : Mr. Mahaveer (Project Manager)

9. Year of Construction : 2018

10. Applicant's letter No. : Outdoor diary no. 9125 dated 22/06/2018

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building						
	Road width	12m	12m	MR			
	Gate width	NA	NA	NA			
	Width of internal road	6m (Two side)	Provided	MR			
2.	Number, Width, Type & Arrangement						
	a. Number of staircases						
	Upper Floors	3 Nos	Provided	MR			
	Basements	NA*	NA	NA			
	b. Width of staircases			1			
		1.5m	2.3m, 1.5m & 1.5m	MR			
	Upper Floor	NA*	NA	NA			
	Basements						
	c. Protection of exits	Required	Provided	MR			
		Required	Natural Ventilation	MR			
	Fire check door	2 Nos	Provided	MR			
	• Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace			MR			
	e. Width of Corridor	1 m	Provided (final exit)	IVIIX			
	f. Door Size		a see ge				
3.	Compartmentation						
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Provided	MR			
		Required	Provided	MR			
	 Fire Rating of shaft door 	NA*	NA	NA			
	Water Curtain	Required	Provided	MR			
4	• Fire Dampers	1					
4.	Smoke Management System	NIAY	NIA	NIA			
	Basements	NA*	NA	NA			
	• Upper floors	12 a/c per hour		MR			
27			Ventilation#				
5.	Fire Extinguishers						
	 Total numbers 	30 No's	Provided	MR			
	• Types	ABC/ W. CO ₂ /CC		MR			
	IS marking	ISI	Yes	MR			
6.	First-Aid Hose Reels						
	 Total numbers on each floor 	Three	Provided	MR			
	 Length of hose reel hose 	30m _	Provided	MR			
	Nozzle diameter	5mm	Provided	MR			
7.	Automatic fire detection and alarming system						
	Type of detectors	Smoke & Heat	Provided	MR			
	 Location of Main Panel 	Ground Floor	Provided	MR			
	 Location of Repeater Panel 	-NA-	-NA-	-NA-			

8	Alternate source of power	Required	Provided	MR		
	Hooters' Location	All Area	Provided	MR		
3.	MOEFA	Required	Provided	MR		
).	Public Address System	Required	Provided	MR		
0.	Automatic Sprinkler System		100			
	Basement	NA*	NA	NA		
	 Ground & Upper Floors 	Required	Provided	MR		
	 Sprinkler above false ceiling 	NA#	NA	NA		
11.	Internal Hydrants					
	Size of riser/down-comer	100mm	Provided	MR		
	 Number of hydrants per floor 	03Nos	Provided	MR		
	Hose Box	03Nos	Provided	MR		
12.	Yard Hydrants		-			
	Total number of hydrants	06 Nos	Provided	MR		
	Hose Box	06 Nos	Provided	MR		
13.	Pumping Arrangements		1			
10.	Ground Level [Common Pump Room at B-2 level]					
	Discharge of main Pump	2850LPM	2850LPM	MR		
	Head of Main pump	85m & 40m(WC)	Provided	MR		
	Number of main pumps	3Nos (one is for WC)	Provided	MR		
	Jockey Pump out put	2 of 280 LPM	Provided	MR		
	> Jockey pump head	85m	Provided	MR		
	> Standby Pump out put	2850LPM	Provided	MR		
1	Standby Pump Head	85m	Provided	MR		
	> Auto Starting/Manual Stopping		Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Tump House Recess	Required	Provided	IVIIX		
	Terrace level					
	Discharge of pump	NA	NA	NA		
	Head of the pump	NA	NA	NA		
	> Power Supply	NA	NA	NA		
	> Auto Starting of pump	NA	NA :	NA		
14.	Captive Water Storage					
) (D		
	 Underground tank capacity 	2,00,000 Lts	Provided	MR		
	Draw-off connection	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
	Overhead Tank capacity	20,000 Lts.	Provided	MR		
15.	Exit Signage	Required	Provided#	MR		
16.	Provision of Lifts			T		
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of Lift lobby	Required	Provided	MR		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area					
	> Total Area	NA	NA	NA		
	> Location	NA	NA	NA		
19.	Fire Control Room		Entrance Lobby]			
19.	MOEFA System Panel	Required	Provided	MR		
	Flow Switch Panel	Required	Provided	MR		
	PA System Panel					
	Battery backup	Required	Provided	MR		
	Building Floor Plans	Required	Provided	MR		
	Daniel Brook Fland	Required	Provided	MR		

Office Block (Tower-3), Kidwai Nagar(East) for GPRA, New Delhi

20. Special Fire Protection System for NA* NA Protection of special Risks, if any: NA

Note:-

- 1. The requirement of basement is not generated in the inspection note and are shown with*, since applicant i.e. NBCC vide its letter no. NBCC/EKN-Office Block-3/GM/DFS/2018/584 dated 14/05/2018 (C/76) undertook that Basements underneath of Office Block-3 shall not be occupied or used till the receipt of its clearance/FSC from
- 2. The compartmentation/segregation of basements with ground and upper floors found complied as undertook by NBCC at point no.2 of the letter mentioned above.
- 3. The smoke management system, sprinklers/detectors below false ceiling and other fire prevention & fire safety measures shall be executed by the tenants/occupiers as per NBC as undertook at point no. 3 of above letter and same are marked with # in the inspection

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection. The shortcomings communicated vide letter no. F6/DFS/MS/SZ/2018/2269 dated 23/05/2018 found complied during the inspection. Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules it is recommended under Rule 35(3) of the Delhi Fire Service Rules 2010 to grant Fire Safety Certificate under rule 35(4).

Accordingly form "H" in shape of DFA is put up for approval.

Signature of Inspecting Officer Name: A. K. Malik

Designation: Divisional Officer