FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No: F-6/DFS/MS/Hospital/WZ/2018/ 1406

Dated:) \(\int \) 06/2018

FIRE SAFETY CERTIFICATE

Certified that the building of New Block, MAX Health Care Institute Ltd. Located at FC-50 Shalimar Bagh, New Delhi comprised of Two Basement + Mez. + Ground Floor only owned/ occupied by MAX Health Care Institute Ltd have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 06-06-2018 in the presence of Sh. Inderjeet Kumar (GM Hospital Operation) and that the building / premises is fit for the a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ..., 5.1.96/18.... at New Delhi.

Chief Fire Officer Delhi Fire Service

Copy to:-

Sh. Inderjeet Kumar (GM Hospital Operation), MAX Health Care Institute Ltd FC-50 Shalimar Bagh, New Delhi

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

INSPECTION REPORT

1. Name & address of the building: **New Block**, MAX Health Care Institute Ltd. Located at FC-50 Shalimar Bagh, New Delhi.

2. Type of Occupancy : Institutional (Two Basement Maz + GF)

3. Type of Case : New (Addl/ alteration or Expansion)

4. Details of previous NOC: F6/DFS/MS/Hospital/2016/43 Dated- 09/03/2018

5. Fire Safety directives Letter No.: F6/DFS/MS/Hosp/2018/854 date 09/03/2018

6. Date of inspection : 06-06-2018

7. Name of the Inspecting Officer: DO(W), ADO(WP)

8. Name and designation of Officer

from the building side :Sh Inderjeet Kumar (GM Hospital Operation)

9. Year of Construction : 2016/018

10. Applicant's letter No. : Nil Dated- Nil

0	prevention and fire safety U/R I	BBL Requirements	Provided at site		Remarks MR/NMR		
	33			21			
1.	Access of building	12 m	Provided	I	ИR		
	1 Road Width	06 m	provided		MR		
	• Gate width	6 m	provided	N	MR	S	
	Width of internal road		provide	2.7			
2.	Number, width, Type & Arranger	ments of exits			7	y W	
	a. Number of staircases	•		3 ³ 11 11			
	• Upper floors	02			rided	MR	
	Basements	02		Provi	ded	MR	
-	b. Width of staircases		* y				
	Upper floors	2 mtr	Provided		MR		
	Basements	2 mtr	Provided		MR		
	c. Protection of exits						
	Fire check door	Required	Provided		MR		
	 Pressurization 	Required	Provided		MR	5(4)	
	d. No of continuous staircas						
	to terrace				2 1		
	e. Width Of Corridor	2.4m	Provided		MR		
	f. Door Size	2m	Provided		MR		
3.	Compartmentation						
٥.	Fire check door	Required	Provided		MR		
	Sealing of electrical shafe	ts Required	Provided		MR		
	• Fire Rating of shaft door		Provided		MR	7	
	Water Curtain	Required	Provided		MR		
	• Fire Dampers	Required	Provided		MR		
4.	Smoke managements System		8				
	Basements	Required	Provided		MR	-	
	Upper floors	Required	Provided		MR		
5.	Fire Extinguishers				-		
J.	Total numbers	20 nos.	Provided	9	MR		
	• Types	DCP &	Provided		-MR		

0.	THSU	- Alu nose keels				
		Total numbers on each		02	Provided	MR
		floor		30 m	Provided	MR
		Length of hose reel hose	<u>a</u>	5 mm	Provided	MR
-		Nozzle diameter			Tioviaca	IVIIC
7.	Autor	natic fire detection and ala	armir	a system		
/ -	Tutoi				Dunnidad	MD
		Type of detectors	Smoke & Heat		Provided	MR
	•	Location of Main	Gro	ound floor	Provided	MR
		Panel	_	1.0		
	•	Location of Repeater	Eac	ch floor	Provided	NR
		Panel				
	•	Alternate source of	Rec	quired	Provided	MR
		power				- ,
	× •	Hooters' Location	Rec	quired	Provided	MR
					Strategic	
	3				location	
8.	MOE	FA	Rec	quired	Provided	MR
9.	Public	Address System	-	quired	Provided	MR
10.		natic Sprinkler System	1100	Į dili v d	TTOTIGEG	IVIIC
		Basements	Rec	quired	Provided	MR
					Provided	
	•	Upper Floor		quired		MR
	•	Sprinkler above false	NR		NR	NR
		ceiling				
11.	Intern	al Hydrants:				
	1	2			V	
	•	Size of riser/down-	150	mm	Provided	MR
		comer			*	
		Number of hydrants	Rec	luired	Provided	MR
	8	per floor				
		Hose Box	Rec	uired	Provided	MR
12.	Vord I		Tree	unca	TTOVICCU	IVIIX
12.	1 aru 1	Hydrants	0.6	14	T	
	•	Total number of	06		Provided	MR
	,	hydrants				
	•	Hose Box	06	# X	Provided	MR
13.	Pumpi	ing Arrangements: Comm	ion v	vith existing	arrangement	
	•	Ground Level				
		Discharge of main	228	0 lpm	Provided	MR
		pump		•		
	>	Head of main pump	120	m	Provided	MR
,		Number of main	2		Provided	MR
		pumps	_		Tiovided	14117
	>	Jockey pump out put	120	lpm	Provided	MR
	>	Jockey pump head	120		Provided	
	>	Standby Pump out put				MR
	>	Standby Pump Head		0 lpm	Provided	MR
	>	Auto Staring/Manual	120		Provided	MR
			Req	uired	Provided	MR
- 15	_	stopping				
		Pump House Access	Req	uired	Accessible	MR
	•	Terrace level				
d	A	Discharge of pump	NA	22	NA	NA
		Head of the pump	NA		NA	NA
		Power supply	NA		NA	NA
	>	Auto starting of pump	NA		NA .	NA
14.	Cantiv	ve water Storage for fire fi		g. (Terraca		
- 1	compa	rised of 2Basement, Ma	7 + C	Eround Floo	r ank not prov	idea as building
	Compi					MD
		Under ground tank	2,00	0,000 litre	Provided	MR
		capacity	D			
	1	Degree off				
	>	Draw off connection	-	uired	Provided	MR
		Draw off connection Fire service inlet Access to tank	Req	uired uired	Provided Provided	MR MR

		. 1	Provided	MR
1	Exit Signage	Required	1100100	
	Provision of Lifts			
5. I		. 1	Provided	MR
	Pressurization of Lift	Required	110 / 10	
	Shaft	D inad	Provided	MR
	> Pressurization of lift	Required		
	lobby	Required	Provided	MR
	Communication in lift	Required		- m
	Car	Required	Provided	MR
	Fireman's Grounding	Required		1 N (D)
	Switch	Required	Provided	MR
	> Lift Signage		Provided	MR
·	Standby power supply	Required	Provided	
17.				NA
18.	Refuge Area	NA	NA	NA
_	> Total area	NA	NA	1112
	Location		1 1 1	MR
19.	Fire control room Detector system panel	Required	Provided	MR
	> Flow Switch Panel	Require	Provided	MR
	> PA System Panel	Required	Provided	MR
	- la algun	Required	Provided	MR
	Battery backupBuilding Floor Plans	Required	Provided	NR
	. I.F. Duetoction	NR	NR	
20	Systems for Protection of			
	special Risks, if any;			
	special Kisks, if any,	•	1 Luilding	were test checked a

The fire protection systems provided in the building were test checked and

found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire prevention and fire safety required under the Delhi Fire Service Rules 2010/issue Safety Certificate under rule 35 of the Delhi Fire Service Rules numbers shortcomings as noted at serial numbers

.....NIL....

Signature of the Inspecting Officer

Signature of the inspecting offi

Name UdaiVir Singh

Designation ADO/WP

Name Sh Mukesh Verma

Designation DO/West

CAO WALLANDER

FO (NY) 4.7. 1656 is put up for signature place.

The Way 400 11/4/12