## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/School/2018/SZ/

Dated: 07/06/18

## **FIRE SAFETY CERTIFICATE**

(Vipin Kental)
Chief Fire Officer

Copy to:-

1. Dy. Director, Education) Govt. of NCT of Delhi, Old Secretariat, New Delhi-54.

2. Authorized Signatory, Presidium (Mother's Pride) School (Sant Namdev Education Society) located at Sector-6, Dwarka, New Delhi.

## **CONDITIONS**

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

ADO PWARS

	IN	SPECTION REPO	RT			
4 - 1	f the a building	Presidium (Mother's Pr	ide) School (S	Sant Namdev E	ducation	
1	Valle & address of the same 5	Society) Sector-6, Dwarka, New Delni.  Educational Building "B"				
2	Type of Occupancy					
	Type of case	New Ground plus three upper floors				
		Nil	1016 dated 28	8 11 2003 / DOE	Circular 262-	
-		F6/DFS/MS/BP/2003/1916 dated 28.11.2003 / DOE Circular 262- 362 dated 17.1.2005				
	Date of inspection	10.5.2018				
0	Name of the inspecting Officers :	ADO S.P. Bhardwaj				
	Name and designation of officers					
8	from the building side	Sh. Abhishek (Admin.)				
	Year of construction	2007 Ground plus three upper				
	Applicant's letter No.	Nil dated 16.4.2018  Nil dated 16.4.2018  Nil dated 16.4.2018  Nil dated 16.4.2018		ment & one floor are closed		
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/ DOE Circular dated 17.1.2005	Provi	ded at site	Remarks MR / NMR	
1	Access to building				B 4 D	
1	1) Road width	6 Mtrs.	12 Mtrs.		MR	
	· ·	6 Mtrs.	6 Mtrs.		MR	
	2) Gate width		N/A		N/A	
	3) Width of internal road	N/A	IV/A			
2	Number, width Type & arrangement of	exits				
	a. Number of staircases		0.11		MR	
	1. Upper floors	2 Nos.	2 Nos.			
	2. basements	2 Nos.	Closed (Un	dertaking)	Closed	
	b. Width of staircase					
		1.50 Mtrs	1.50 Mtrs.	en <sup>15</sup>	MR	
	1. Upper floors		Closed (Un	dertaking)	Closed	
	2. basements	1.50 Mtrs.		0,000 (2,12,2,2,0)		
	c. Protection of exits	NI/A	N/A		N/A	
	1. Fire check door	N/A	N/A		N/A	
	2. Pressurization	N/A			MR	
	d. No. of continuous staircase terrace	2 Nos.	Provided		3.0	
	e. Width of corridor	1.50 Mtrs.	Provided	1	MR	
	f. Door size	1 Mtr.	Provided		MR	
	Compartmentation.			:		
3	1. Fire check door	N/A	N/A		N/A	
	2. Sealing of electrical shafts	N/A	N/A		N/A	
	Sealing of electrical sharts     Fire Rating of shaft door	N/A	N/A		N/A	
	And the second s	N/A	N/A		N/A	
	4. water curtain	N/A	N/A		N/A	
	5. Fire dampers  Smoke Management system.					
4	basement	NUA	Closed		Closed	
and the state of t		N/A	Natural V	/entilation	MR	
	upper floors Fire Extinguishers					
5		40.11 0000 000	Provided		MR	
The second second	total numbers	16 Nos. CO2 OR ABC	CO2 & A	BC	MR	
C. C	Types	ISI Marked			MR	
		.5151	Provided		IVIIX	

		MIT					
6	First-Aid Hose Reels.						
	total numbers on each floor	One	One	MR			
	Length of Hose reel hose	36 Mtrs.	36 Mtrs.	MR			
	Nozzle Diameter	5 mm	5 mm	N/A			
7	Automatic fire detection and alarming system						
	Type of detectors	N/A	N/A	N/A			
	location of Main Panel	N/A	N/A	N/A			
	location of Repeater panel	N/A	N/A	N/A			
>	Alternate source of power	N/A	N/A	N/A			
	hooter's location	N/A	N/A	N/A			
8	MOEFA	N/A	Provided	N/A			
9	Public Address System.	Required	Provided	MR			
10	Automatic Sprinkler System.						
	basement	Required	Closed	Closed			
	upper floors	N/A	N/A	N/A			
	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	Size of riser/down-corner	100 mm	100 mm	MR			
	Number of Hydrants per floor	One	One	MR			
	hose Box	Required	Provided	MR			
12	Yard Hydrants.			Lill Males			
	total number of hydrants	N/A	N/A	N/A			
	hose box	N/A	N/A	N/A			
13	Pumping arrangements						
	1. Ground level						
	a. Discharge of main Pump	N/A	N/A	N/A			
	b.Head of main pump	N/A	N/A	N/A			
	c.Number of main pumps	N/A	N/A	N/A			
	d.jockey pump out put	N/A	N/A	N/A			
	e.jockey pump head	N/A	N/A	N/A			
	f. Standby Pump output	N/A	N/A	N/A			
	g.Stanby Pump head	N/A	N/A	N/A			
	h.Auto Starting/Manual stopping	N/A	N/A	N/A			
	pump house access	N/A	N/A	N/A			
	2.Terrace level						
	a. Discharge of pump	900 & 450 LPM	Provided	MR			
	b. head of the pump	40 Mtrs.	Provided	MR			
	c. Power supply	Required	Provided	MR			
	d. Auto starting of pump	Required	Provided	MR			
4.4	2						
14	Captive water storage for fire fighting	5000011	5000011	Tub			
	Underground tank capacity      Draw off compacting	50000 Ltrs.	50000 Ltrs.	MR			
	a. Draw-off connection	N/A	N/A	N/A			
	b. fire service inlet	Required	Provided	MR			
	c.Access to tank	Required	Provided	MR			
15	Over head tank Capacity	20000 Ltrs.	20000 Ltrs.	MR			
16	Exit Signage. Required Provided MR						
16	Provision of lifts.			1.172			
	a. Pressurization of lift shaft	N/A	N/A	N/A			
	b. pressurization of lift lobby	N/A	N/A	N/A			
	c. communication in lift car	Required	Provided	MR			
	d. Fireman's grounding switch	Required	Provided	MR			
	e. Lift signage	Required	Provided	MR			

		1.00	MA		
			Dequired	Provided	MR
17	Standby power	er supply	Required	Not Required	· ·
18	Refuge Area.				
	total area				
	location			\ •	
19	Fire control r	oom	1.110	N/A	N/A
	a. detector sys	stem Panel	N/A	N/A	N/A
	b. Flow switch		N/A	N/A	N/A
	c. PA system		N/A	N/A	N/A
	d. Batter back		N/A	N/A	N/A
			N/A	ricks, if any: CO2 Fire Exting	quisher provided
20	Special Fire	Protection systems for pr	otection of special	risks, if any: CO2 Fire Exting	MR
	near electric	panel/Meter			
					· The

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings vide letter no. F6/DFS/MS/2007/632 dated 2.3.2007 found rectified.

Note: - Seating arrangement of 350 seats in Open Court is provided with two exits of 2 Mtrs. & 4 Mtrs.

Keeping in view compliance of minimum standards on fire prevention and fire safety requirements as per guidelines vide letter dated 28.11.2003 DOE Cir. Dated 17.1.2005, Issuance of Fire Safety Certificate is recommended

Accordingly DFA is put up for approval and signature please

ADO (Dwarka)

Put up inspedien report as per DRS Act 2007 & Pulu 2010 as you have mentioned in FSC and Set Him School is Comes under the purview of DF Act.

ADO (Jame)

Str. Please puruse spe at 'C'side dated 2.3. 2007, which were would under guidding dated 28/11/2003 and restioned DOF letter dated 17.1.2005 Now place quide the Care more be Considered as four old rules or as pur Act & new rules.

Submiffed flear dus.