GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/EH/2018/SZ/

Dated: 18/06/18

FIRE SAFETY CERTIFICATE

Certified that the M/S Drink 'N' Dine Restaurant located at Supreme Plaza, Shop No. 5,6,7, Plot No-15,16, Sector-6, Dwarka, New Delhi-110075, is running at third floor of the building comprised of ground plus three upper floors was issued Fire Safety Certificate this department vide letter by F6/DFS/MS/EH/2015/SZ/919 dated 3.6.2015. The premises have been re-inspected by the officer concerned of this department on 11.6.2018 in presence of Sh. Anil Singh Negi (Manager) and found the premises have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010, and that the building is fit for occupancy class D "Assembly building ("Restaurant") with effect from..... for a period of three years subject to compliance of the conditions printed overleaf.

(Vipin Kental) Chief Fire Officer

Copy to:-

1. DHO/West Zone, Deputy Health Office, SDMC, Najafgarh Zone, New Delhi.

2. Proprietor, Drink 'N' Restaurant, third floor, Supreme Plaza, Shop No. 5,6,7, Plot No-16, Sector-6, Dwarka, New Delhi-110075.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

Do Dunte

		INSPECTION REPORT		
1	Name & address of the building	M/S Drink 'N' Dine Restaura	ant, Supereme Plaza	a,Shop
1	Name & address of the bananing	No.5,6,7, Plot No. 15-16, S	ector-6, Dwarka, Ne	w Deini-
7		110075		
2	Type of Occupancy	Assembly "D" Restaurant		
			9	
3	Type of case	Renewal		
	But all as are wisus NOC	No. F-6/DFS/MS/EH/2015/	SZ/919 dated 3.6.20)15
4	Details of previous NOC			
5	Fire safety directives letter No	letter dated17.3.2008		
	Date of inspection	11.6.2018		
6)warka	
7	Name of the inspecting Officers :	ADO S.P Bhardwaj ADO Dwarka		
	Name and designation of officers	Sh. Anil Singh Negi (Mana	iger)	
8				
	from the building side			
		Before 2006	Restaurant Runin	ig at 3rd Floor
9	Year of construction	Delote 2000	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
				Fleen
10	Applicant's letter No.	Nil Dated 13.5.2015	Ground + 3 up	oper Floors
		NDC Dequirement/	Provided at site Remarks	
S. NO.	Minimum Standards on fire	NBC Requirement/ letter dated 17.3.2008	Flovided at oits	MR / NMR
	prevention and fire safety U/R 33	letter dated 17.5.2000		
	Access to building			
1	1) Road width	9 Mtrs.	Provided	MR
	2) Gate width		Diect accesible	MR
	2) Gate Width	4.5 Mtrs.	from road	
	3) Width of internal road	N/A	N/A	N/A
2	Number, width Type & arrangeme	ent of exits		
4	a. Number of staircases		Ono	MR
	1. Upper floors	Old Case	One N/A	N/A
	2. basements	N/A	IN/A	1477
	b. Width of staircase	4.05.845	4 OF Mtro	MR
	1. Upper floors	1.25 Mtr.	1.25 Mtrs.	N/A
	2. basements	N/A	IN/A	
3	c. Protection of exits	NI/A	N/A	N/A
	1. Fire check door	N/A N/A	N/A	N/A
:	2. Pressurization		One	
	d. No. of continuous staircase	to Nequied		
	e. Width of corridor	1.42 Mtr.	1.42 Mtrs.	MR
	e. width of corndo		2 Mtrs.	MR
	f. Door size	90 x 210 Cms.	Z IVILIS.	
3	Compartmentation.		121/0	N/A
3	1. Fire check door	N/A	N/A	N/A N/A
	2. Sealing of electrical shafts	N/A	N/A	N/A
4	3. Fire Rating of shaft door	N/A	N/A N/A	N/A
	4. water curtain	N/A	N/A	N/A
	5. Fire dampers	N/A	IN//A	
4	Smoke Management system.			N/A
	basement		N/A	IN/A
		12 a/c per hour		
			Natural Ventilate	d MR

	total numbers			
	Types		4 Nos	MR
	ISI Marked	ISI Marked	ABC, CO2,	MR
6	First-Aid Hose Reels.	TOT Warked	Yes	MR
	total numbers on each floor	1 No.	-	
	Length of Hose reel hose	30 m	1 No.	MR
	Nozzle Diameter	E mana	30 Mtrs.	MR
7	Automatic fire detection and a	larming eveters	5 mm	MR
	Type of detectors			
	location of Main Panel	Required	Smoke & Hea	
	location of Repeater panel	Required	Near Main Ga	te MR
	Alternate source of power	N/A	N/A	N/A
	hooter's location	Required	DG Set 62.5 K	CVA MR
8	MOEFA	Required	Near Main Gar	te MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.	Required	Provided	MR
	basement			1
	basement	N/A	N/A	N/A
	upper floors	Required	Provided in	
			restaurant area	MR
11	sprinkler above false ceiling Internal Hydrants	N/A	N/A	N/A
	Size of ricor/days			
	Size of riser/down-corner	100 MM	100 MM	MR
	Number of Hydrants per floor	One at 3rd floor	One at 3rd floo	
12	hose Box	Required	Provided	MR
14	Yard Hydrants.		7 7 7 1 4 5 4	IVII
	total number of hydrants	N/A	N/A	N/A
10	hose box	N/A	N/A	
13	Pumping arrangements		14/1	N/A
	1. Ground level/			
	a. Discharge of main Pump	N/A	N/A	N1/A
	b.Head of main pump	N/A	N/A	N/A
	c Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A		N/A
	e.jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
19	g.Stanby Pump head	N/A	N/A	N/A
Ī	h.Auto Starting/Manual stopping	N/A	N/A	N/A
1	pump house access	N/A	N/A	N/A
	2.Terrace level	IN/A	N/A	N/A
		450 400 :		
a	a. Discharge of pump	450, 180 Lpm.	450,180 Lpm.	MR
b	p. head of the pump	30 Mtrs.	0.0	
- 1	c. Power supply		30 Mtrs.	MR
		Required	Provided	MR
	d. Auto starting of pump	Required	Provided	MR
A E	Captive water storage for fire			IVIIX
	ighting			** z
1	. Underground tank capacity	N/A	N/A	NIA
а	. Draw-off connection	N/A	N/A	N/A
	. fire service inlet	N/A	N/A	N/A
	.Access to tank	N/A		N/A
0	over head tank Capacity	Old Case	N/A	N/A
5 E	xit Signage.	Required	5000 Itrs.	MR
6 P	rovision of lifts.	required	Provided	MR
a.	Pressurization of lift shaft	N/A		
b.	pressurization of lift lobby		N/A	N/A
C	communication in lift car	N/A	N/A	N/A
d	Fireman's grounding switch	Required	Provided	MR
u.	mornan a grounding switch	Required	D	

17	Standby power supply	Required	Provided	MR
18	Refuge Area.	Not Required		
	total area			
	location			
19	Fire control room		Y	
	a. detector system Panel	N/A	N/A	N/A
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup	N/A	N/A	N/A
	e. Building floor plans	N/A	N/A	N/A
	Special Fire Protection system	me for protection of an	solol rioks, if any COO) fine extinguisher
20	Special Fire Protection syste provided near electric panel.	ins for protection of spe	eciai risks, if any: CO2	tire extinguisner

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no.F6/MS/EH/2012/1888 dated 24.5.2015/SZ/919 dated 3.6.2015 is recommended.

Accordingly DFA is put up for approval and signature please.

S.P Bhardwaj ADO (DWARKA)

682/01/SW 12/6/18 12/6/18

200p

12/6/18 1034 15/6/06/52

Cho 174 Missell

14/6 14/6

PT is put up for Signalu plu

Cforsy Miscel

MC 1896.

15/61/8