GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2018/SZ/ 1396

Dated: 14 06 2018

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls Sr. Sec. School,** Khaira, New Delhi-110043 comprised of two blocks namely Block-A & Block-B. Block-A is having ground floor only and Block-B is having ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2015/SZ/1030 dated 18.06.2015. The school building was re- inspected by the officer concerned of this department on 11.05.2018 in the presence of Smt. Manju Rani (Vice Principal) and found that the Govt. Girls Sr. Sec. School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 14 06 2018 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Principal, Govt. Girls Sr. Sec. School, Khaira, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

and Block-B is naving ground plus one upper floor. INSPECTION REPORT 1. Name & address of the building: Govt. Girls Sr. Sec. School, Khaira, New Delhi-110043 Type of Occupancy Educational 3. Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2015/SZ/1030 dated 18.06.2015 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 11.05.2018 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Smt. Manju Rani (Vice Principal) 9. Year of Construction 1986 onward 10. Applicant's letter No. Ref. no. 08 dated 05.04.2018 Minimum Standards on fire prevention and S. No. Requirement Provided at Remarks fire safety U/R 33 as per FSC dt. MR/NMR site 18.06.2015 1. Access to building Accessible 06 mtrs Road width Provided MR 4.5 mtrs Directly accessible Gate width M/Rfrom road N/A Width of internal road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases **Upper Floors** 02 no.'s in Block-B Provided MR **Basements** N/A N/A N/A b. Width of staircases 150 cms 186 & 208 cms MR Upper Floor N/A N/A N/A **Basements** c. Protection of exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to 150 cms 155 cms MR terrace e. Width of Corridor 98 cms 100 cms MR, being old (Double door) f. Door Size case 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A **Basements** Natural Ventilation Upper floors Required MR provided 5. Fire Extinguishers Total numbers 15 No's Provided MR **Types** ABC/CO₂ type Provided MR ISI marked IS marking ISI marked MR 6. First-Aid Hose Reels N/A Total numbers on each floor N/A N/A Length of hose reel hose N/A N/A N/A NIA

	e detection and anarming system	N/A	N/A	N/A
	of detectors	N/A	N/A	N/A
	on of Main Panel	N/A	N/A	N/A
	on of Repeater Panel ate source of power	N/A	N/A	N/A
	rs' Location	N/A	N/A	N/A
8. MOEFA	is Location	N/A	N/A	N/A
CALCO I	es System	N/A	Provided	N/A
	orinkler System	N/A	N/A	N/A
Baser		N/A	N/A	N/A
	nd Floor	N/A	N/A	N/A
	kler above false ceiling	11/12		
11. Internal Hyd	of riser/down-comer	N/A	N/A	N/A
	ber of hydrants per floor	N/A	N/A	N/A
Num Hose		N/A	N/A	N/A
	number of hydrants	N/A	N/A	N/A
	Box	N/A	N/A	N/A
	and Level			
	ond Level Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put		N/A	N/A
> .	Jockey pump head	N/A	N/A	N/A
>	Standby Pump out put	N/A		N/A
>	Standby Pump Head	N/A	N/A	
>	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access			
	race level	N/A	N/A	N/A
	Discharge of pump Head of the pump	N/A	N/A	N/A
	Power Supply	N/A	N/A	N/A
	Auto Starting of pump	N/A	N/A	N/A
14 Cantive W	ater Storage for fire fighting			
		N/A	N/A	N/A
• Un	derground tank capacity Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	verhead Tank capacity	N/A	N/A	N/A
		N/A	N/A	N/A
				(No Lift)
16. Provision		N/A	N/A	N/A
• Pr	essurization of Lift Shaft		N/A	N/A
• Pr	ressurization of Lift lobby	N/A N/A	N/A	N/A
	ommunication In lift Car	N/A	N/A	N/A
• L:	ift Signage	N/A	N/A	N/A
17. Standby	power supply	N/A	N/A	N/A
18. Refuge A	rea.		Lux II majawa	
	Total Area	N/A	N/A	N/A
	otal Area ocation	N/A	N/A	N/A

9.	Fire Control Room	N/A	N/A	N/A
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Battery backup Building Floor Plans	N/A	N/A	N/A
	Dunding 1 1001 1 11111	14/71		
20.	Special Fire Protection System for Protection of	N/A	N/A	N/A
∠ ∪ •	special Risks, if any:			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2015/SZ/1030 dated 18.06.2015 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

484 DOCSW) 28/05/18

Divisional Officer (South West)

miscell by

F.T. leter is put up der signatur please.

CRO CSES mccoll W