GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F6/DFS/MS/School/2018/NDZ/

1420

Dated: 13/06/18

FIRE SAFETY CERTIFICATE

(Vipin Kental)
Chief Fire Officer
Delhi Fire Service

To,

The Manager, Green Garden Public School, 287, Main Road, Brahmpuri, Ghonda, Delhi-53.

Copy:-

The Director of Education, Udyog Sadan, Plot No.419, FIE, Patparganj Industrial Area, Delhi-110092.

- Conditions -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

1.Name & address of the building : Green Garden Public School, at 287, Main Road,

Brahmpuri, Ghonda, Delhi-53.

2. Building is comprised of : G+2 (school is running at ground plus Ist loor only &

2 nd floor use for owner)

e service of

3.Type of Occupancy : Educational

4.Type of Case : New

5.Details of Previous NOC letter : Nil

6. Fire Safety direction letter No : F.16/Estate/CC/Fire Safety/2011/3298 to

3398 dt. 01/03/11

7. Date of Inspection : 30/05/18

8. Name of the Inspecting officers : ADO R.K. Yadav

9. Name and designation of Officer:

from the building side : Sh. B.S.Tomar (Manager)

10.Year of Construction : 1990

11.Applicant's letter no. : 18/05/18

S.	Minimum Standards on fire prevention	Circular	Provided	Remarks		
V	and fire safety U/R33	Requirement	at Site	MR/NMR		
	Access to building					
	Road width	06 m	10 m	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases		- P. W			
	 Upper Floor 	1 no.	1 no.	MR		
	 Basement 	N/A	N/A.	N/A		
	B. Width of Staircases		5 ² N E			
	Upper Floor	1.0 m	1.0 m	MR		
	Basement	N/A	N/A	N/A		
	c. Protection of exits		*1	27		
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A	*N/A		
	d. No. of continuous staircases to terrace	1no.	1 no.	MR		
	e. Width of Corridor	N/A	N/A	N/A		
	f. Door Size	1.0 Mtr.	1.0 mtr.	MR		
3	Compartmentation.					
	Fire check door	N/A	N/A	N/A		
	 Sealing of electrical shafts 	N/A	N/A	N/A		
	 Fire rating of shaft door 	N/A	N/A	N/A		
	 Water curtain 	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	*N/A		
4	Smoke Management System.					
	Basement	N/A	N/A	N/A		
	Upper floor	N/A	N/A	N/A		
5.	Fire Extinguishers					
	Total numbers	04 nos.	04 nos.	MR		
	types	ABC /CO ₂	ABC /CO2			
	IS marking	ISI marked	ISI marked	d MR		

6	First-aid-Hose Reels.					
	Total numbers of each floor	N/A	N/A	B1/A		
	 Length of hose reel hose 			N/A		
	 Nozzle diameter 	N/A N/A	N/A	N/A		
7	Automatic fire detection and alarming s	N/A vstem	N/A	N/A		
	Type of detectors					
	 Location of main panel 	N/A	N/A	N/A		
	 Location of repeater panel 	N/A	N/A N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A		
	Hooter's location	N/A		N/A		
3	MOEFA	N/A	N/A	NA		
9	Public address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.	IN/A	N/A	N/A		
	Basement	N/A	N/A	N/A		
-	upper floor	N 1/A				
	sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants	N/A	N/A	N/A		
	size of riser/down-comer	NI/A				
	Number of hydrants per floor	N/A	N/A	N/A		
		N/A	N/A	N/A		
10	Hose Box	N/A	N/A	N/A		
12	Yard Hydrants.					
-	Total number of hydrants	N/A	N/A	N/A		
12	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.		-			
2	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
i	> Head of Main Pump	N/A	N/A	N/A		
-	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
-	Standby pump out put	N/A	N/A	N/A		
	Standby pump Head	N/A	N/A	N/A		
	Auto Starting /Manual stopping	N/A	N/A	N/A		
-	> Pump House Access	N/A	N/A	N/A		
+	Terrace Level					
-	 Discharge of pump Head of the Pump 	N/A	N/A	N/A		
-	Trade of the Famp	N/A	N/A	N/A		
	. Give capply	N/A	N/A	N/A		
4	tate starting or partip	N/A	N/A	N/A		
4 (Captive Water Storage for Fire Fighting.	N/A	N/A	N/A		
-	Underground tank capacity	N/A	N/A	N/A		
	Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
E	Overhead Tank capacity	N/A	N/A	N/A		
5 E	Exit Signage.	N/A	N/A	N/A		

16	Provision of Lifts.					
	 Pressurization of Lift Shaft 	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication in lift car	N/A	N/A	N/A		
	Firemen's grounding switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection systems for	N/A	N/A	N/A		
	protection of special Risks, if any:	n				

The fire protection systems provided in the building were tested/checked at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the circularno.F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/11, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting officer

Name- R.K. Yadav Designation- ADO

The inspecting officer should write that
the school is now only at around and the
flan. The owner has purushed an undertaking that the second plan mall not be
used for school purposes as shortcomings

alsoudy bean communicated for