GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2018/SZ/ 1449

Dated: 20 06 2018

FIRE SAFETY CERTIFICATE

Certified that Guest House in the name & style of M/s **Hira Palace** located at Property No. 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi-110076, comprised of ground plus three upper floors (Ground floor- Rec., 1st Floor- 06 guest rooms, 2nd & 3rd floor-05 guest rooms each, Total 16 guest rooms) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 25/05/2018 in the presence of Mr. Manoj Kumar (Manager) of the guest house and that the premises is fit for occupancy class "Residential, Group-A" (Guest House) with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued 2018 at New Delhi by

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to: -

- 1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049
- 2. M/s Hira Palace Guest House, 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi-76

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system.
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

_ * 0	INSPECT	ION REPORT	\		
1	Name & Address of the Building	M/s Hira Palace Guest House, 1010/121, Chauhan			
		Mohalla, Madanpur Khadar, New Delhi-110076			
2	Type of Occupancy	Residential, "Group—A" (Guest House)			
3	Building Comprised of	Ground + 03 upper floors.			
4	Type of Case	New			
5	Details of Previous NOC	Nil	The second secon		
6	Fire Safety Directives Letter No	Nil			
7	Date of Inspection	25-05-2018			
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)			
9	Name & Designation of Officers	Sh. Manoj Kumar (Manager)			
	from the building side				
10	Year of construction	2001 Gd. floor- Reception, 1 st floor- 06 rooms, 2 nd floor- 05 rooms, 3 rd floor-05 rooms, Total=16 G/Rooms			
11	Applicant letter No.	Outdoor diary No. 6303 dated 19.04.2018			
S. No	Minimum standards on Fire Prevention			Remarks	
	and Fire Safety U/R 33	requirements		MR/NMR	
1	Access to Building.			T	
	Road width	9 mtr	Provided	MR	
	Gate width	-NA-	-NA-	-NA-	
	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.				
	a) Number of Staircase		*		
	Upper floors.	One	Provided	MR	
	Basement floor.	-NA-	-NA-	-NA-	
	b) Width of Staircase				
	Upper floors	1.25 mtr	Provided	MR	
	Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits				
	Fire check door	-NA-	-NA-	-NA-	
	Pressurization	-NA-	-NA-	-NA-	
	d) No. of continuous staircase to terrace	One	One	MR	
	e) Width of corridor f) Door size	-NA-	-NA-	-NA-	
3		1 m	1.10m (final exit)	MR	
3	Compartmentation.	NIA	NIA	NIA	
	• Fire check door.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts. Size rating of shaft door. **The rating of shaft door.** **The rating of shaft door.** **The rating of shaft door.** **The rating of shaft door.**	-NA-	-NA- -NA-	-NA-	
	Fire rating of shaft door.Water curtain	-NA-	-NA- -NA-	-NA-	
	• Fire dampers.	-NA-			
4.		-IN/A-	-NA-	-NA-	
7.	Smoke Management system. Basement	30 ACPH	NIA	N.I.A	
			-NA-	-NA-	
	• Upper floors	12 ACPH	-NA-	-NA-	
5.	Fire Extinguishers.				
	Total numbers	08 Nos	10 Nos	MR	
	 Types 	ABC / CO2	ABC & CO2	MR	
	 ISI Marking 	ISI marked	Provided	MR	
6.	First Aid Hose Reels.				
	Total numbers on each floor.	One	Provided	MR	
	• Length of hose-reel hose.	30 mtr	Provided	MR	
	Nozzle Diameter	5 mm	Provided		
	M/s Hira Palace Guest House 1010/121 C1			MR	

M/s Hira Palace Guest House, 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi

7	Automatic fire detection & alarming system.		214	NIA
	Type of detectors	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	
	Hooter's location	-NA-	-NA-	-NA-
3.	MOEFA	Required	Provided	MR
	Public Address System	-NA-	-NA-	-NA-
	Automatic Sprinkler System			-NA-
0.	Basement	-NA-	-NA-	
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
1.	Internal Hydrants.			NIA
1.	Size of Riser/Down-comer	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			NIA
1. 44 •	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.		-	
13.	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		5 11	MR
	Discharge of pump.	450 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	IVIIX
14.	Captive water storage for fire fighting.	711	NIA	-NA-
	 Underground tank capacity. 	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	Provided	MR
	Overhead tank capacity.	5,000 Ltr.	Provided	MR
15.	Exit Signage.	Required	riovided	
16.	Provision of Lifts.	-NA-	-NA-	-NA-
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	 Pressurization of lift lobby. 	-NA-	-NA-	-NA-
	 Communication in lift car. 	-NA-	-NA-	-NA-
	• Fireman's switch.		-NA-	-NA-
	 Lift signage. 	-NA-	Provided	MR
17.	Standby Power Supply	Required	riovided	1111
18.	Refuge Area	NIA	-NA-	-NA
	Total area	-NA-		-NA
	Location M/s Hira Palace Guest House, 1010/121, C	-NA-	-NA-	

M/s Hira Palace Guest House, 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi

19.	Fire Control Room.		Ì	
	Detector system panel.	-NA-	-NA-	-NA-
	Flow switch panel.PA system panel.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection. Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

M/s Hira Palace Guest House, 1010/121, Chauhan Mohalla, Madanpur Khadar, New Delhi

1594/ CPAS3 A. F. T. Letter hust up ten Signature Reace James 1861.