GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.**

No.F.6/DFS/MS/School/2018/SZ / 4 7 9

Dated: 22/6/18

FIRE SAFETY CERTIFICATE

Certified that the Mother Teresa Convent School, RZ-705, Gali No.-4, Sagarpur (Main), Palam Road, New Delhi-110046, comprised of basement, ground floor plus two upper floors having total 18 rooms (Including Class Rooms, Offices, Library & Store etc.) owned/occupied by Mother Teresa Convent School was issued Fire Safety Certificate by this department vide letter F.6/DFS/MS/School/2015/SZ/486 dated 06.04.2015. The School building was re-inspected by the officer concerned of this department on 08.06.2018 in the presence of Sh. Harjeet Singh (Manager) and found that four rooms of tin shed have been constructed for personal use on third floor. The Mother Teresa Convent School have deemed complied the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (Basement, ground floor plus two upper floors) is fit for occupancy class "Educational" for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on. 92/6/18 at New Delhi.

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to:-

- The Manager, 1. Mother Teresa Convent School, RZ-705, Gali No.-4, Sagarpur (Main), Palam Road, New Delhi-110046
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1	Nama	& address of the building: Mother Ter	esa Convent School,	RZ-705, Gali No.	4, Sagarpur
1	. Name c	(Main), Pal	am Road, New Delhi	i-110046.	
2	2. Type of	f Occupancy : Educations	d		
3	3. Type o	f Case : Renewal	10015/07/	196 datad 06 04 20	115
4	1. Details	OITIONICUST	IS/School/2015/SZ/4	186 dated 00.04.20	713
		fety directives letter No : N/A : 08.06.2018			
		mspection	ndeep Duggal		
	7. Name	of Inspecting Officer : A.D.O. Sar and designation of officers	Idoob Daggar		
	8. Name a	he building side : Sh. Harjee	t Singh (Manager)		
	Vear o	f Construction : 2006			
		ant's letter No. : Nil dated	12.06.2018		
No.	Minimu	m Standards on fire prevention and	Requirement as	Provided at	Remarks MR/NMR
110.		y U/R 33	per FSC dt. 06.04.2015	site	WIR/NWIR
		1 111	00.04.2015		
	Access to	o building			
		Road width	Accessible 6 mtrs	5.5 mtrs	MR, being old case
		Gate width	4.5 mtrs	Directly accessible from road	MR N/A
		Width of internal road	N/A	N/A	IVA
N - 4				11/12	-
	Number	, Width, Type & Arrangement of Exit	.5	A Table	
	AT1	per of staircases			
	a. Numb	Upper Floors	02 No's	02 No's	MR
		Basements	02 No's	02 No's	MR
		Basements	021103		
	b Widtl	h of staircases	150 cms/additional	96 & 68 cms	MR, being old
	0. 11.00	Upper Floor	staircase of 75 cms	90 & 00 cms	case
			if less than 150 cms	10.00	MD hains old
		Basements	150 cms/additional staircase of 100 cms	95 & 93 cms	MR, being old
	c. Prote	ection of exits	if less than 150 cms		case
		Fire check door	N 1000 Union		
	•	Pressurization	N/A	N/A	N/A
			N/A	N/A	N/A
		of continuous staircases to	14/71		
	terra	ace Ith of Corridor	Required	Two	MR
	e. Wic	IIII of Corridor	150 cms	200 cms	MR
	f. Do	or Size			MR, being old
	1. Do		100 cms	88 cms	case
		The state of the s			Casc
3.	Comp	artmentation	The factor		NT/A
19	•	Fire check door	N/A	N/A	N/A
		Sealing of electrical shafts	N/A	N/A	N/A
		Fire Rating of shaft door	N/A	N/A	N/A
		Water Curtain	N/A	N/A	N/A
	•	Fire Dampers	N/A N/A	N/A	N/A
3	DR		IVA		
4.	Smok	Management System		Exhaust fans	MR
	•	Basements	Required	are provided	
	-		D	Natural	MR
	•	Upper floors	Required	ventilation	
		The second secon	5 1 W T 5 1 N S	Ventracion	
5.	Fire F	extinguishers			
		Total numbers	06 no.'s	Provided	MR
	•		ABC/CO ₂ type	Provided	MR
	•	Types	ISI marked	ISI marked	MR
	•	IS marking	131 marked		
6.	First-	Aid Hose Reels		Provided	MR
		Total numbers on each floor	One	Provided	MR
		Length of hose reel hose	30 mtrs 5 mm	Provided	MR
		Nozzle diameter			

INSPECTION REPORT

	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	
	Location of Repeater Panel	N/A		N/A
	Alternate source of power	N/A	N/A N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A N/A
10.	Automatic Sprinkler System		14/11	IN/A
	• Basement	N/A	Provided	N/A
	Ground Floor	N/A	N/A	N/A
11.	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			IVA.
	• Size of riser/down-comer	N/A	100 mm	N/A
1	Number of hydrants per floorHose Box	N/A	One	N/A
12.	Yard Hydrants	N/A	One	N/A
I.M.				
	Total number of hydrants	N/A	N/A	N/A
13.	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	AND THE PARTY OF T		- 1/4
	• Ground Level		12.44	
	Discharge of main Pump Head of Main pump	N/A	N/A	N/A
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A
	> Jockey Pump out put	N/A	N/A	The same of the sa
	Jockey pump head	N/A		N/A
	Standby Pump out put		N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A.	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level	9 1		
	Discharge of pump	450 LPM	450 LPM & 180	MR
	> Head of the pump	40	LPM provided	IVIIC
	Power Supply	40 mtrs	Provided	MR
	Auto Starting of pump	Required	Provided	MR
		N/A	N/A	N/A
14.	Captive Water Storage for fire fighting		· · · · · · · · · · · · · · · · · · ·	
	 Underground tank capacity Draw-off connection 	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
*1	- upaony	10,000 ltrs	4000 ltrs	MR, being old case
5.	Fyit Signage		Provided	mit, boing old case
.J.	Exit Signage.	Required	Provided	MR
6.	Provision of Lifts.			No I : G
	Pressurization of Lift Shaft	N/A	N/A	No Lift N/A
	Pressurization of Lift lobby	N/A		
	Communication In lift Car	N/A	N/A N/A	N/A
	Fireman's Grounding Switch			N/A
	Lift Signage	N/A	N/A	N/A
7.	C4an II	N/A	N/A	N/A
/ •	Standby power supply	N/A	N/A	N/A
8.	Refuge Area.			
	Awage Alta.			
	> Total Area	N/A	37/4	
1 7 5	> Location		N/A	N/A
		N/A	N/A	and the second second section in the second section is a second section of the second section in the second section is a second section sectio

T I D com		N/A	N/A
Fire Control Room	N/A	-	N/A
Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	
PA System Panel		N/A	N/A
Dettory backup	N/A	N/A	N/A
Duilding Floor Plans	N/A	N/A	
Special Fire Protection System for Protection	N/A	N/A	N/A
of special Risks, II any.		were tested, ch	

The fire protection systems provided in the building were tested, checked and found

In view of the deemed compliance of the minimum standards of fire prevention and fire functional at the time of inspection. safety measures as required under the rules the Fire Safety Certificate issued vide letter number F.6/DFS/MS/School/2015/SZ/486 dated 06.04.2015 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note: - As per the undertaking given by the Headmaster (placed at C-20) management is using tin shed rooms on third floor for personal use not for school purpose and area of the basement is less than 200 Sq. mtrs.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

593/DOBW 14/06/2018

D.O. (South West)

1531/cto Steps of M. scell 1916.

1531/cto Steps of F.T. Letter is put up for signature phease

226

15007) m. scell 1411