GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI

No. F.6/DFS/MS/School/2018/SZ/1432

Dated: 20 06 2018

FIRE SAFETY CERTIFICATE

Certified that Rajkiya Pratibha Vikas Vidyalaya located at Lajpat Nagar-I (Krishna Market). New Delhi-110024, comprised of Ground + 01 upper floor was issued FSC by this department vide letter No.F.6/MS/DFS/School/2015/SZ/1299 dated 21/07/2015. The premises was re-inspected by officer concerned of this department on 25/05/2018 in the presence of Mr. Bimlesh (Chowkidar) and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. F.16/Estate/CC/Fire/Safety/2011/2398 Dated 01/03/2011 issued by Education Directorate, Govt. of NCT of Delhi and that the premises is fit for occupancy class "Educational Building, Group—B" (School) as above with effect from the date of issue of this certificate for period of three years subject to compliance of conditions mentioned below.

Issued 20 06 2018 at New Delhi by

(Vipin Kental) Chief Fire Officer Tel: 011-23412225

Copy to: -

- 1. Principal, Rajkiya Pratibha Vikas Vidyalaya, Lajpat Nagar-I (Krishna Mkt), New Delhi-24
- 2. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept unlocked and free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire fighting system
- 4. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL- 2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

| | | A CONTRACTOR OF THE PROPERTY O | ON REPORT | Jikas Vidvalava Lair | oat Nagar-I | | |
|-------------|---|--|--|----------------------|-------------|--|--|
| 1 | Nam | e & Address of the Building | Rajkiya Pratibha Vikas Vidyalaya, Lajpat Nagar-I | | | | |
| | | | (Krishna Mkt), New Delhi-110024 (1925334) | | | | |
| 2 | | e of Occupancy | Educational, Group—B (School) | | | | |
| 3 | Build | ding Comprised of | Ground + 01 upper floor. | | | | |
| 4 | Туре | e of Case | Renewal F.6/DFS/MS/School/2015/SZ/1299 Dated 21/07/2015 | | | | |
| 5 | Deta | ils of Previous NOC | F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 | | | | |
| 6 | Fire | Safety Directives Letter No | F.16//Estate/CC/Fire Sarcty/2011/3298 to 3378 dated 67/03/2011 | | | | |
| 7 | Date | e of Inspection | 25-05-2018 Mehmood, ADO (SJ) | | | | |
| 8 | Nam | ne of the Inspecting Officers | MR. Bimlesh (Chowkidar) | | | | |
| 9 | Name & Designation of Officers | | MK. Dilliesii (Cilowkidai) | | | | |
| | fron | n the building side | 2011 | | | | |
| 10 | | r of construction | RPVV/LN/619 dated 09-04-2018 | | | | |
| 11 | App | licant letter No. | Old NOC Provided at Site Remarks | | | | |
| S. No. | | nimum standards on Fire Prevention | 1347.35.45.15.15.15.15.15.1 | Trovided at Site | MR/NMR | | |
| | | Fire Safety U/R 33 | requirements | | | | |
| 1 | Acc | ess to Building. | Required | 6 mtr | MR | | |
| | | Road width | -NA- | 4.5 mtr | -NA- | | |
| | | • Gate width | -NA- | -NA- | -NA- | | |
| 946.500.000 | | Width of internal road | | -1477 | | | |
| 2 | Number, width, type & arrangement of exits. | | | | | | |
| | a) | Number of Staircase | (/2 NI | Provided | MR | | |
| | | > Upper floors. | . 02 Nos | -NA- | -NA- | | |
| | | Basement floor. | -NA- | -NA- | -1471 | | |
| | b) | Width of Staircase | | 1.05 | MR | | |
| | D) | > Upper floors | 1.5m / 0.75m | 1.85m each | | | |
| | | Basement floor | -NA- | -NA- | -NA- | | |
| | | Protection of exits | | | | | |
| | c) | Fire check door | -NA- | -NA- | -NA- | | |
| | | | -NA- | -NA- | -NA- | | |
| | | > Pressurization | | One | MR | | |
| | d) | No. of continuous staircase to terrac | -NA- | 1.50m | MR | | |
| | | Width of corridor | 1 mtr | Provided | MR | | |
| | | Door size | Tille | | | | |
| 3 | Co | mpartmentation. | -NA- | -NA- | -NA- | | |
| | | Fire check door. | -NA- | -NA- | -NA- | | |
| | | Sealing of electrical shafts. | -NA- | -NA- | -NA- | | |
| | | • Fire rating of shaft door. | -NA- | -NA- | -NA- | | |
| | | Water curtain | -NA- | -NA- | -NA- | | |
| | | Fire dampers. | -11/7- | | | | |
| 4. | Sı | moke Management system. | 30 ACPH | -NA- | -NA- | | |
| | | • Basement | | -NA- | -NA- | | |
| | | Upper floors | 12 ACPH | -11/7 | | | |
| 5. | Fire Extinguishers. | | | 12 Noc | MR | | |
| J. | - | Total numbers | Required | 12 Nos | MR | | |
| | | • Types | ABC / CO2 | ABC & CO2 | | | |
| | | | ISI mark | Provided | MR | | |
| | | • ISI Marking | | | | | |
| 6. | F | irst Aid Hose Reels. | -NA- | -NA- | -NA- | | |
| | | Total numbers on each floor. | -NA- | -NA- | -NA- | | |
| | | Length of hose-reel hose. | | -NA- | -NA- | | |
| | | Nozzle Diameter Nozzle Diameter Nozzle Diameter | -NA- | | | | |

Rajkiya Pratibha Vikas Vidyalaya, Lajpat Nagar-I (Krishna Mkt), New Delhi

| 7 A | Automatic fire detection & alarming system. | N. A. | N1 A | X I A |
|-------|--|----------|----------|--------|
| | Type of detectors | -NA- | -NA- | -NA- |
| | Location of Main Panel | -NA- | -NA- | -NA- |
| | Location of Repeater Panel | -NA- | -NA- | -NA- |
| | Alternate source of power | -NA- | -NA- | -NA- |
| | Hooter's location | -NA- | -NA- | -NA- |
| | MOEFA | -NA- | -NA- | -NA- |
| | Public Address System | -NA- | -NA- | -NA- |
| 10. A | Automatic Sprinkler System | | | |
| | Basement | -NA- | -NA- | -NA- |
| | Upper floors | -NA- | -NA- | -NA- |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA- |
| 11. I | nternal Hydrants. | | | |
| | Size of Riser/Down-comer | -NA- | -NA- | -NA- |
| | Number of Hydrant per floor | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 12. Y | ard Hydrants. | • | | |
| | Total number of hydrants. | -NA- | -NA- | -NA- |
| | Hose box. | -NA- | -NA- | -NA- |
| 13. P | umping arrangements. | | | |
| 201 | Ground Level | | | |
| | Discharge of main pump. | -NA- | -NA- | -NA- |
| | Head of main pump. | -NA- | -NA- | -NA- |
| | Number of main pumps. | -NA- | -NA- | -NA- |
| | > Jockey Pump output. | -NA- | -NA- | -NA- |
| | Jockey Pump head. | -NA- | -NA- | -NA- |
| | > Standby Pump output. | -NA- | -NA- | -NA- |
| | Standby Pump head. | -NA- | -NA- | -NA- |
| | > Auto Starting / Manual Stopping. | -NA- | -NA- | -NA- |
| | Pump house access. | -NA- | -NA- | -NA- |
| | Terrace Level | 1111 | | |
| | Discharge of pump. | -NA- | -NA- | -NA- |
| | > Head of pump. | -NA- | -NA- | -NA- |
| | Power supply. | -NA- | -NA- | -NA- |
| | Auto starting of pump. | -NA- | -NA- | -NA- |
| 14 (| Captive water storage for fire fighting. | -1471 | 1171 | 1 177 |
| 14. | Underground tank capacity. | -NA- | -NA- | -NA- |
| | Underground tank capacity. Draw-off connection. | -NA- | -NA- | -NA- |
| | Fire Service Inlet. | -NA- | -NA- | -NA- |
| | Access to tank. | -NA- | -NA- | -NA- |
| | Overhead tank capacity. | -NA- | -NA- | -NA- |
| 15 T | | Required | Provided | MR |
| | Exit Signage. Provision of Lifts. | Required | HOVIGEG | 14117 |
| 16. F | Clic 1 C | -NA- | -NA- | -NA- |
| | | -NA- | -NA- | -NA- |
| | Pressurization of lift lobby. Communication in lift car | -NA- | -NA- | -NA- |
| | Communication in lift ear. Signal a switch | -NA- | -NA- | -NA- |
| | • Fireman's switch. | -NA- | -NA- | -NA- |
| | Lift signage. | | | -NA- |
| | Standby Power Supply | -NA- | -NA- | -1\/\- |
| 18. I | Refuge Area | D.I.A. | NIA | -NA- |
| | • Total area | -NA- | -NA- | |
| | Location | -NA- | -NA- | -NA- |

Rajkiya Pratibha Vikas Vidyalaya, Lajpat Nagar-I (Krishna Mkt), New Delhi

| -NA- |
|--|
| 1 17 1 |
| -NA- |
| -NA- |
| -NA- |
| -NA- |
| nguisher MR ical panel at random and found |
| ectr |

The fire protection system provided in the building /premises were test checked at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular, the FSC issued vide letter No. F.6/DFS/MS/School/2015/SZ/1299 dated 21/07/2015, renewal under rule 37 of the Delhi Fire Service Rules 2010, is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspe

Name: Mehmood Design: ADO (SJ)

Rajkiya Pratibha Vikas Vidyalaya, Lajpat Nagar-I (Krishna Mkt), New Delhi

A. P.T. Letter bon- my for crocs2p miscell lym.