GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

Dated:- 11/06/18

FIRE SAFETY CERTIFICATE

Certified that the Express Building located at 9-10 B.S.Z Marg, New Delhi comprised of Basement + Ground + 04 Upper floors owned/occupied by Express Newspapers Pvt. Ltd. was granted NOC by this department vide letter No. F6/DFS/MS/2003/2917 dated 26/11/2003. The premises was re-inspected by the officer concerned of this department on 18/05/18 in the presence of Sh. Virender Singh and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Business Building, with effect from - Type for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

(Vipin Kental) Chief Fire Officer Delhi Fire Service

Copy to:-

Sh. B.K. Das, Express Building, 9-10 B.S.Z Marg, New Delhi.

Condition for the validity of fire safety certificate

- 1. at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

MICDE	CTION	DEDODT
INSEE	CHUN	REPORT

1. Name & address of the building: Express Building, 9-10 B.S.Z Marg,

New Delhi.

2. Type of occupancy : Business Building B + Gr. 04 Upper floor

3. Type of case:- : Renewal

4. Details of previous NOC :F6/DFS/MS/2003/2917 dated 26/11/2003

5. Fire safety directives No. : N/A6. Date of inspection:- 18/05/18

7. Name of the inspecting officer : Sh. M.K. Sharma ADO/CC

8. Name & designation of officer From the building side

From the building side Sh. Virender Singh (Maintenance Manager

9. Year of construction : 1994

	i cai oi construction	. 1994			
10.	Applicant's letter No	: Nil dated	15/02/2018		
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	09 mtr.	09 Mtr.	MR	
	2) Gate width	06 mtr.	06 mtr.	MR	
	3)Width of internal road	NA	NA	NA	
2.	Number, Width Type & Arran	gement of Exits			
	A. Number of staircases		,		
	1. Upper floors	03 Nos.	03 Nos.	MR	
	2. Basements	02 Nos.	02 Nos.	MR	
	B. Width of staircase				
	1. Upper floors	1.25 mtr.	1.22 ,1.22 & 1.83 mtr.	MR	
	2. Basements	1.25 mtr.	1.22 & 1.83 mtr.	MR	
	C. Protection of exits		5 P	2	
	1. Fire check door	Required	Provided	MR	
	2. Pressurization	NA	NA	NA	
	D. No. of continuous	01 No	01 No	MR	
	staircase to terrace		1		
	E. Width of corridor	NA	NA	NA	
	F. Door size	1 Mtr.	1 Mtr.	MR	
3.	Compartmentation				
	1) Fire check door	Required	Provided	MR	
	2) Sealing of electrical shafts	Required	Provided	MR	
	3) Fire rating of shaft door	NA	NA	NA	
150	4) Water curtain	NA	NA	NA	
	5) Fire Dampers	NA	NA	NA	
4.	Smoke Management System				
	1) Basements	30 ACPH	Provided	MR	
9	2) Upper floors	12 ACPH	Natural	MR	
5.	Fire Extinguishers		9		
	1) Total numbers	50 Nos.	55 Nos.	MR	
	2) Types	ABC & CO2	ABC, CO2 & W.CO2	MR	
	3) ISI marking	Required	Provided	MR	

6.	First-Aid Hose Reel			
	1)Total number of each floor	01 No.	01 No.	MR
	2) Length of hose reel hose	30 m	30 m	MR
	3) Nozzle diameter	6 mm	6 mm	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Required	Provided	MR
	2) Location of main panel	Gr. Floor	Provided	MR
	3) Location of repeater panel	Gr. Floor	Provided	MR
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Required	Provided	
3.	MOEFA	Required	Provided	MR
).	Public Address System	Required	Provided	MR
0.	Automatic Sprinkler System	required	Provided	MR
	1) Basement	Required	Duaridad	1 (1)
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false		Provided	MR
	ceiling	NA	NA	NA
1.	Internal Hydrants			
	1) Size of riser/down-comer	150 MM	150 MM) (D)
	2) Number of hydrants per	01		MR
	floor	01	01	MR
	3) Hose box each floor	01	01	1 (1)
2.	Yard Hydrants	01	01	MR
	1) Total number of hydrants	04	04) (D
	2) Hose box	04	04	MR
3.	Pumping Arrangement	04	04	MR
	1) Ground level			
	a) Discharge of main	2225 LPM	2225 I DV 4	1.00
	pump	2223 LFIVI	2225 LPM	MR
	b) Head of main pump	70 mtr.	70	1.00
	c) Number of main	01	70 mtr.	MR
	pump	01	01	MR
	d) Jockey pump out put	450 LPM	450 LPM) (D)
	e) Jockey pump head	70 mtr.		MR
	f) Stand by pump output	2225 LPM	70 mtr.	MR
	g) Stand by pump head	70 mtr.	2225 LPM	MR
	h) Auto starting/Manual	Required	70 mtr.	MR
	stopping	Required	Provided	MR
	2) Terrace level			
	a) Discharge of pump	NA	NIA	274
	b) Head of pump	NA	NA	NA
	c) Power supply	NA	NA	NA
	d) Auto starting of pump	NA	NA	NA
	Captive Water Storage for Fire	INA Fighting	NA	NA
•			2.00.0001	
	capacity	2,00,000 ltr.	2,00,000 ltr.	MR
		Dogwie 1	D	
	a) Diaw-off confiection	Required	Provided	MR

h

	b) Fire service inlet	Required	Duay: 1-1	
	c) Access to tank	required	Provided	MR
	d) Over head tank capacity	10,000 ltr.	10,000 ltr.	MR
15.	Exit Signage.	Required	D., 1	
16.	Provision of Lifts.	required	Provided	MR
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	NA	NA	NA
	c) Communication in lift car	Required	Provided	MR
	d) Fireman's switch	Required	Provided	MR
17.	e) Lift signage	Required	Provided	MR
18.	Stand by Power Supply	Required	Provided	MR
10.	Refuge Area	N/A	N/A	
, S	Total area location	N/A	N/A	N/A N/A
19.	Fire Control Room			
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
0.	e) Building floor plan	N/A	N/A	N/A
0.	Special Fire Protection System	for Protection of s	special Risk, if any:	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

Shortcomings communicated vide letter No. F6/DFS/MS/2018/998 dated 13/03/2018 have

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F6/DFS/MS/2009/2917 dated 26/11/2003 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name :- M.K. Sharma Designation :- ADO (CC)

CF.O-

M. Scell

FTho.

Me

F.T. letter is put up for biggi pt