GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/NDZ/2018//340

Dated :- 07/06/2018

FIRE SAFETY CERTIFICATE

Certified that the Gold Resto-Bar located at Ground floor, 4350, Main Bazar, Pahar Ganj, New Delhi comprises of Ground + 03 Upper floor, Gold Resto-Bar at Ground floor owned/occupied by Gold Resto-Bar was granted FSC by this department vide letter No.F6/DFS/MS/EH/2015/NDZ/805 dated 20/05/15. The premises was re-inspected by the officer concerned of this department on 01/06/18 in the presence of Mr. Ashok Malhotra (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Assembly Building Group D (Gold Resto-Bar at Ground floor only) with effect from Ground floor only only floor onl

Issued -07/06/2018 -at New Delhi by.

(Vipin Kental) Chief Fire officer Delhi Fire Service

Copy to:-

1. The Medical Officer of Health, Health Department, Palika Kendra, New Delhi.

2. The Manager,

Gold Resto-Bar at Ground floor, 4350, Main Bazar, Pahar Ganj, New Delhi. Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

Artist Control of the Control			The second second	
INSPE	CTI	ON	REP	ORT

1. Name & address of the building Gold Resto-Bar at Ground floor, 4350,

Main Bazar, Pahar Ganj, New Delhi

Assembly Building Group-D 2. Type of occupancy:-

Gr. + 03 upper floors,

Gold Resto-Bar at Ground floor

3. Type of case:-Renewal

F6/DFS/MS/EH/2015/NDZ/805 dated 4. Details of previous FSC:-

20/05/15

5. Fire safety directives No.-N/A

6. Date of inspection:-01/06/18

7. Name of the inspecting officer:-

Sh. Manoj Kumar Sharma (ADO/CC)

8. Name & designation of officer from the building side:-

Mr. Ashok Malhotra (Manager)

Old Heritage Bldg. 9. Year of construction:-

Nil diary dated 15/05/2018 10. Applicant's letter No:-

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR		
1.	Access to Building					
	1) Road width	09 mtr	09 mtr.	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road	N/A	N/A	N/A		
2.	Number, Width Type & Arra	angement of Ex	its			
	A. Number of staircases			**		
	1. Upper floors	N/A	N/A	N/A		
	2. Basements	N/A	N/A	N/A		
	B. Width of staircase					
	1. Upper floors	N/A	N/A	N/A		
	2. Basements	N/A	N/A	N/A		
	C. Protection of exits	N/A	N/A	N/A		
	1. Fire check door	Required	Provided	MR		
	2. Pressurization	N/A	N/A	N/A		
	D. No. of continuous	N/A	N/A	N/A		
	staircase to terrace		· ·			
	E. Width of corridor	N/A	N/A	N/A		
	F. Door size	1.68 & 1.10 mtr.	1.68 & 1.10 mtr.	MR		
3.	Compartmentation					
	1) Fire check door	Required	Provided	MR		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
4.	Smoke Management System					
	1) Basements	30 ACPH	N/A	N/A		
	2) Upper floors	12 ACPH	Exhaust fan	MR		
5.	Fire Extinguishers					
	1) Total numbers	10 Nos.	10 Nos.	MR		
	2) Types	ABC & CO2	ABC & CO2	MR		
	3) ISI marking	Required	Provided	MR		

6.	First-Aid Hose Reel					
	1) Total number of eachfloor	01	01	MR		
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR		
	3) Nozzle diameter	05 mm	05 mm	MR		
7.	Automatic Fire Detection & Alarming System					
	1) Type of detectors	N/A	Provided	N/A		
	2) Location of main panel	N/A	Gr. floor	N/A		
	3) Location of repeater panel	N/A	N/A	N/A		
	4) Alternate source of power	N/A	Provided	N/A		
	5) Hooter's Location	N/A	Ground floor	N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	1) Basement	N/A	N/A	N/A		
	2) Upper floors (Gr.Floor)	Required	Provided	MR		
	3) Sprinkler above false	N/A	N/A	N/A		
	ceiling		and the Specialists			
11.	Internal Hydrants			1		
	1) Size of riser/down-comer	N/A	N/A	N/A		
	2) Number of hydrants per	N/A	N/A	N/A		
	floor			and appropriate to the second		
	3) Hose box	N/A	N/A	N/A		
12.	Yard Hydrants		J ₂			
12.	1) Total number of hydrants	N/A	N/A	N/A		
	2) Hose box	N/A	N/A	N/A		
13.	Pumping Arrangement					
	1) Ground level			:		
	a) Discharge of main	N/A	N/A	N/A		
	pump		.,			
	b) Head of main pump	N/A	N/A	N/A		
	c) Number of main pur	np N/A	N/A	N/A		
	d) Jockey pump out pur		N/A	N/A		
	e) Jockey pump head	N/A	N/A	N/A		
	f) Stand by pump outp		· N/A	N/A		
1	g) Stand by pump head		N/A	N/A		
	h) Auto starting/Manua		N/A	N/A		
	stopping	**				
	2) Terrace level					
	a) Discharge of pump	450 LPM	450&180 LP	M MR		
	b) Head of pump	35 mtr.	35 mtr.	MR		
	c) Power supply	Required	Provided	MR		
	d) Auto starting of pun	1	Provided	MR		
14.	Captive Water Storage for					
- "	1) Under ground tank	N/A	N/A	N/A		
	capacity	1000	53			
	a) Draw-off connection	n N/A	N/A	N/A		
	al Maw-Chi Commercian	- * 11 * *				
		N/A	N/A	N/A		
	b) Fire service inlet	N/A Required	N/A Provided			
		N/A Required 10,000 ltr.	N/A Provided 10,000 ltr.	MR MR		

m

15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		1	
10.	a) Pressurization of lift	N/A	N/A	N/A
	shaft b) Pressurization of lift	N/A	N/A	N/A
	c) Communication in	N/A	N/A	N/A
	lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	Required	Provided	MR
17.	Stand by Power Supply Refuge Area	N/A	N/A	N/A
18.	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
17.	a) Detector system	N/A	N/A	N/A
	panel b) Flow switch panel	N/A	N/A	N/A
		N/A	N/A	N/A
	c) PA system panel d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Syr Risk, if any: ABC & Co2	stem for Prote	ection of special	MR

The fire protection systems provided in the building were randomly tested, checked and

found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/EH/2015/NDZ/805 dated 20/05/15 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation :- ADO (CC)

601/CRO/ND2